

## **SIX-MONTH SURVEILLANCE AHERA REPORT**

**BUESD MAINTENANCE AND TRANSPORTATION YARD  
945 PIEDMONT ROAD  
SAN JOSE, CA 95132**

**PREPARED FOR:  
BERRYESSA UNION ELEMENTARY SCHOOL DISTRICT  
1376 PIEDMONT ROAD  
SAN JOSE, CA 95132**

**INSPECTED ON:  
FEBRUARY 16, 2022**

**HAZMAT DOC PROJECT #22-025**

**PREPARED BY:  
HAZMAT DOC  
3080 OLCOTT STREET • SUITE D135  
SANTA CLARA, CA 95054  
Tel: 408.748.0055**

**BERRYESSA UNION ELEMENTARY SCHOOL DISTRICT  
BUESD MAINTENANCE AND TRANSPORTATION YARD**

**INSPECTED ON:  
FEBRUARY 16, 2022**

**INSPECTED BY:**



---

**Leland Kafeyan  
Cal/OSHA Certified Site Surveillance Technician  
Certification Number 06-4110**

**REPORTED BY:**

*Maheen B. Doctor*

---

**Maheen B. Doctor  
Cal/OSHA Certified Asbestos Consultant  
Certification Number 95-1798**

# **CONTENTS**

## **PART - I**

### **LEGEND AND GLOSSARY OF TERMS**

## **PART - II**

### **AHERA REPORT A - LIST OF BUILDINGS**

## **PART - III**

### **AHERA REPORT B - SURVEY REPORT**

## **PART - IV**

### **HOMOGENEOUS MATERIALS REPORT**

## **PART - V**

### **FRIABLE LOCATIONS REPORT**

## **PART - VI**

### **NON-FRIABLE LOCATIONS REPORT**

## **PART - VII**

### **RECOMMENDATIONS REPORT**

## **PART - VIII**

### **SAMPLES REPORT**

## **PART - IX**

### **DAMAGE REPORT**

## **PART - X**

### **SITE MAPS**

## LEGEND

THE FOLLOWING IS A LIST OF ABBREVIATIONS USED IN THIS REPORT:

### Asbestos Sample Types

AC	=	ACTINOLITE
AM	=	AMOSITE
AN	=	ANTHOPHYLLITE
CH	=	CHRYSOTILE
CR	=	CROCIDOLITE
TR	=	TREMOLITE
ND	=	NONE DETECTED
NS	=	NO SAMPLE

### Measurements

APPROX.	=	APPROXIMATELY
EA	=	EACH
I	=	INCHES
LF	=	LINEAR FEET
N	=	NUMBER
O.D.	=	OUTSIDE DIAMETER
SF	=	SQUARE FEET
TBD	=	TO BE DETERMINED

# LIST OF BUILDINGS AT

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME BUILDING USED AS ( #FLOORS ) CONSTRUCTION	BUILDING AREA (APPROXIMATE)
<b>GROUNDS STORAGE BUILDING</b>	
Storage ( 1 ) Wood, Concrete, Metal	240 SF
<b>MAINTENANCE GARAGE BUILDING</b>	
Garage and Storage ( 1 ) Wood, Metal, Concrete	730 SF
<b>MAINTENANCE SHOPS OFFICE PORTABLE BUILDING</b>	
Offices, Shops, Storage, Plumbing, and Locksmith ( 1 ) Wood and Metal Portable	1,780 SF
<b>MENTOR'S HOUSE</b>	
Daycare ( 1 ) Wood, Metal, Plaster	1,840 SF
<b>METAL STORAGE CONTAINERS (10 EA)</b>	
Storage ( 1 ) Metal	2,560 SF
<b>METAL STORAGE SHED</b>	
Storage ( 1 ) Metal Wall and Ceiling, Wood, and Asphalt	725 SF
<b>PG&amp;E NORTH TOWER BUILDING</b>	
PG&E ( 1 ) Metal and Concrete	154 SF
<b>PG&amp;E SOUTH TOWER ENCLOSURE</b>	
PG&E ( 1 ) Wood Fence, and Concrete Floor	533 SF
<b>PORTABLE</b>	
Storage ( 1 ) Wood, Metal	480 SF
<b>STUDENT NUTRITION SERVICE</b>	
Kitchen ( 1 ) Wood, Metal, Concrete	7,480 SF
<b>TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING</b>	
Office, Lounge, Storage, Restrooms ( 1 ) Portable with Wood Floor and Preformed Walls	3,750 SF
<b>WAREHOUSE BUILDING</b>	
Warehouse, Office, Storage, Lounge, Restrooms ( 1 ) Wood, Metal, Concrete	9,000 SF
<b>WELDING SHOP BUILDING</b>	
Welding Shop ( 1 ) Wood, Metal, Concrete	760 SF

# LIST OF BUILDINGS AT

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

BUILDING NAME	BUILDING AREA (APPROXIMATE)
<b>BUILDING USED AS</b> ( #FLOORS ) CONSTRUCTION	
<hr/>	
<b>WOOD SHEDS (2 EA)</b>	
Storage ( 1 ) Wood	200 SF
<hr/>	
<b>WOOD STORAGE SHED</b>	
Storage ( 1 ) Wood Wall and Ceiling, Concrete Floor	330 SF
<hr/>	
<b>Total Number Of Buildings : <u>15</u></b>	<b>(Approximate) Total Sq Ft. : <u>30,562</u></b>
<hr/>	
End Of Report, Total Of 2 Pages	

---

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME

LOCATION

MATERIAL TYPE

COMMENTS

QTY (APPROXIMATE)

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

### GROUPS STORAGE BUILDING

### GROUPS STORAGE BUILDING

10/13/2008 BUILDING NOTES:

10/13/2008 Metal Ceiling, Wood Wall, Concrete Floor.

12/01/2016 Building name changed from GROUNDS SHED to GROUNDS STORAGE BUILDING.

### GROUPS STORAGE BUILDING

11/08/2021 This Material is unchanged as of this date.

02/16/2022 This Material is unchanged as of this date.

### GROUPS STORAGE BUILDING

EXTERIOR

FIRE DOOR CORE INSULATION

21 SF

09/16/2015 Fire Door Core Insulation (1 EA Doors). This Material is in GOOD condition as of this date.

03/17/2016 This Material is unchanged as of this date.

09/09/2016 This Material is unchanged as of this date.

03/27/2017 This Material is unchanged as of this date.

08/25/2017 This Material is unchanged as of this date.

02/12/2018 This Material is unchanged as of this date.

08/06/2018 This Material is unchanged as of this date.

02/04/2019 This Material is unchanged as of this date.

08/12/2019 This Material is unchanged as of this date.

08/26/2020 This Material is unchanged as of this date.

02/08/2021 This Material is unchanged as of this date.

08/09/2021 This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

02/16/2022 This Material is unchanged as of this date.

15-174AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

### GROUPS STORAGE BUILDING

STORAGE

MISCELLANEOUS

240 SF

- 10/13/2008 Metal Ceiling, Wood Wall and Concrete Floor Shed. This Material is in GOOD condition as of this date.
- 03/03/2014 This Material is unchanged as of this date.
- 08/28/2014 This Material is unchanged as of this date.
- 03/18/2015 This Material is unchanged as of this date.
- 09/16/2015 This Material is unchanged as of this date.
- 03/17/2016 This Material is unchanged as of this date.
- 09/09/2016 This Material is unchanged as of this date.
- 03/27/2017 This Material is unchanged as of this date.
- 08/25/2017 This Material is unchanged as of this date.
- 02/12/2018 This Material is unchanged as of this date.
- 02/12/2018 This Material is unchanged as of this date.
- 08/06/2018 This Material is unchanged as of this date.
- 02/04/2019 This Material is unchanged as of this date.
- 08/12/2019 This Material is unchanged as of this date.
- 08/26/2020 This Material is unchanged as of this date.
- 02/08/2021 This Material is unchanged as of this date.
- 08/09/2021 This Material is unchanged as of this date.
- 02/16/2022 This Material is unchanged as of this date.

08-241AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------



# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**COMMENTS**

**QTY (APPROXIMATE)**

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

### MAINTENANCE GARAGE BUILDING

### MAINTENANCE GARAGE BUILDING

03/05/2007 BUILDING NOTES:

03/05/2007 Building Name changed from BUS GARAGE to BUS GARAGE BUILDING.

12/01/2016 Building Name changed from BUS GARAGE BUILDING to MAINTENANCE GARAGE BUILDING.

### MAINTENANCE GARAGE BUILDING

OFFICE

SINK UNDERCOATING

5 SF

05/11/2009 Black Thermal Undercoating on Sink (1 EA Sink). This Material is in GOOD condition as of this date. (Original Entry updated on 08/30/10.)

08/30/2010 Undercoating is Black. Original entry updated. No other changes as of this date.

03/03/2014 This Material is unchanged as of this date.

08/28/2014 This Material is unchanged as of this date.

03/18/2015 This Material is unchanged as of this date.

09/16/2015 This Material is unchanged as of this date.

03/17/2016 This Material is unchanged as of this date.

09/09/2016 This Material is unchanged as of this date.

03/27/2017 This Material is unchanged as of this date.

08/25/2017 This Material is unchanged as of this date.

02/12/2018 This Material is unchanged as of this date.

08/06/2018 This Material is unchanged as of this date.

02/04/2019 This Material is unchanged as of this date.

08/12/2019 This Material is unchanged as of this date.

08/26/2020 This Material is unchanged as of this date.

02/08/2021 This Material is unchanged as of this date.

SF=Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

08/09/2021 This Material is unchanged as of this date.

02/16/2022 This Material is unchanged as of this date.

09-098AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

### MAINTENANCE GARAGE BUILDING

OFFICE

SUSPENDED CEILING TILE

260 SF

09/06/2005 2'X4' Suspended Ceiling Tile. This Material is in GOOD condition as of this date.

05/11/2009 Damage Observed. <5% Physical Damage in the form of minor cuts and holes. <10% Water Damage due to 3 Tiles with water stains. Material Condition changed from GOOD to FAIR overall as of this date. No other changes as of this date.

03/03/2014 This Material is unchanged as of this date.

08/28/2014 This Material is unchanged as of this date.

03/18/2015 This Material is unchanged as of this date.

09/16/2015 This Material is unchanged as of this date.

03/17/2016 This Material is unchanged as of this date.

09/09/2016 This Material is unchanged as of this date.

03/27/2017 Additional Damage Observed. 11 Tiles have Water Damage. No other changes as of this date.

08/25/2017 This Material is unchanged as of this date.

02/12/2018 This Material is unchanged as of this date.

08/06/2018 This Material is unchanged as of this date.

02/04/2019 This Material is unchanged as of this date.

08/12/2019 This Material is unchanged as of this date.

08/26/2020 This Material is unchanged as of this date.

02/08/2021 This Material is unchanged as of this date.

08/09/2021 This Material is unchanged as of this date.

02/16/2022 This Material is unchanged as of this date.

09-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

SF=Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
05-212AAA	ASSUMED	NO SAMPLE	( NS )

### MAINTENANCE GARAGE BUILDING

OFFICE, RESTROOM, SHOWER ROOM, AND STORAGE ROOM

SMOOTH WALL MISCELLANEOUS 2,650 SF

09/06/2005	Gypsum Wallboard System Walls and Ceilings. This Material is in GOOD condition as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	Damage Observed. <5% Physical Damage in the form of 4 LF of Cracks at South and West Walls of Storage Room. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

### MAINTENANCE GARAGE BUILDING

OFFICE, RESTROOM, SHOWER ROOM, AND STORAGE ROOM

SMOOTH WALL SURFACING

2,650 SF

04/18/2006	Skim Coat for Gypsum Wallboard System Walls and Ceilings. This Material is in GOOD condition as of this date. This Material is in GOOD condition as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	Damage Observed. <5% Physical Damage in the form of 4 LF of Cracks at South and West Walls of Storage Room. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

### MAINTENANCE GARAGE BUILDING

#### REPAIR / SERVICES GARAGE

#### CHALK BOARD

8 SF

05/11/2009	20 SF Green Cementitious Chalkboard, (on Wall next to office). (1 EA). 8 SF Black Cementitious Chalkboard, (located on Door to office). (1 EA). This Material is in GOOD condition as of this date.	
08/30/2010	Material Description clarified. Green Chalkboard is Wood not Cementitious. Material Description changed from '20 SF Green Cementitious Chalkboard, (on Wall next to office).' to '20 SF Green Wood Chalkboard, (on Wall next to office).' Quantity changed from 28 SF to 8 SF. No other changes as of this date.	
11/28/2011	Chalkboard is Black and is located on Door to office. No other changes as of this date.	
03/03/2014	This Material is unchanged as of this date.	
08/28/2014	This Material is unchanged as of this date.	
03/18/2015	This Material is unchanged as of this date.	
09/16/2015	This Material is unchanged as of this date.	
03/17/2016	This Material is unchanged as of this date.	
09/09/2016	This Material is unchanged as of this date.	
03/27/2017	This Material is unchanged as of this date.	
08/25/2017	This Material is unchanged as of this date.	
02/12/2018	This Material is unchanged as of this date.	
08/06/2018	This Material is unchanged as of this date.	
02/04/2019	This Material is unchanged as of this date.	
08/12/2019	This Material is unchanged as of this date.	
08/26/2020	This Material is unchanged as of this date.	
02/08/2021	This Material is unchanged as of this date.	
08/09/2021	This Material is unchanged as of this date.	
02/16/2022	This Material is unchanged as of this date.	

09-098AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>				
<b>LOCATION</b>				
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>				

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

### MAINTENANCE GARAGE BUILDING

#### REPAIR / SERVICES GARAGE

WALL MASTIC

8 SF

05/11/2009	Mastic/Adhesive for 20 SF Green Cementitious Chalkboard, (on Wall next to office). (1 EA). 8 SF Black Cementitious Chalkboard, (located on Door to office). (1 EA). This Material is in GOOD condition as of this date.
08/30/2010	Material Re-Assessed. Material Description changed from '20 SF Green Cementitious Chalkboard, (on Wall next to office).' to '20 SF Green Wood Chalkboard, (on Wall next to office) .8 SF Black Cementitious Chalkboard, (located on Door to office)' Quantity changed from 28 SF to 8 SF. No other changes as of this date.
11/28/2011	Chalkboard is Black and is located on Door to office. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

09-098AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>				
<b>LOCATION</b>				
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>				

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

### MAINTENANCE GARAGE BUILDING

RESTROOMS (2), AND SHOWER ROOM

HEAT SHIELD 7.5 SF

03/05/2007	Heat Shields (3 EA Round Light Fixtures). This Material is in GOOD condition as of this date.
04/13/2012	Quantity Re-Assessed and changed from 7.5 SF to 3.5 SF. No other changes as of this date.
10/08/2012	Material Re-Assessed and Quantity is 7.5 SF. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>				
<b>LOCATION</b>				
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>				

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

**MAINTENANCE SHOPS OFFICE PORTABLE BUILDING**

**MAINTENANCE SHOPS OFFICE PORTABLE BUILDING**

- 03/05/2007 BUILDING NOTES:
  
- 03/05/2007 Building Name changed from OFFICE PORTABLE to OFFICE PORTABLE BUILDING.
  
- 12/01/2016 Building Name changed from OFFICE PORTABLE BUILDING to MAINTENANCE SHOPS OFFICE PORTABLE BUILDING.

**MAINTENANCE SHOPS OFFICE PORTABLE BUILDING**

DOORS - EXTERIOR

FIRE DOOR CORE INSULATION 42 SF

- 10/08/2012 Fire Door Core Insulation (2 EA Doors). This Material is in GOOD condition as of this date.
  
- 03/03/2014 This Material is unchanged as of this date.
  
- 08/28/2014 This Material is unchanged as of this date.
  
- 03/18/2015 This Material is unchanged as of this date.
  
- 09/16/2015 This Material is unchanged as of this date.
  
- 03/17/2016 This Material is unchanged as of this date.
  
- 09/09/2016 This Material is unchanged as of this date.
  
- 03/27/2017 This Material is unchanged as of this date.
  
- 08/25/2017 This Material is unchanged as of this date.
  
- 02/12/2018 This Material is unchanged as of this date.
  
- 08/06/2018 This Material is unchanged as of this date.
  
- 02/04/2019 This Material is unchanged as of this date.
  
- 08/12/2019 This Material is unchanged as of this date.
  
- 08/26/2020 This Material is unchanged as of this date.
  
- 02/08/2021 This Material is unchanged as of this date.
  
- 08/09/2021 This Material is unchanged as of this date.



# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

02/16/2022 This Material is unchanged as of this date.

12-185AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

### MAINTENANCE SHOPS OFFICE PORTABLE BUILDING

DOORS - INTERIOR

FIRE DOOR CORE INSULATION

168 SF

05/11/2009	Fire Door Core Insulation (6 EA Doors). All Wood Interior Doors to Offices, Storage Rooms, and Utility Closet. This Material is in GOOD condition as of this date.
10/08/2012	Material Description changed from ' Fire Door Core Insulation. (6 EA Doors). ' to ' Fire Door Core Insulation. (8 EA Doors).'. Quantity changed from 144 SF to 168 SF. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	Location Description changed from OFFICE PORTABLE to DOORS-INTERIOR. No other changes as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

09-095AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>					<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

### MAINTENANCE SHOPS OFFICE PORTABLE BUILDING

#### EXTERIOR WALLS

WEATHER PROOFING (OUTSIDE) 2,800 SF

04/18/2006	Weather Proofing Wall Panels. This Material is in GOOD condition as of this date.
09/23/2013	Friability changed from Moderate to Non. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date
08/28/2014	This Material is unchanged as of this date..
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

### MAINTENANCE SHOPS OFFICE PORTABLE BUILDING

#### HVAC OFFICE AND HALLWAY

BASEBOARD MASTIC 20 LF

04/18/2006	Mastic/Adhesive for 4" Blue Baseboard. This Material is in GOOD condition as of this date.
------------	--

SF= Sq. Ft, l=Inches, LF=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**COMMENTS**

**QTY (APPROXIMATE)**

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

**MAINTENANCE SHOPS OFFICE PORTABLE BUILDING**

HVAC OFFICE AND HALLWAY

SMOOTH WALL MISCELLANEOUS

1,000 SF

09/06/2005	Gypsum Wallboard System, Walls. This Material is in GOOD condition as of this date.
04/18/2006	Location changed from CENTRAL SHOP AREA to HVAC OFFICE AND HALLWAY. Quantity changed from 900 SF to 1,000 SF. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**COMMENTS**

**QTY (APPROXIMATE)**

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
09/16/2015			
This Material is unchanged as of this date.			
03/17/2016			
This Material is unchanged as of this date.			
09/09/2016			
This Material is unchanged as of this date.			
03/27/2017			
This Material is unchanged as of this date.			
08/25/2017			
This Material is unchanged as of this date.			
02/12/2018			
This Material is unchanged as of this date.			
08/06/2018			
This Material is unchanged as of this date.			
02/04/2019			
This Material is unchanged as of this date.			
08/12/2019			
This Material is unchanged as of this date.			
08/26/2020			
This Material is unchanged as of this date.			
02/08/2021			
This Material is unchanged as of this date.			
08/09/2021			
This Material is unchanged as of this date.			
02/16/2022			
This Material is unchanged as of this date.			

<b>05-212AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>
------------------	----------------	------------------	---------------

**MAINTENANCE SHOPS OFFICE PORTABLE BUILDING**

HVAC OFFICE AND HALLWAY

SMOOTH WALL SURFACING

1,000 SF

09/06/2005	Skim Coat for Gypsum Wallboard System, Walls. This Material is in GOOD condition as of this date.
04/18/2006	Location changed from CENTRAL SHOP AREA to HVAC OFFICE AND HALLWAY. Quantity changed from 900 SF to 1,000 SF. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date..
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.

SF=Sq. Ft, l=Inches, LF=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
03/27/2017	This Material is unchanged as of this date.		
08/25/2017	This Material is unchanged as of this date.		
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>05-212AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

### MAINTENANCE SHOPS OFFICE PORTABLE BUILDING

OFFICE PORTABLE

BASEBOARD MASTIC

265 LF

09/06/2005	Mastic/Adhesive for 3" Cream Baseboard. This Material is in GOOD condition as of this date.
11/05/2007	Material Re-Assessed. Damage Observed <5% Physical Damage - due to 5 LF loose in Front Office. Material condition changed from GOOD to FAIR overall. No other changes as of this date.
11/28/2011	Additional Damage observed - in the form of approximately 20 LF is loose in 1 Office. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	Material Re-Assessed. Additional 40 LF of Damage found. Baseboard is missing and Mastic/Adhesive is exposed. No other changes as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>					<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
03/27/2017	Additional Damage Observed. 8 LF Loose Mastic Exposed in Office 1. 8 LF Loose and 4 LF Missing in Office 2. No other changes as of this date.		
08/25/2017	Additional Damage Observed. Front Office now has 25 LF of Baseboard Missing. Mastic/Adhesive is Exposed. No other changes as of this date.		
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>05-212AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

### MAINTENANCE SHOPS OFFICE PORTABLE BUILDING

OFFICE PORTABLE

PRESSED WOOD WALL PANEL

2,660 SF

10/13/2008	4'x10' Pressed Wood Wall Panel with Vinyl Wall Cover. This Material is in GOOD condition as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	Damage Observed. <10% Water Damage - in the form of 16 SF of Loose and Peeling Vinyl. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.
08/25/2017	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**COMMENTS**

**QTY (APPROXIMATE)**

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>08-241AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

**MAINTENANCE SHOPS OFFICE PORTABLE BUILDING**

OFFICE PORTABLE

PRESSED WOOD WALL PANEL MASTIC

2,660 SF

10/13/2008	Mastic/Adhesive for 4'x10' Pressed Wood Wall Panel with Vinyl Wall Cover. This Material is in GOOD condition as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	Damage Observed. <10% Water Damage - in the form of 16 SF of Loose and Peeling Vinyl. Material condition changed from GOOD to FAIR overall. Friability changed from Non to Low. No other changes as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME

LOCATION

MATERIAL TYPE

COMMENTS

QTY (APPROXIMATE)

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

08/12/2019 This Material is unchanged as of this date.

08/26/2020 This Material is unchanged as of this date.

02/08/2021 This Material is unchanged as of this date.

02/16/2022 This Material is unchanged as of this date.

### MAINTENANCE SHOPS OFFICE PORTABLE BUILDING

OFFICE PORTABLE

SUSPENDED CEILING TILE

1,600 SF

09/06/2005 2'X4' Suspended Ceiling Tile. This Material is in GOOD condition as of this date.

11/28/2011 Damage Observed. <10% Water Damage - in the form of 2 Tiles are Water Damaged in Office; <5% Physical Damage - in the form of 1 Tile is broken. Material condition changed from GOOD to FAIR overall. No other changes as of this date.

03/03/2014 This Material is unchanged as of this date.

08/28/2014 This Material is unchanged as of this date.

03/18/2015 This Material is unchanged as of this date.

09/16/2015 This Material is unchanged as of this date.

03/17/2016 This Material is unchanged as of this date.

09/09/2016 Additional Damage observed. 1 Tile is missing in Office. No other changes as of this date.

03/27/2017 This Material is unchanged as of this date.

08/25/2017 This Material is unchanged as of this date.

02/12/2018 This Material is unchanged as of this date.

08/06/2018 This Material is unchanged as of this date.

02/04/2019 This Material is unchanged as of this date.

08/12/2019 This Material is unchanged as of this date.

08/26/2020 This Material is unchanged as of this date.

02/08/2021 This Material is unchanged as of this date.

08/09/2021 This Material is unchanged as of this date.

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

HazMat Doc. All Rights Reserved.



# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

08/09/2021 This Material is unchanged as of this date.

02/16/2022 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

### MAINTENANCE SHOPS OFFICE PORTABLE BUILDING

OFFICE PORTABLE

VINYL WALL COVER

2,660 SF

09/06/2005 4'X10' Vinyl Cover on Pressed Wood Wall Panels. This Material is in GOOD condition as of this date.

11/28/2011 Damage Observed. <5% Physical Damage - in the form of approximately 1 SF is Damaged. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.

03/03/2014 This Material is unchanged as of this date.

08/28/2014 This Material is unchanged as of this date.

03/18/2015 This Material is unchanged as of this date.

09/16/2015 This Material is unchanged as of this date.

03/17/2016 This Material is unchanged as of this date.

09/09/2016 This Material is unchanged as of this date.

03/27/2017 Damage Observed. <10% Water Damage - in the form of 16 SF of Loose and Peeling Vinyl. Material condition changed from GOOD to FAIR overall. Friability changed from Non to Low. No other changes as of this date.

08/25/2017 This Material is unchanged as of this date.

02/12/2018 This Material is unchanged as of this date.

08/06/2018 This Material is unchanged as of this date.

02/04/2019 This Material is unchanged as of this date.

08/12/2019 This Material is unchanged as of this date.

08/26/2020 This Material is unchanged as of this date.

02/08/2021 This Material is unchanged as of this date.

08/09/2021 This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>			
<b>LOCATION</b>			
<b>MATERIAL TYPE</b>	<b>QTY (APPROXIMATE)</b>		
<b>COMMENTS</b>			

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

02/16/2022 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

### MAINTENANCE SHOPS OFFICE PORTABLE BUILDING

OFFICE PORTABLE

VINYL WALL COVER MASTIC

2,660 SF

10/13/2008	Mastic/Adhesive for Vinyl Wall Cover, (on 4'x10' Pressed Wood Wall Panel). This Material is in GOOD condition as of this date.
11/28/2011	Damage Observed. <5% Physical Damage - in the form of approximately 1 SF is Damaged. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

08-241AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>				
<b>LOCATION</b>				
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>				

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

### MAINTENANCE SHOPS OFFICE PORTABLE BUILDING

OFFICES, LOUNGE ROOM AND LOCKSMITH OFFICE

CARPET MASTIC 1,600 SF

04/18/2006	Mastic/Adhesive for Green Carpet. This Material is in GOOD condition as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	Damage Observed. Offices have Approximately 1 SF of Carpet Damaged exposing Mastic/Adhesive. Material Condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	Additional Damage Observed. Water Damages and Stains found in all of the Rooms. No other changes as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>					<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

**MENTOR'S HOUSE**

**MENTOR'S HOUSE**

- 09/09/2016 BUILDING NOTES:
- 09/09/2016 Building name changed from DAYCARE BUILDING to MENTOR'S HOUSE.
- 08/06/2018 Rooms are currently underconstruction. DAYCARE is no longer in this building.

**MENTOR'S HOUSE**

ATTIC

LOOSE FILL INSULATION 800 SF

- 09/06/2005 Blown-In Insulation. This Material is in GOOD condition as of this date.
- 03/03/2014 This Material is unchanged as of this date.
- 08/28/2014 This Material is unchanged as of this date.
- 03/18/2015 This Material is unchanged as of this date.
- 09/16/2015 This Material is unchanged as of this date.
- 03/17/2016 This Material is unchanged as of this date.
- 09/09/2016 This Material is unchanged as of this date.
- 03/27/2017 This Material is unchanged as of this date.
- 08/25/2017 This Material is unchanged as of this date.
- 02/12/2018 This Material is unchanged as of this date.
- 08/06/2018 This Material is unchanged as of this date.
- 02/04/2019 This Material is unchanged as of this date.
- 08/12/2019 This Material is unchanged as of this date.
- 08/26/2020 This Material is unchanged as of this date.
- 02/08/2021 This Material is unchanged as of this date.
- 08/09/2021 This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>			
<b>LOCATION</b>			
<b>MATERIAL TYPE</b>			<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>			

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

02/16/2022 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

### MENTOR'S HOUSE

CHILDREN'S RESTROOM

VINYL FLOOR TILE

70 SF

08/06/2018 12"x12" Gray Pattern Vinyl Floor Tile. 1Tile is Loose. This Material is in FAIR condition as of this date.

02/04/2019 This Material is unchanged as of this date.

08/12/2019 This Material is unchanged as of this date.

08/26/2020 This Material is unchanged as of this date.

02/08/2021 This Material is unchanged as of this date.

08/09/2021 This Material is unchanged as of this date.

02/16/2022 This Material is unchanged as of this date.

18-127AAA	NEW	NONE DETECTED	( ND )
-----------	-----	---------------	--------

### MENTOR'S HOUSE

CHILDREN'S RESTROOM

VINYL FLOOR TILE MASTIC

70 SF

08/06/2018 Mastic/Adhesive for 2"x12" Gray Pattern Vinyl Floor Tile. 1 Tile is Loose. This Material is in FAIR condition as of this date.

02/04/2019 This Material is unchanged as of this date.

08/12/2019 This Material is unchanged as of this date.

08/26/2020 This Material is unchanged as of this date.

02/08/2021 This Material is unchanged as of this date.

08/09/2021 This Material is unchanged as of this date.

02/16/2022 This Material is unchanged as of this date.

18-127AAA	NEW	NONE DETECTED	( ND )
-----------	-----	---------------	--------

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>				
<b>LOCATION</b>				
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>				

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

### MENTOR'S HOUSE

DAYCARE KITCHEN

VINYL SHEETING

250 SF

09/06/2005	Green Vinyl Sheeting. This Material is in GOOD condition as of this date.
04/18/2006	Vinyl Sheeting has Square Patterns. No other changes as of this date.
04/14/2008	1 SF is cut and missing in the center of the Kitchen and this Material is in FAIR condition as of this date.
10/13/2008	Damages Re-Assessed. Material has been Repaired. This Material changed from FAIR to GOOD condition as of this date.
09/23/2013	Friability changed from Low to Non. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	New Gray Speckled Vinyl Floor Sheeting installed. Old Material may remain under New Material. No other changes as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

05-212AAA

ASSUMED

NO SAMPLE

( NS )

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>					<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

### MENTOR'S HOUSE

DAYCARE KITCHEN

VINYL SHEETING

250 SF

- 03/17/2016 Gray Speckle Vinyl Floor Sheeting. This Material is in GOOD condition as of this date.
- 09/09/2016 This Material is unchanged as of this date.
- 03/27/2017 This Material is unchanged as of this date.
- 08/25/2017 This Material is unchanged as of this date.
- 02/12/2018 This Material is unchanged as of this date.
- 08/06/2018 This Material is unchanged as of this date.
- 02/04/2019 This Material is unchanged as of this date.
- 08/12/2019 This Material is unchanged as of this date.
- 08/26/2020 This Material is unchanged as of this date.
- 02/08/2021 This Material is unchanged as of this date.
- 08/09/2021 This Material is unchanged as of this date.
- 02/16/2022 This Material is unchanged as of this date.

16-074AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

### MENTOR'S HOUSE

DAYCARE KITCHEN

VINYL SHEETING BACKING PAPER/MASTIC

250 SF

- 09/06/2005 Backing Paper for Green Vinyl Sheeting. This Material is in GOOD condition as of this date.
- 04/14/2008 1 SF is cut and missing in the center of the Kitchen and this Material is in FAIR condition as of this date.
- 10/13/2008 Damages reassessed. Material has been replaced. This Material has changed from FAIR to GOOD condition as of this date.
- 09/23/2013 Friability changed from High to Low. No other changes as of this date.
- 03/03/2014 Friability changed from Low to Moderate. No other changes as of this date.
- 08/28/2014 This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
03/18/2015	This Material is unchanged as of this date.		
09/16/2015	This Material is unchanged as of this date.		
03/17/2016	New Gray Speckled Vinyl Floor Sheeting installed. Old Material may remain under New Material. No other changes as of this date.		
09/09/2016	This Material is unchanged as of this date.		
03/27/2017	This Material is unchanged as of this date.		
08/25/2017	This Material is unchanged as of this date.		
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>05-212AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

### MENTOR'S HOUSE

DAYCARE KITCHEN

VINYL SHEETING BACKING PAPER/MASTIC

250 SF

03/17/2016	Backing Paper for Gray Speckle Vinyl Floor Sheeting. This Material is in GOOD condition as of this date.		
09/09/2016	This Material is unchanged as of this date.		
03/27/2017	This Material is unchanged as of this date.		
08/25/2017	This Material is unchanged as of this date.		
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		



# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>16-074AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

### MENTOR'S HOUSE

DAYCARE ROOM AND ENTRY TO KITCHEN

CEILING MASTIC

500 SF

09/06/2005	Mastic/Adhesive for 1'X1' Ceiling Tile. This Material is in GOOD condition as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	Damage Observed. <5% Physically Damage - in the form of 4 Tiles have small Cracks and Chips in them. Material condition changed from GOOD to FAIR overall. Friability changed from Non to Low. No other changes as of this date.
08/06/2018	Material Re-assessed. Partial Repairs made some Tiles have been Patched with Mud. Remains in FAIR condition as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>			
<b>LOCATION</b>			
<b>MATERIAL TYPE</b>	<b>QTY (APPROXIMATE)</b>		
<b>COMMENTS</b>			

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

08/09/2021 This Material is unchanged as of this date.

02/16/2022 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

### MENTOR'S HOUSE

DAYCARE ROOM AND ENTRY TO KITCHEN

CEILING TILE

500 SF

09/06/2005 1'X1' Ceiling Tile. This Material is in GOOD condition as of this date.

03/03/2014 This Material is unchanged as of this date.

08/28/2014 This Material is unchanged as of this date.

03/18/2015 This Material is unchanged as of this date.

09/16/2015 This Material is unchanged as of this date.

03/17/2016 This Material is unchanged as of this date.

09/09/2016 This Material is unchanged as of this date.

03/27/2017 This Material is unchanged as of this date.

08/25/2017 This Material is unchanged as of this date.

02/12/2018 Damage Observed. <5% Physically Damage - in the form of 4 Tiles have small Cracks and Chips in them. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.

08/06/2018 Material Re-assessed. Partial Repairs made some Tiles have been Patched with Mud. Remains in FAIR condition as of this date.

02/04/2019 This Material is unchanged as of this date.

08/12/2019 This Material is unchanged as of this date.

08/26/2020 Additional Damage Observed. <5% Physical Damage in the form of 3 Loose Tiles at Enry into Kitchen. Material remains in FAIR condition overall. No other changes as of this date.

02/08/2021 This Material is unchanged as of this date.

08/09/2021 This Material is unchanged as of this date.

02/16/2022 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

SF= Sq. Ft, l=Inches, LF=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**QTY (APPROXIMATE)**

**COMMENTS**

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

**MENTOR'S HOUSE**

DAYCARE ROOM (IN SE CORNER OF BUILDING)

CARPET MASTIC

240 SF

- 04/14/2008 Mastic/Adhesive for Brown/Grey Carpet. This Material is in GOOD condition as of this date.
- 03/03/2014 This Material is unchanged as of this date.
- 08/28/2014 This Material is unchanged as of this date.
- 03/18/2015 This Material is unchanged as of this date.
- 09/16/2015 This Material is unchanged as of this date.
- 03/17/2016 This Material is unchanged as of this date.
- 09/09/2016 This Material is unchanged as of this date.
- 03/27/2017 This Material is unchanged as of this date.
- 08/25/2017 This Material is unchanged as of this date.
- 02/12/2018 Damage Observed. <10% Water Damage - in the form of a 12 SF Water Stain by the Desk. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.
- 08/06/2018 This Material is unchanged as of this date.
- 02/04/2019 This Material is unchanged as of this date.
- 08/12/2019 This Material is unchanged as of this date.
- 08/26/2020 Additional Damage Observed. <5% Physical Damage in the form of 3 Loose Tiles at Enry into Kitchen. Material remains in FAIR condition overall. No other changes as of this date.
- 02/08/2021 This Material is unchanged as of this date.
- 08/09/2021 This Material is unchanged as of this date.
- 02/16/2022 This Material is unchanged as of this date.

08-075AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

### MENTOR'S HOUSE

ENTIRE BUILDING

SMOOTH WALL MISCELLANEOUS

6,400 SF

09/06/2005	Gypsum Wallboard System Walls, (with Vinyl Wall Cover in some areas). This Material is in GOOD condition as of this date.
04/18/2006	This Material is also on ceilings. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	Damage observed. Physical Damage <5% in the of form of a crack in the Hallway. Material condition changed from GOOD to FAIR overall. No other changes as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	Additional Damage observed. 6 LF is cracked in Kitchen. No other changes as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	Additional Damage Observed. 12 LF is Cracked in Kitchen. No other changes as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	Additional Damage Observed. 12 LF Crack in Kithchen is no 1/4" Split to it. No other changes as of this date.
08/06/2018	Material Re-assessed. 12 LF Crack in Kithchen has been Patched with Mud. 6 LF Crack now in the same spot. No other changes as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

### MENTOR'S HOUSE

ENTIRE BUILDING

SMOOTH WALL SURFACING

6,400 SF

04/18/2006	Skim Coat for Gypsum Wallboard System Walls, (with Vinyl Wall Cover in some areas). This Material is in GOOD condition as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	Damage observed. Physical Damage <5% in the of form of a crack in the Hallway. Material condition changed from GOOD to FAIR overall. No other changes as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	Additional Damage observed. 6 LF is cracked in Kitchen. No other changes as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	Additional Damage Observed. 12 LF is Cracked in Kitchen. 2 Small Holes in Large Room with Wood Ceilings. No other changes as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	Additional Damage Observed. 12 LF Crack in Kithchen is no 1/4" Split to it. No other changes as of this date.
08/06/2018	Material Re-assessed. 12 LF Crack in Kithchen has been Patched with Mud. 6 LF Crack now in the same spot. No other changes as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>				
<b>LOCATION</b>				
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>				

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

### MENTOR'S HOUSE

#### EXTERIOR WALLS

##### ROUGH WALL

1,400 SF

09/06/2005	Stucco Walls. This Material is in GOOD condition as of this date.
03/05/2007	Material changed from 'Stucco Walls.' to 'Exterior Stucco Walls.' No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

### MENTOR'S HOUSE

#### EXTERIOR WALLS

##### ROUGH WALL SURFACING

1,400 SF

09/06/2005	Skim Coat for Stucco Walls. This Material is in GOOD condition as of this date.
------------	---

SF= Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>					<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
03/05/2007	Material changed from 'Skim Coat for Stucco Walls.' to 'Skim Coat for Exterior Stucco Walls.' No other changes as of this date.		
03/03/2014	This Material is unchanged as of this date.		
08/28/2014	This Material is unchanged as of this date.		
03/18/2015	This Material is unchanged as of this date.		
09/16/2015	This Material is unchanged as of this date.		
03/17/2016	This Material is unchanged as of this date.		
09/09/2016	This Material is unchanged as of this date.		
03/27/2017	This Material is unchanged as of this date.		
08/25/2017	This Material is unchanged as of this date.		
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>05-212AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

### MENTOR'S HOUSE

#### EXTERIOR WINDOWS

##### CAULKING

400 LF

09/06/2005	Window Caulking. Damaged in various areas. This Material is in FAIR condition as of this date.
05/11/2009	Damage Observed. <10% Water Damage due to moisture and heat degradation on various surfaces. Material remains in FAIR condition overall as of this date.
03/03/2014	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
08/28/2014	This Material is unchanged as of this date.		
03/18/2015	This Material is unchanged as of this date.		
09/16/2015	This Material is unchanged as of this date.		
03/17/2016	This Material is unchanged as of this date.		
09/09/2016	This Material is unchanged as of this date.		
03/27/2017	This Material is unchanged as of this date.		
08/25/2017	This Material is unchanged as of this date.		
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>05-212AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

### MENTOR'S HOUSE

KITCHEN (COUNTER TOP) AND RESTROOM

MORTAR MISCELLANEOUS

750 SF

04/18/2006	Grout/Mortar for 4"x4" Tan/Light Brown Ceramic Tile. This Material is in GOOD condition as of this date. (Original Entry updated on 04/14/08.)
04/14/2008	4"x4" Ceramic Tile are Tan/Light Brown. Original entry updated. No other changes as of this date.
05/11/2009	Material Re-Assessed. Approximately 70 SF is covering the floor, and approx. 50 SF is under the rubber floor mat. Quantity changed from 750 SF to 820 SF. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.



# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**COMMENTS**

**QTY (APPROXIMATE)**

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

03/18/2015	This Material is unchanged as of this date.		
09/16/2015	This Material is unchanged as of this date.		
03/17/2016	This Material is unchanged as of this date.		
09/09/2016	This Material is unchanged as of this date.		
03/27/2017	This Material is unchanged as of this date.		
08/25/2017	This Material is unchanged as of this date.		
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	Material Re-assessed. 70 SF has been Removed from Floor. Quantity changed from 820 SF to 750 SF		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		

05-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

**MENTOR'S HOUSE**

OFFICE AND DAYCARE ROOMS

CARPET MASTIC

1,300 SF

09/06/2005	Mastic/Adhesive for Blue Carpet. This Material is in GOOD condition as of this date. (Original Entry updated on 04/14/08.)		
04/14/2008	Carpet is Blue. Original entry updated. No other changes as of this date.		
03/03/2014	This Material is unchanged as of this date.		
08/28/2014	This Material is unchanged as of this date.		
03/18/2015	This Material is unchanged as of this date.		
09/16/2015	This Material is unchanged as of this date.		
03/17/2016	This Material is unchanged as of this date.		

SF= Sq. Ft, l=Inches, LF=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>					<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
09/09/2016	This Material is unchanged as of this date.		
03/27/2017	This Material is unchanged as of this date.		
08/25/2017	This Material is unchanged as of this date.		
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>05-212AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

### MENTOR'S HOUSE

#### RESTROOM

#### BASEBOARD MASTIC

20 LF

10/13/2008	Mastic/Adhesive for 4" Blue Baseboard. This Material is in GOOD condition as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>					<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>08-241AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

### MENTOR'S HOUSE

#### RESTROOM

#### VINYL FLOOR TILE

32 SF

10/13/2008	12"x12" Off-White Vinyl Floor Tile. This Material is in GOOD condition as of this date.
09/23/2013	Friability changed from Low to Non. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**QTY (APPROXIMATE)**

**COMMENTS**

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

08/26/2020 This Material is unchanged as of this date.

02/08/2021 This Material is unchanged as of this date.

08/09/2021 This Material is unchanged as of this date.

02/16/2022 This Material is unchanged as of this date.

08-241AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

**MENTOR'S HOUSE**

RESTROOM

VINYL FLOOR TILE MASTIC

32 SF

10/13/2008 Mastic/Adhesive for 12"x12" off White Vinyl Floor Tile. This Material is in GOOD condition as of this date.

03/03/2014 This Material is unchanged as of this date.

08/28/2014 This Material is unchanged as of this date.

03/18/2015 This Material is unchanged as of this date.

09/16/2015 This Material is unchanged as of this date.

03/17/2016 This Material is unchanged as of this date.

09/09/2016 This Material is unchanged as of this date.

03/27/2017 This Material is unchanged as of this date.

08/25/2017 This Material is unchanged as of this date.

02/12/2018 This Material is unchanged as of this date.

08/06/2018 This Material is unchanged as of this date.

02/04/2019 This Material is unchanged as of this date.

08/12/2019 This Material is unchanged as of this date.

08/26/2020 This Material is unchanged as of this date.

02/08/2021 This Material is unchanged as of this date.

08/09/2021 This Material is unchanged as of this date.

02/16/2022 This Material is unchanged as of this date.

08-241AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

SF=Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
08-241AAA	ASSUMED	NO SAMPLE	( NS )

**MENTOR'S HOUSE**

SOUTHEAST ROOM

LAMINATE FLOORING

421 SF

- 08/06/2018 Pergo Laminate Flooring. This Material is in GOOD condition as of this date.
- 02/04/2019 This Material is unchanged as of this date.
- 08/12/2019 This Material is unchanged as of this date.
- 08/26/2020 This Material is unchanged as of this date.
- 02/08/2021 This Material is unchanged as of this date.
- 08/09/2021 This Material is unchanged as of this date.
- 02/16/2022 This Material is unchanged as of this date.

18-127AAA	NEW	NONE DETECTED	( ND )
-----------	-----	---------------	--------

**MENTOR'S HOUSE**

SOUTHEAST ROOM

LAMINATE FLOORING MASTIC

421 SF

- 08/06/2018 Mastic/Adhesive for Pergo Laminate Flooring. This Material is in GOOD condition as of this date.
- 02/04/2019 This Material is unchanged as of this date.
- 08/12/2019 This Material is unchanged as of this date.
- 08/26/2020 This Material is unchanged as of this date.
- 02/08/2021 This Material is unchanged as of this date.
- 08/09/2021 This Material is unchanged as of this date.
- 02/16/2022 This Material is unchanged as of this date.

18-127AAA	NEW	NONE DETECTED	( ND )
-----------	-----	---------------	--------

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

**METAL STORAGE CONTAINERS (10 EA)**

**METAL STORAGE CONTAINERS (10 EA)**

- 09/06/2005 BUILDING NOTES:
  
- 09/06/2005 Assumed Non-ACM. All Metal Construction.
  
- 11/28/2011 Building Name changed from METAL STORAGE SHEDS to METAL STORAGE CONTAINERS (8 EA). Area changed from 3,180 SF to 2,560 SF.
  
- 08/09/2021 Quantity Re-Assessed from METAL STORAGE CONTAINER (8 EA) to METAL STORAGE CONTAINER (10 EA). Material Quantity changed from 2,560 SF to 2,750 SF. No other changes as of this date.

**METAL STORAGE CONTAINERS (10 EA)**

METAL STORAGE CONTAINERS (8 EA)

STORAGE CONTAINER

2,750 SF

- 09/06/2005 Metal Storage Containers 6 EA, approximately 426 SF EA.
  
- 04/18/2006 Material redefined as (3) Metal Storage Units. Quantity changed from 530 SF to 1,590 SF. No other changes as of this date.
  
- 03/05/2007 Location Name changed from METAL STORAGE SHEDS to METAL STORAGE SHEDS (3). No other changes as of this date.
  
- 08/30/2010 Location Description changed from METAL STORAGE SHEDS (3) to METAL STORAGE SHEDS (6). Quantity changed from 1,590 SF to 3,180 SF. No other changes as of this date.
  
- 11/28/2011 Location Description changed from METAL STORAGE SHEDS (6) to METAL STORAGE CONTAINERS (8). Quantity changed from 3,180 SF to to 2,560 SF. No other changes as of this date.
  
- 11/28/2011 This Material is unchanged as of this date.
  
- 03/03/2014 This Material is unchanged as of this date.
  
- 08/28/2014 This Material is unchanged as of this date.
  
- 03/18/2015 This Material is unchanged as of this date.
  
- 09/16/2015 This Material is unchanged as of this date.
  
- 03/17/2016 This Material is unchanged as of this date.
  
- 09/09/2016 This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
08/25/2017	This Material is unchanged as of this date.		
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	Quantity Re-Assessed from METAL STORAGE CONTAINER (8 EA) to METAL STORAGE CONTAINER (10 EA). Material Quantity changed from 2,560 SF to 2,750 SF. No other changes as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>05-212.NS</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

**METAL STORAGE SHED**

**METAL STORAGE SHED**

11/28/2011 BUILDING NOTES:

11/28/2011 Metal Storage Shed.

**METAL STORAGE SHED**

METAL STORAGE SHED

STORAGE BUILDING

725 SF

- 11/28/2011 Metal Storage Shed 1 EA.
- 03/03/2014 This Material is unchanged as of this date.
- 08/28/2014 This Material is unchanged as of this date.
- 03/18/2015 This Material is unchanged as of this date.
- 09/16/2015 This Material is unchanged as of this date.
- 03/17/2016 This Material is unchanged as of this date.
- 09/09/2016 This Material is unchanged as of this date.
- 03/27/2017 This Material is unchanged as of this date.
- 08/25/2017 This Material is unchanged as of this date.
- 02/12/2018 This Material is unchanged as of this date.
- 08/06/2018 This Material is unchanged as of this date.
- 02/04/2019 This Material is unchanged as of this date.
- 08/12/2019 This Material is unchanged as of this date.
- 08/26/2020 This Material is unchanged as of this date.
- 02/08/2021 This Material is unchanged as of this date.
- 08/09/2021 This Material is unchanged as of this date.
- 02/16/2022 This Material is unchanged as of this date.

11-202.NS ASSUMED NO SAMPLE ( NS )

SF=Sq. Ft, I=Inches, LF=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*



# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME			
LOCATION			
MATERIAL TYPE			QTY (APPROXIMATE)
COMMENTS			

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
11-200-10	ASSUMED	NO SAMPLE	11-200-10

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>				
<b>LOCATION</b>				
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>				

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

**PG&E NORTH TOWER BUILDING**

**PG&E NORTH TOWER BUILDING**

- 11/28/2011 BUILDING NOTES:
- 11/28/2011 Metal and Concrete Building.
- 12/01/2016 Building name changed from PG&E to PG&E NORTH TOWER BUILDING.

**PG&E NORTH TOWER BUILDING**

PG&E

MISCELLANEOUS

154 SF

- 03/17/2016 Metal and Concrete Building. This Material is in GOOD condition as of this date.
- 09/09/2016 This Material is unchanged as of this date.
- 03/27/2017 This Material is unchanged as of this date.
- 08/25/2017 This Material is unchanged as of this date.
- 02/12/2018 This Material is unchanged as of this date.
- 08/06/2018 This Material is unchanged as of this date.
- 02/04/2019 This Material is unchanged as of this date.
- 08/12/2019 This Material is unchanged as of this date.
- 08/26/2020 This Material is unchanged as of this date.
- 02/08/2021 This Material is unchanged as of this date.
- 08/09/2021 This Material is unchanged as of this date.
- 02/16/2022 This Material is unchanged as of this date.

16-074.NS	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

**PG&E SOUTH TOWER ENCLOSURE**

**PG&E SOUTH TOWER ENCLOSURE**

12/01/2016 BUILDING NOTES:

12/01/2016 Building name changed from TOWER to PG&E SOUTH TOWER ENCLOSURE.

**PG&E SOUTH TOWER ENCLOSURE**

TOWER

WOOD WALL

533 SF

11/28/2011 Wood Wall. Non-ACM Material identified by the AHERA Accredited inspector. This Material is in GOOD condition as of this date.

03/03/2014 This Material is unchanged as of this date.

08/28/2014 This Material is unchanged as of this date.

03/18/2015 This Material is unchanged as of this date.

09/16/2015 This Material is unchanged as of this date.

03/17/2016 This Material is unchanged as of this date.

09/09/2016 This Material is unchanged as of this date.

03/27/2017 This Material is unchanged as of this date.

08/25/2017 This Material is unchanged as of this date.

02/12/2018 This Material is unchanged as of this date.

08/06/2018 This Material is unchanged as of this date.

02/04/2019 This Material is unchanged as of this date.

08/12/2019 This Material is unchanged as of this date.

08/26/2020 This Material is unchanged as of this date.

02/08/2021 This Material is unchanged as of this date.

08/09/2021 This Material is unchanged as of this date.

02/16/2022 This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME

LOCATION

MATERIAL TYPE

COMMENTS

QTY (APPROXIMATE)

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
11-202.NS	NON-ACM	NO SAMPLE	( NS )

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

**PORTABLE**

**PORTABLE**

EXTERIOR DOOR

FIRE DOOR CORE INSULATION

42 SF

07/30/2010 Fire Door Core Insulation (2 EA Double-Doors). This Material is in GOOD condition as of this date.

11/28/2011 Material Description reassessed and changed from 'Fire Door Core Insulation. (2 EA Double-Doors).' to 'Fire Door Core Insulation. (2 EA Single-Doors).' No other changes as of this date.

03/03/2014 This Material is unchanged as of this date.

08/28/2014 This Material is unchanged as of this date.

03/18/2015 This Material is unchanged as of this date.

09/16/2015 This Material is unchanged as of this date.

03/17/2016 This Material is unchanged as of this date.

09/09/2016 This Material is unchanged as of this date.

03/27/2017 This Material is unchanged as of this date.

08/25/2017 This Material is unchanged as of this date.

02/12/2018 This Material is unchanged as of this date.

08/06/2018 This Material is unchanged as of this date.

02/04/2019 This Material is unchanged as of this date.

08/12/2019 This Material is unchanged as of this date.

08/26/2020 This Material is unchanged as of this date.

02/08/2021 This Material is unchanged as of this date.

08/09/2021 This Material is unchanged as of this date.

02/16/2022 This Material is unchanged as of this date.

10-174AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

**PORTABLE**

INTERIOR DOOR

FIRE DOOR CORE INSULATION

21 SF

07/30/2010	Fire Door Core Insulation. (1 EA Double-Doors). This Material is in GOOD condition as of this date.
11/28/2011	Material Description reassessed and changed from ' Fire Door Core Insulation. (1 EA Double-Doors). ' to ' Fire Door Core Insulation. (1 EA Single-Doors). ' No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

10-174AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>					<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

**PORTABLE**

PORTABLES

BASEBOARD MASTIC

130 LF

07/30/2010	Mastic/Adhesive for 4" Brown Baseboard. This Material is in GOOD condition as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

10-174AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

**PORTABLE**

PORTABLES

SUSPENDED CEILING TILE

450 SF

07/30/2010	2'x4' Vinyl Covered Fiberglass Suspended Ceiling Tile. This Material is in GOOD condition as of this date.
09/23/2013	This Material is unchanged as of this date.

SF= Sq. Ft, l=Inches, LF=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**COMMENTS**

**QTY (APPROXIMATE)**

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

03/03/2014	This Material is unchanged as of this date.		
08/28/2014	Damage observed. <5% Physical Damage - 1 Tile is Damaged. Friability changed from Non-Friable to Friable. No other changes as of this date.		
03/18/2015	This Material is unchanged as of this date.		
09/16/2015	This Material is unchanged as of this date.		
03/17/2016	This Material is unchanged as of this date.		
09/09/2016	This Material is unchanged as of this date.		
03/27/2017	This Material is unchanged as of this date.		
08/25/2017	Additional Damage Observed. 4 Tiles now have Physical Damage. No other changes as of this date.		
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		

10-174AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

**PORTABLE**

PORTABLES

VINYL FLOOR TILE

480 SF

07/30/2010	12"x12" Beige and Cream Vinyl Floor Tile. This Material is in GOOD condition as of this date.		
11/28/2011	Damage Observed. <5% Physical Damage - in the form of a hairline crack observed on Tile. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.		
03/03/2014	This Material is unchanged as of this date.		



# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**COMMENTS**

**QTY (APPROXIMATE)**

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
08/28/2014	This Material is unchanged as of this date.		
03/18/2015	This Material is unchanged as of this date.		
09/16/2015	This Material is unchanged as of this date.		
03/17/2016	This Material is unchanged as of this date.		
09/09/2016	This Material is unchanged as of this date.		
03/27/2017	Additional Damage Observed. Several Tiles appear to have Cracks on them. No other changes as of this date.		
08/25/2017	This Material is unchanged as of this date.		
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>10-174AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

**PORTABLE**

PORTABLES

VINYL FLOOR TILE MASTIC

480 SF

07/30/2010	Mastic/Adhesive for 12"x12" Beige and Cream Vinyl Floor Tile. This Material is in GOOD condition as of this date.
11/28/2011	Damage Observed. <5% Physical Damage - in the form of a hairline crack observed on Tile. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>					<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
03/18/2015	This Material is unchanged as of this date.		
09/16/2015	This Material is unchanged as of this date.		
03/17/2016	This Material is unchanged as of this date.		
09/09/2016	This Material is unchanged as of this date.		
03/27/2017	Additional Damage Observed. Several Tiles appear to have Cracks on them. No other changes as of this date.		
08/25/2017	This Material is unchanged as of this date.		
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>10-174AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	QTY (APPROXIMATE)	COMMENTS
---------------	----------	---------------	-------------------	----------

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

### STUDENT NUTRITION SERVICE

### STUDENT NUTRITION SERVICE

02/16/2022 BUILDING NOTES:

02/16/2022 Student Nutricion Services, constrctued about 3 years ago.

### STUDENT NUTRITION SERVICE

STUDENT NUTRITION SERVICES - KITCHEN

PERMANENT BUILDING

7,480 SF

02/16/2022 New Permant Building. Material in GOOD condtion as of this date.

22-025.NS	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>				
<b>LOCATION</b>				
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>				

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

03/05/2007	BUILDING NOTES:
03/05/2007	Building Name changed from MAIN OFFICE to MAIN OFFICE BUILDING.
12/01/2016	Building Name changed from MAIN OFFICE BUILDING to TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING.

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

ASSISTANT DIRECTOR

VINYL FLOOR TILE

38 SF

11/28/2011	12"x12" Grey Vinyl Floor Tile. This Material is in GOOD condition as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	Damage Observed. <5% Physical Damage - in the form of 2 Tiles are Sliding and Exposing Mastic. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.
08/25/2017	Additional Damage Observed. 3 Tiles are now Cracked. No other changes as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

08/09/2021 This Material is unchanged as of this date.

02/16/2022 This Material is unchanged as of this date.

11-202AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

ASSISTANT DIRECTOR

VINYL FLOOR TILE MASTIC

38 SF

11/28/2011 Mastic/Adhesive for 12"x12" Grey Vinyl Floor Tile. This Material is in GOOD condition as of this date

03/03/2014 This Material is unchanged as of this date.

08/28/2014 This Material is unchanged as of this date.

03/18/2015 This Material is unchanged as of this date.

09/16/2015 This Material is unchanged as of this date.

03/17/2016 This Material is unchanged as of this date.

09/09/2016 This Material is unchanged as of this date.

03/27/2017 Damage Observed. <5% Physical Damage - in the form of 2 Tiles are Sliding and Exposing Mastic. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.

08/25/2017 Additional Damage Observed. 3 Tiles are now Cracked. No other changes as of this date.

02/12/2018 This Material is unchanged as of this date.

08/06/2018 This Material is unchanged as of this date.

02/04/2019 This Material is unchanged as of this date.

08/12/2019 This Material is unchanged as of this date.

08/26/2020 This Material is unchanged as of this date.

02/08/2021 This Material is unchanged as of this date.

08/09/2021 This Material is unchanged as of this date.

02/16/2022 This Material is unchanged as of this date.

11-202AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

CONFERENCE ROOM, STAFF'S LOUNGE ROOM, AND 2 STORAGE ROOM

SUSPENDED CEILING TILE 1,500 SF

05/12/2009	2'x4' Suspended Ceiling Tile, (with small uneven cuts and holes pattern). Damage Observed. <5% Physical Damage due to 3 missing Tiles. This Material is in FAIR condition as of this date.
03/08/2010	Location Description changed from STAFF'S LOUNGE ROOM to CONFERENCE ROOM AND STAFF'S LOUNGE ROOM. Quantity changed from 500 SF to 1,500 SF. Additional Damage: <10% Water Damage in the form of 2 Tiles are Water Damaged. No other changes as of this date.
08/30/2010	Location Description changed from CONFERENCE ROOM AND STAFF'S LOUNGE ROOM to CONFERENCE ROOM, STAFF'S LOUNGE ROOM, AND STORAGE ROOM. Additional Damage observed in Conference Room in the form of 3 Tiles are Water Damaged and 1 has a hole. No other changes as of this date.
11/28/2011	Additional Damage observed - in the form of 3 more Tiles are Water Damaged, and 1 Tile is missing in Storage Room. No other changes as of this date.
10/08/2012	Damage Re-Assessed and Conference Room now has a total of 4 Water Damaged Tiles. No other changes as of this date.
09/23/2013	Material Re-Assessed. Conference Room now has Debris on Floor due to Water leaks from the Roof. No other changes as of this date.
03/03/2014	Debris has been cleaned up. No other changes as of this date.
08/28/2014	Material Re-Assessed. 2 Suspended Ceiling Tiles have Water Damage in the Office.
03/18/2015	Additional Damage Observed. 3 Suspended Ceiling Tiles Water Damaged. No other change as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	Additional Damage observed. 1 Tile is missing in Director's Office. No other changes as of this date.
09/09/2016	Partial Repairs observed. Current Damage: 2 Tiles with Water Damage in the Storage Room, and 1 Tile with Water Damage in the Conference Room. No other changes as of this date.
03/27/2017	Additional Damage Observed. 2 Tiles with Water Stains and Several Tiels Have been repainted in Staff Room. However 11 Tiles have Cracks and Cuts with Broken Edges in Staff Room. 5 Tiles have Water Damage while other have been Painted Over. Several Tiles have Cracks and Borken Edges in the Conferecnce Room. 2 Tiles have have Water Damage in the Storage by Front of the Building. 2 Tiles have Water Damage and 1 Tile Missing in the Storage by Rear of the Building. No other changes as of this date.
08/25/2017	Additional Damage Observed. Conference Room now has 3 Tiles with Water Damage. No other changes as of this date.
02/12/2018	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

09-098AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

ENTIRE BUILDING

FIRE DOOR CORE INSULATION 252 SF

09/06/2005	Fire Door Core Insulation (12 EA DOORS). This Material is in GOOD condition as of this date.
03/05/2007	This Material is unchanged as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

EXTERIOR BUILDING

WEATHER PROOFING (OUTSIDE)	1,100 SF
----------------------------	----------

03/05/2007	Weather Proofing Material. This Material is in GOOD condition as of this date.
11/28/2011	Damage Observed. <5% Physical Damage - in the form of approximately 2 SF of Wall is peeling. Material condition changed from GOOD to FAIR overall. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	Repairs observed. Damage has been Repaired. Material condition changed from FAIR to GOOD. Friability changed from Low to Non. No other changes as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	Damage Observed. <5% Physical Damage - in the form of 1 SF to 1 Panel is Broken on North Wall. Material condition changed from GOOD to FAIR overall. No other changes as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.



# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

08/09/2021 This Material is unchanged as of this date.

02/16/2022 This Material is unchanged as of this date.

<b>07-041AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>
------------------	----------------	------------------	---------------

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

LOUNGE ROOM

SINK UNDERCOATING

4 SF

04/14/2008 Black Thermal Undercoating on Sink (1 EA Sink). This Material is in GOOD condition as of this date. (Original Entry updated on 03/17/16.)

08/30/2010 Undercoating is Black. Original entry updated. No other changes as of this date.

03/03/2014 This Material is unchanged as of this date.

08/28/2014 This Material is unchanged as of this date.

03/18/2015 This Material is unchanged as of this date.

09/16/2015 This Material is unchanged as of this date.

03/17/2016 This Material is unchanged as of this date.

09/09/2016 This Material is unchanged as of this date.

03/27/2017 This Material is unchanged as of this date.

08/25/2017 This Material is unchanged as of this date.

02/12/2018 This Material is unchanged as of this date.

08/06/2018 This Material is unchanged as of this date.

02/04/2019 This Material is unchanged as of this date.

08/12/2019 This Material is unchanged as of this date.

08/26/2020 This Material is unchanged as of this date.

02/08/2021 This Material is unchanged as of this date.

08/09/2021 This Material is unchanged as of this date.

02/16/2022 This Material is unchanged as of this date.

<b>08-075AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>
------------------	----------------	------------------	---------------

SF= Sq. Ft, l=Inches, LF=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

MAIN OFFICE

BASEBOARD MASTIC

1,400 LF

09/06/2005	Mastic/Adhesive for Baseboard. Approximately 15 LF exposed in Womens Restroom. This Material is in FAIR condition as of this date.
04/18/2006	Material redefined as 4" Black Baseboard (in Offices and Hallways) and 4" Blue Baseboard (in Conference Room). All Damages have been repaired. Friability changed from Non-Friable to Friable. No other changes as of this date.
03/08/2010	Material Re-Assessed. 4" Brown Baseboard was also observed in several Offices and Main Entry Office. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	New Material Installed. Men's and Women's Restrooms Floor and Baseboard now Covered with Vinyl Sheeting. Old Material is Possibly Behind. No other changes as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	Damage Observed. <5% Physical Damage - in the form of 4" of Baseboard is missing in Main Office. Material condition changed from GOOD to FAIR overall. Friability changed from Non to Low. No other changes as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
05-212AAA	ASSUMED	NO SAMPLE	( NS )

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

MAIN OFFICE

SMOOTH WALL MISCELLANEOUS

5,100 SF

09/06/2005	Gypsum Wallboard System, Walls. Damages noticed. This Material is in FAIR condition as of this date.
05/11/2009	Additional Damages Observed. <5% Physical Damage in the form of small holes, gauging, and scratches on various surfaces. Material remains in FAIR condition overall as of this date.
11/28/2011	Additional Damage observed - in the form of Kitchen Ceiling has a crack, and approximately 1 SF of Material is peeling. Material condition changed from GOOD to FAIR. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	Additional Damage Observed. <10% Water Damage in the form of 1 SF of Water Damage on Wall under Urinal in Mens Restroom in Drivers Lounge. Material remains in FAIR condition overall. No other changes as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
05-212AAA	ASSUMED	NO SAMPLE	( NS )

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

MAIN OFFICE

SMOOTH WALL SURFACING

5,100 SF

04/18/2006	Skim Coat for Gypsum Wallboard System, Walls. Various Damages noticed. This Material is in FAIR condition as of this date.
05/11/2009	Additional Damages observed. <5% Physical Damage in the form of small holes, gauging, and scratches on various surfaces. Material remains in FAIR condition overall as of this date.
11/28/2011	Additional Damage observed - in the form of Kitchen Ceiling has a crack, and approximately 1 SF of Material is peeling. Material condition changed from GOOD to FAIR. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	Additional Damage Observed. <10% Water Damage in the form of 1 SF of Water Damage on Wall under Urinal in Mens Restroom in Drivers Lounge. Material remains in FAIR condition overall. No other changes as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
05-212AAA	ASSUMED	NO SAMPLE	( NS )

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

#### MAIN OFFICE

SUSPENDED CEILING TILE 2,150 SF

09/06/2005	2'X4' Suspended Ceiling Tile. Several Tiles Damaged and Water stained. This Material is in FAIR condition as of this date.
11/05/2007	Material Re-Assessed. Damage: <5% Physical Damage - 1 Tile in Telephone Panel Closet and 1 Tile in Mens Restroom; <10% Water Damage - 2 Tiles in Blueprint Office and 4 Tiles in Trainer Office. This Material is in FAIR condition overall as of this date.
04/14/2008	Additional Damage noted: 1/2 Tile is missing in the Supply Storage Room as of this date.
10/13/2008	Additional 3 Tiles missing at Lounge area. Also several Tiles Damaged at Hallway. No other changes as of this date.
05/11/2009	Damages Re-Assessed. 1 Tile is missing above the Main Entry Door, (next to Receptionist Office). Physical damage is in various locations. Tiles damaged in Telephone Panel Closet has increased to 3 Tiles. Quantity changed from 2,650 SF to 3,150 SF. No change to damage in Hallway. Friability changed from Moderate to High to reflect these changes.
09/03/2009	Repairs have been made in Main Lobby. Missing Tile has been replaced. Also, 3 Tiles Damaged at Hallway have been repaired. Telephone Panel Closet and Storage Closet are Water Damaged. No other changes as of this date.
03/08/2010	Material Re-Assessed. Approx. 1,000 SF of 2'x4' Suspended Ceiling Tile is the same as Staff's Lounge. Quantity changed from 3,150 SF to 2,150 SF. Additional Damage in the form of 6 Tiles are cracked in Hallway and Main Office. Also, 2 Tiles are Water Damaged in Office, adjacent to Lounge Room. Material remains in FAIR condition. No other changes as of this date.
11/28/2011	Additional Damage observed - in the form of Hallway has some Tiles broken. No other changes as of this date.
10/08/2012	Additional Damage - in the form of 1 hole observed on Hallway Ceiling. Also, 2 additional Water Damaged Tiles observed in Telephone Panel Closet. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	Material Re-Assessed. Additional Water Damage Observed. No other changes as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	Additional Damage observed and Partial Repairs made. Director's Office has 1 Tile with Water Damage. Missing Tile above Main Entry Door has been Replaced. No other changes as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
09/09/2016	Additional Damage observed. 2 Tiles with Water Damage in Trainer's Office. No other changes as of this date.		
03/27/2017	Additional Damage Observed. 4 Tiles with Water Damage and Several other have broken edges and are Cracked in the Director's Office. 4 Water Damage Tiles, 7 other Tiles have Cracks, in the Project Manager's Office. 4 Tiles with Cracked and Chipped Tiles in the Executive Assistant Office. No other changes as of this date.		
08/25/2017	Additional Damage Observed. Trainer's Office now has 3 Tiles. No other changes as of this date.		
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>05-212AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

MAIN OFFICES, HALLWAY, CONFERENCE ROOM, STORAGE ROOM AND LOUNGE ROOM

CARPET MASTIC 3,300 SF

04/18/2006	Mastic/Adhesive for Carpets (Approximately 80% Blue and 20% Mix of Red, Brown and Grey Colors). This Material is in FAIR condition as of this date.
05/11/2009	Damage Observed. <5% Physical Damage in the form of the Carpet has been Damaged due to several separations observed in locations of seams. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
09/09/2016	This Material is unchanged as of this date.		
03/27/2017	Additional Damage Observed. Storage Room by Rear of Building there is Water Damage in the form of Stains and Mold, still damp. 20 LF of Blue Carpet in the Staff Lounge is loose. No other changes as of this date.		
08/25/2017	This Material is unchanged as of this date.		
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>05-212AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

MAIN OFFICES, RESTROOM, HALLWAY, CONFERENCE ROOM

VINYL WALL COVER

7,800 SF

10/13/2008	Vinyl Wall Cover, (on Pressed Wood Wall Panel). Damage in the form of cuts and holes. This Material is in FAIR condition as of this date.		
09/03/2009	This Material is unchanged as of this date.		
03/03/2014	This Material is unchanged as of this date.		
08/28/2014	This Material is unchanged as of this date.		
03/18/2015	This Material is unchanged as of this date.		
09/16/2015	This Material is unchanged as of this date.		
03/17/2016	This Material is unchanged as of this date.		
09/09/2016	This Material is unchanged as of this date.		

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
03/27/2017	Additional Damage Observed. 20 SF of Loose Vinyl and Wall Boards in the Conference Room. No other changes as of this date.		
08/25/2017	This Material is unchanged as of this date.		
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	Additional Damage Observed. 1 Panel with Holes in it and 1 Panle has Scrapes and Cuts in Project Manager's Office. No other changes as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>08-214AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

**TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING**

MAIN OFFICES, RESTROOM, HALLWAY, CONFERENCE ROOM

VINYL WALL COVER MASTIC 7,800 SF

10/13/2008	Mastic/Adhesive for Vinyl Wall Cover, (on Pressed Wood Wall Panel). Damage in the form of cuts and holes. This Material is in FAIR condition as of this date.
09/03/2009	Material remains in <5% Physical Damage. This Material is unchanged as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	Additional Damage Observed. 20 SF of Loose Vinyl and Wall Boards in the Conference Room. No other changes as of this date.



# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>					<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
08/25/2017		This Material is unchanged as of this date.	
02/12/2018		This Material is unchanged as of this date.	
08/06/2018		This Material is unchanged as of this date.	
02/04/2019		This Material is unchanged as of this date.	
08/12/2019		This Material is unchanged as of this date.	
08/26/2020		This Material is unchanged as of this date.	
02/08/2021		Additional Damage Observed. 1 Panel with Holes in it and 1 Panle has Scrapes and Cuts in Project Manager's Office. No other changes as of this date.	
08/09/2021		This Material is unchanged as of this date.	
02/16/2022		This Material is unchanged as of this date.	
<b>08-241AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

MAIN OFFICES, RESTROOMS, HALLWAY CONFERENCE ROOM

PRESSED WOOD WALL PANEL

7,800 SF

09/06/2005	Pressed wood wall panels. Damaged in forms of cuts and holes in Receptionist Area. This Material is in FAIR condition as of this date.
10/13/2008	Material Location changed from MAIN OFFICE to MAIN OFFICES, RESTROOMS, HALLWAY CONFERENCE ROOM. No other changes as of this date.
09/03/2009	Material remains in <5% Physical Damage. No changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	Additional Damage Observed. 20 SF of Loose Vinyl and Wall Boards in the Conference Room. No other changes as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
08/25/2017	This Material is unchanged as of this date.		
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>05-212AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

**TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING**

MAIN OFFICES, RESTROOMS, HALLWAY CONFERENCE ROOM

PRESSED WOOD WALL PANEL MASTIC 7,800 SF

09/06/2005	Mastic/Adhesive for Pressed Wood Wall Panels. Damaged in forms of cuts and holes in Receptionist Area. This Material is in FAIR condition as of this date.
10/13/2008	Material Location changed from MAIN OFFICE to MAIN OFFICES, RESTROOMS, HALLWAY CONFERENCE ROOM. No other changes as of this date.
09/03/2009	Material remains in <5% Physical Damage. No changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	Additional Damage Observed. 20 SF of Loose Vinyl and Wall Boards in the Conference Room. No other changes as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**COMMENTS**

**QTY (APPROXIMATE)**

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

08/25/2017	This Material is unchanged as of this date.		
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

PLENUM

WALL INSULATION

2,500 SF

09/06/2005	Spray-On Foam Insulation. Material is loose and Water Damaged in several locations. This Material is in FAIR condition as of this date.		
09/03/2009	Material remains in <5% Physical Damage and <10% Water Damage. This Material is unchanged as of this date.		
03/03/2014	This Material is unchanged as of this date.		
08/28/2014	This Material is unchanged as of this date.		
03/18/2015	This Material is unchanged as of this date.		
09/16/2015	This Material is unchanged as of this date.		
03/17/2016	This Material is unchanged as of this date.		
09/09/2016	This Material is unchanged as of this date.		
03/27/2017	This Material is unchanged as of this date.		
08/25/2017	This Material is unchanged as of this date.		
02/12/2018	This Material is unchanged as of this date.		

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>05-212AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

**TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING**

STAFF RESTROOMS (2)

VINYL SHEETING

400 SF

04/18/2006	Grey Vinyl Sheeting. (Apparent New Material identified by the AHERA Accredited Inspector). This material is in GOOD condition as of this date.
03/05/2007	Location Name changed from TWO STAFF RESTROOMS to STAFF RESTROOMS (2). No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

STAFF RESTROOMS (2)

VINYL SHEETING BACKING PAPER/MASTIC

400 SF

04/18/2006	Backing Paper for Grey Vinyl Sheeting. (Apparent New Material identified by the AHERA Accredited Inspector). This material is in GOOD condition as of this date.
03/05/2007	Location Name changed from TWO STAFF RESTROOMS to STAFF RESTROOMS (2). No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

SUPPLY ROOM, DISPATCH, DRIVER TRAINING OFFICE, DRIVERS LOUNGE, KITCHEN, AND PROGRAMMING ROOM

VINYL FLOOR TILE 700 SF

09/06/2005	9"X9" Vinyl Floor Tile, under carpeting in programming room. Approximatly 10 SF missing in Womens Restroom, also Damaged in 2 Restrooms. This Material is in FAIR condition as of this date.
04/18/2006	Approximately 400 SF of Material Removed in two Restrooms. Quantity changed from 1,100 SF to 700 SF. Material replaced with New Grey Vinyl Sheeting. No other changes as of this date.
05/11/2009	Material Re-Assessed. Material is not visible in remaining locations due to being covered with existing Carpet. New Grey Vinyl Sheeting is in Restrooms. Material condition is TBD.
09/23/2013	Material Re-Assessed. This Material changed from FAIR to GOOD condition. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>05-212AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

**TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING**

SUPPLY ROOM, DISPATCH, DRIVER TRAINING OFFICE, DRIVERS LOUNGE, KITCHEN, AND PROGRAMMING ROOM

VINYL FLOOR TILE MASTIC 700 SF

09/06/2005	Mastic/Adhesive for 9"X9" Vinyl Floor Tile, under carpeting in programming room. Approximately 10 SF missing in Womens Restroom, also Damaged in 2 Restrooms. This Material is in FAIR condition as of this date.
04/18/2006	Approximately 400 SF of Material removed in 2 Restrooms. Quantity changed from 1,100 SF to 700 SF. Material replaced with New Backing Paper for Grey Vinyl Sheeting. No other changes as of this date.
05/11/2009	Material Re-Assessed. Material is not visible in remaining locations due to being covered with existing Carpet. New Grey Vinyl Sheeting is in Restrooms. Material condition is TBD.
09/23/2013	Material Re-Assessed. This Material changed from FAIR to GOOD condition. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
05-212AAA	ASSUMED	NO SAMPLE	( NS )



# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>			
<b>LOCATION</b>			
<b>MATERIAL TYPE</b>			<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>			

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

**WAREHOUSE BUILDING**

**WAREHOUSE BUILDING**

ALL OFFICES, RESTROOMS, CARPENTERS SHOP, AND LOUNGE ROOM

BASEBOARD MASTIC

470 LF

09/06/2005	Mastic/Adhesive for 4" Black and brown Baseboards. Material is exposed in Carpenters Shop and Restroom. This Material is in FAIR condition as of this date.
04/18/2006	Approximately 120 LF is exposed in Shop and Main Office. Condition changed from FAIR to POOR. Recommendation changed to reflect this fact. No other changes as of this date.
05/11/2009	Damages Re-Assessed. Physical Damages remains at <50%. This Material is unchanged as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	Additional Damage Observed. <5% Physical Damage in the form of 2 LF of Missing Baseboard with Brown Mastic exposed in Restroom. Material remains in FAIR condition overall. No other changes as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

### WAREHOUSE BUILDING

ALL OFFICES, RESTROOMS, SHOPS, LOUNGE ROOM, AND WAREHOUSE STORAGE ROOM

VINYL FLOOR TILE

2,310 SF

09/06/2005	12"X12" Multi-Color Vinyl Floor Tile. Broken and missing in various locations. This Material is in FAIR condition as of this date.
04/14/2008	50 SF Removed in the Restroom. Quantity changed from 2,360 SF to 2,310 SF. This Material condition is unchanged as of this date.
05/11/2009	Damages Re-Assessed. Physical Damage has increased to <50% and approx. 100 SF is damaged due to oil spills and degradation in Wood Shop (Warehouse Storage Room) by the South Wall. Material condition changed from FAIR to POOR. Recommendation changed to reflect this change.
04/13/2012	Location Description changed from ALL OFFICES, RESTROOMS, SHOPS, AND LOUNGE ROOM to ALL OFFICES, RESTROOMS, SHOPS, LOUNGE ROOM, AND WAREHOUSE STORAGE ROOM. No other changes as of this date.
10/08/2012	Additional Damage - in the form of 4 Tiles are becoming loose in Wood Shop. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	Material Re-Assessed. Warehouse Storage Room has Several Tiles Broken and Missing. Friability changed from Moderate to Low. No other changes as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>05-212AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

### WAREHOUSE BUILDING

ALL OFFICES, RESTROOMS, SHOPS, LOUNGE ROOM, AND WAREHOUSE STORAGE ROOM

VINYL FLOOR TILE MASTIC

2,360 SF

09/06/2005	Mastic/Adhesive for 12"X12" Multi-Color Vinyl Floor Tile. Material is exposed in broken and missing Tile locations. This Material is in FAIR condition as of this date.
04/14/2008	50 SF is exposed in the Restroom. This Material condition is unchanged as of this date.
05/11/2009	Damages Re-Assessed. Physical Damage has increased to <50% and approx. 100 SF is Damaged due to oil spills and degradation in Wood Shop (Warehouse Storage Room) by the South Wall. Material condition changed from FAIR to POOR. Friability changed from Low to Moderate. Recommendation changed to reflect this change. 50 SF that was exposed in Restroom has been repaired. Material has been replaced with Off-White 12"x12".
04/13/2012	Location Description changed from ALL OFFICES, RESTROOMS, SHOPS, AND LOUNGE ROOM to ALL OFFICES, RESTROOMS, SHOPS, LOUNGE ROOM, AND WAREHOUSE STORAGE ROOM. No other changes as of this date.
10/08/2012	Additional Damage - in the form of 4 Tiles are becoming loose in Wood Shop. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	Material Re-Assessed. Warehouse Storage Room has Several Tiles Broken and Missing. Friability changed from Moderate to Low. No other changes as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>05-212AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

**WAREHOUSE BUILDING**

**CARPENTERS SHOP, AND RESTROOM**

**CEILING MASTIC** 1,000 SF

03/05/2007	Mastic/Adhesive for 1'x1' Ceiling Tile. Damage: <5% Physical Damage - in the form of approximately 10 SF missing in Entry Area; <10% Water Damage - in the form of loose and falling Ceiling Tiles. No other changes as of this date.
05/11/2009	Material condition is FAIR overall. This Material is unchanged as of this date.
09/03/2009	Material Re-Assessed. Physical Damage is <50% and remains in FAIR condition overall as of this date.
10/08/2012	Material condition Re-Assessed and Wood Shop has 4 Tiles becoming loose. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	Carpenter's Shop has 300 Ceiling Tiles Missing and Mastic/Adhesive is exposed. It is now Covered with Plywood. No other changes as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	Additional Damage Observed. Storage Room has 100 SF of Water Damage and 6 Tiles are Missing. 40 Sf of Water Damage and 25 loose Tiles in the Shop. No other changes as of this date.
08/25/2017	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>					<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>07-041AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

### WAREHOUSE BUILDING

#### CARPENTERS SHOP, AND RESTROOM

#### CEILING TILE

1,000 SF

09/06/2005	1'X1' Nailed-On Ceiling Tile. Material is damaged in the form of holes and cuts. This Material is in FAIR condition as of this date.
04/18/2006	Damage Observed. >10% Water Damaged. Friability changed from Moderate to High. Condition changed from FAIR to POOR. Recommendation changed to reflect this fact. No other changes as of this date.
03/05/2007	Material Description changed from ' 1'x1' Nailed-on Ceiling Tile. ' to '1'x1' Ceiling Tile, (Glued-on). Mastic/Adhesive entry added for this Material. Damage reassessed. Damage: <5% Physical Damage - in the form of approximately 10 SF missing in Entry Area; <10% Water Damage - in the form of loose and falling Ceiling Tiles. Friability changed to High. No other changes as of this date.
09/03/2009	Damage Re-Assessed. Physical Damage has changed to <50% due to scratches and gouging observed. Water Damage remains <10% and in POOR condition as of this date.
10/08/2012	Material condition Re-Assessed and Wood Shop has 4 Tiles becoming loose. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	Carpenter's Shop has 300 Ceiling Tiles Missing and Mastic/Adhesive is exposed. It is now Covered with Plywood. Friability changed from Low to Moderate. No other changes as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>					<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
03/17/2016		This Material is unchanged as of this date.	
09/09/2016		This Material is unchanged as of this date.	
03/27/2017		This Material is unchanged as of this date.	
08/25/2017		This Material is unchanged as of this date.	
02/12/2018		This Material is unchanged as of this date.	
08/06/2018		This Material is unchanged as of this date.	
02/04/2019		This Material is unchanged as of this date.	
08/12/2019		This Material is unchanged as of this date.	
08/26/2020		This Material is unchanged as of this date.	
02/08/2021		This Material is unchanged as of this date.	
08/09/2021		This Material is unchanged as of this date.	
02/16/2022		This Material is unchanged as of this date.	
<b>05-212AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

**WAREHOUSE BUILDING**

ENTIRE BUILDING

FIRE DOOR CORE INSULATION

294 SF

09/06/2005	Fire Door Core Insulation (14 EA DOOR). This Material is in GOOD condition as of this date. (Original entry updated 09/16/15)
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	Location and Quantity Re-Assessed. Location Description changed from 'SPRINKLER AND GROUND SHOP' to 'ENTIRE BUILDING'. There are 14 Fire Doors. Original entry updated, Material description changed from 'FIRE DOOR CORE INSULATION. (1 EA DOOR)' to ' FIRE DOOR CORE INSULATION. (14 EA DOOR)'. Quantity changed from 21 SF to 294 SF. No other change as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>					<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
03/27/2017	This Material is unchanged as of this date.		
08/25/2017	This Material is unchanged as of this date.		
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>05-212AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

**WAREHOUSE BUILDING**

EXTERIOR WALL OF WAREHOUSE OFFICE

CHALK BOARD

20 SF

05/11/2009	Green Cementitious Chalkboard (1 EA). This Material is in GOOD condition as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

09-098AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

### WAREHOUSE BUILDING

EXTERIOR WALL OF WAREHOUSE OFFICE

WALL MASTIC

20 SF

05/11/2009	Mastic/Adhesive for Green Cementitious Chalkboard (1 EA). This Material is in GOOD condition as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.



# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**QTY (APPROXIMATE)**

**COMMENTS**

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

08/09/2021 This Material is unchanged as of this date.

02/16/2022 This Material is unchanged as of this date.

<b>09-098AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>
------------------	----------------	------------------	---------------

**WAREHOUSE BUILDING**

WAREHOUSE OFFICE

CARPET MASTIC

72 SF

09/06/2005 Mastic/Adhesive for Grey Carpet. This Material is in GOOD condition as of this date.

03/03/2014 This Material is unchanged as of this date.

08/28/2014 This Material is unchanged as of this date.

03/18/2015 This Material is unchanged as of this date.

09/16/2015 This Material is unchanged as of this date.

03/17/2016 This Material is unchanged as of this date.

09/09/2016 This Material is unchanged as of this date.

03/27/2017 This Material is unchanged as of this date.

08/25/2017 This Material is unchanged as of this date.

02/12/2018 This Material is unchanged as of this date.

08/06/2018 This Material is unchanged as of this date.

02/04/2019 This Material is unchanged as of this date.

08/12/2019 This Material is unchanged as of this date.

08/26/2020 This Material is unchanged as of this date.

02/08/2021 This Material is unchanged as of this date.

08/09/2021 This Material is unchanged as of this date.

02/16/2022 This Material is unchanged as of this date.

<b>05-212AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>
------------------	----------------	------------------	---------------

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

### WAREHOUSE BUILDING

WAREHOUSE RESTROOMS, LOUNGE ROOM, OFFICES, AND SHOPS

SMOOTH WALL MISCELLANEOUS 6,620 SF

09/06/2005	Gypsum Wallboard System Walls and Ceilings. This Material is in GOOD condition as of this date.
03/05/2007	Damage Re-Assessed. Damage Observed. <5% Physical Damage - in the form of small cuts and holes in Restrooms and Entry Hall. Material Condition changed from GOOD to FAIR. No other changes as of this date.
04/14/2008	Water Damage (<10% overall) under the 1'x1' Ceiling Tiles and 5 SF Damaged or missing on the Wall next to the Entry Door. This Material is in FAIR condition as of this date.
09/03/2009	Material remains in <5% Physical Damage and <10% Water Damage. This Material is unchanged as of this date.
09/23/2013	Friability changed from Moderate to Low. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	No Access to Lounge Room as of this date. Other locations were Accessable. No other changes as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	Additional Damage Observed. <5% Physical Damage in the form of 10 SF of Cracks and Peeling on Ceiling in Woodshop Restroom. Material remains in FAIR condition overall. No other changes as of this date.
02/08/2021	This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

08/09/2021 This Material is unchanged as of this date.

02/16/2022 This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

### WAREHOUSE BUILDING

WAREHOUSE RESTROOMS, LOUNGE ROOM, OFFICES, AND SHOPS

SMOOTH WALL SURFACING

6,620 SF

04/18/2006 Skim Coat for Gypsum Wallboard System Walls and Ceilings. This Material is in GOOD condition as of this date.

03/05/2007 Damage Re-Assessed. Damage: <5% Physical Damage - in the form of small cuts and holes in Restrooms and Entry Hall. Material Condition changed from GOOD to FAIR. No other changes as of this date.

04/14/2008 Water Damage (<10% overall) under the 1'x1' Ceiling Tiles and 5 SF damaged or missing on the Wall next to the Entry Door. This Material is in FAIR condition as of this date.

09/03/2009 Material remains in <5% Physical Damage and <10% Water Damage. This Material is unchanged as of this date.

09/23/2013 Friability changed from Moderate to Low. No other changes as of this date.

03/03/2014 Friability changed from Low to Moderate. No other changes as of this date.

08/28/2014 This Material is unchanged as of this date.

03/18/2015 This Material is unchanged as of this date.

09/16/2015 This Material is unchanged as of this date.

03/17/2016 This Material is unchanged as of this date.

09/09/2016 This Material is unchanged as of this date.

03/27/2017 No Access to Lounge Room as of this date. Other locations were Accessable. No other changes as of this date.

08/25/2017 This Material is unchanged as of this date.

02/12/2018 This Material is unchanged as of this date.

08/06/2018 This Material is unchanged as of this date.

02/04/2019 This Material is unchanged as of this date.

08/12/2019 This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>					<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
08/26/2020	Additional Damage Observed. <5% Physical Damage in the form of 10 SF of Cracks and Peeling on Ceiling in Woodshop Restroom. Material remains in FAIR condition overall. No other changes as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		
<b>05-212AAA</b>	<b>ASSUMED</b>	<b>NO SAMPLE</b>	<b>( NS )</b>

**WAREHOUSE BUILDING**

WOOD SHOP (RESTROOM ONLY)

VINYL FLOOR TILE

50 SF

05/11/2009	12"x12" Off-White Vinyl Floor Tile. Old Mastic/Adhesive may exist under new Vinyl Floor Tile and Mastic/Adhesive. (Apparent New Material identified by the AHERA accredited Inspector). This Material is in GOOD condition as of this date.		
03/03/2014	This Material is unchanged as of this date.		
08/28/2014	This Material is unchanged as of this date.		
03/18/2015	This Material is unchanged as of this date.		
09/16/2015	This Material is unchanged as of this date.		
03/17/2016	This Material is unchanged as of this date.		
09/09/2016	This Material is unchanged as of this date.		
03/27/2017	This Material is unchanged as of this date.		
08/25/2017	This Material is unchanged as of this date.		
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

08/09/2021 This Material is unchanged as of this date.

02/16/2022 This Material is unchanged as of this date.

09-098AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

### WAREHOUSE BUILDING

WOOD SHOP (RESTROOM ONLY)

VINYL FLOOR TILE MASTIC

50 SF

05/11/2009 Mastic/Adhesive for 12"x12" Off-White Vinyl Floor Tile. Old Mastic/Adhesive may exist under new Vinyl Floor Tile and Mastic/Adhesive. (Apparent New Material identified by the AHERA accredited Inspector). This Material is in GOOD condition as of this date.

03/03/2014 This Material is unchanged as of this date.

08/28/2014 This Material is unchanged as of this date.

03/18/2015 This Material is unchanged as of this date.

09/16/2015 This Material is unchanged as of this date.

03/17/2016 This Material is unchanged as of this date.

09/09/2016 This Material is unchanged as of this date.

03/27/2017 This Material is unchanged as of this date.

08/25/2017 This Material is unchanged as of this date.

02/12/2018 This Material is unchanged as of this date.

08/06/2018 This Material is unchanged as of this date.

02/04/2019 This Material is unchanged as of this date.

08/12/2019 This Material is unchanged as of this date.

08/26/2020 This Material is unchanged as of this date.

02/08/2021 This Material is unchanged as of this date.

08/09/2021 This Material is unchanged as of this date.

02/16/2022 This Material is unchanged as of this date.

09-098AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>				
<b>LOCATION</b>				
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>				

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

**WELDING SHOP BUILDING**

**WELDING SHOP BUILDING**

- 03/05/2007 BUILDING NOTES:
  
- 03/05/2007 Building Name changed from SIGNS / TOOLS / PARTS SHOP to SIGNS / TOOLS / PARTS SHOP BUILDING.
  
- 03/17/2016 Building Name changed from SIGNS/TOOLS/PARTS SHOP BUILDING to WELDING SHOP BUILDING.

**WELDING SHOP BUILDING**

EXTERIOR

FIRE DOOR CORE INSULATION 21 SF

- 09/16/2015 Fire Door Core Insulation (1 EA Doors). This Material is in GOOD condition as of this date.
  
- 03/17/2016 This Material is unchanged as of this date.
  
- 09/09/2016 This Material is unchanged as of this date.
  
- 03/27/2017 This Material is unchanged as of this date.
  
- 08/25/2017 This Material is unchanged as of this date.
  
- 02/12/2018 This Material is unchanged as of this date.
  
- 08/06/2018 This Material is unchanged as of this date.
  
- 02/04/2019 This Material is unchanged as of this date.
  
- 08/12/2019 This Material is unchanged as of this date.
  
- 08/26/2020 This Material is unchanged as of this date.
  
- 02/08/2021 This Material is unchanged as of this date.
  
- 08/09/2021 This Material is unchanged as of this date.
  
- 02/16/2022 This Material is unchanged as of this date.

15-174AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

### WELDING SHOP BUILDING

SIGNS / TOOLS / PARTS SHOP

SMOOTH WALL MISCELLANEOUS

650 SF

09/06/2005	Gypsum Wallboard System Walls and Ceilings. This Material is in GOOD condition as of this date.
04/18/2006	Material Re-Assessed. Damage: <10% Physical Damage - noted in forms of holes and cuts. This Material is in FAIR condition overall as of this date.
05/11/2009	Damages Re-Assessed. Physical Damages changed to <50% due to deterioration of Material in the form of cuts, holes, and gauging. <10% Water Damage in the form of degredation. Material condition changed from FAIR to POOR overall. Recommendation changed to reflect this change. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>				
<b>LOCATION</b>				
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>
<b>COMMENTS</b>				

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

### WELDING SHOP BUILDING

SIGNS / TOOLS / PARTS SHOP

SMOOTH WALL SURFACING

650 SF

04/18/2006	Skim Coat for Gypsum Wallboard System Walls and Ceilings. <10% Physical Damages noted in forms of holes and cuts. This Material is in FAIR condition as of this date.
05/11/2009	Damages Re-Assessed. Physical Damages changed to <50% due to deterioration of Material in the form of cuts, holes, and gauging. <10% Water Damage in the form of degradation. Material condition changed from FAIR to POOR overall. Recommendation changed to reflect this change.
09/23/2013	This Material changed from POOR condition to FAIR condition as of this date. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is in POOR condition as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

05-212AAA	ASSUMED	NO SAMPLE	( NS )
-----------	---------	-----------	--------



# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

**WOOD SHEDS (2 EA)**

**WOOD SHEDS (2 EA)**

- 03/08/2010 BUILDING NOTES:
- 03/08/2010 Wood Storage Sheds are located on back side of Daycare Building.
- 03/17/2016 Building Name changed from WOOD SHEDS (3) to WOOD SHEDS (2 EA) (by Daycare).

**WOOD SHEDS (2 EA)**

WOOD STORAGE SHEDS (2 EA)

WOOD WALL 200 SF

- 03/08/2010 Wood Wall Panels. Non-ACM Material identified by the AHERA Accredited inspector. This Material is in GOOD condition as of this date.
- 03/03/2014 This Material is unchanged as of this date.
- 08/28/2014 This Material is unchanged as of this date.
- 03/18/2015 This Material is unchanged as of this date.
- 09/16/2015 This Material is unchanged as of this date.
- 03/17/2016 This Material is unchanged as of this date.
- 09/09/2016 This Material is unchanged as of this date.
- 03/27/2017 This Material is unchanged as of this date.
- 08/25/2017 This Material is unchanged as of this date.
- 02/12/2018 This Material is unchanged as of this date.
- 08/06/2018 This Material is unchanged as of this date.
- 02/04/2019 This Material is unchanged as of this date.
- 08/12/2019 This Material is unchanged as of this date.
- 08/26/2020 This Material is unchanged as of this date.
- 02/08/2021 This Material is unchanged as of this date.
- 08/09/2021 This Material is unchanged as of this date.

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME

LOCATION

MATERIAL TYPE

QTY (APPROXIMATE)

COMMENTS

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

02/16/2022 This Material is unchanged as of this date.

10-052AAA	NON-ACM	NO SAMPLE	( NS )
-----------	---------	-----------	--------

# SURVEY REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>					
<b>LOCATION</b>					
<b>MATERIAL TYPE</b>				<b>QTY (APPROXIMATE)</b>	
<b>COMMENTS</b>					

SAMPLE NO.	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS CODE
------------	------------------	---------------	---------------

**WOOD STORAGE SHED**

**WOOD STORAGE SHED**

WOOD STORAGE SHED

WOOD WALL

330 SF

11/28/2011	Wood Walls. Non-ACM Material identified by the AHERA Accredited inspector. This Material is in GOOD condition as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

11-202.NS	NON-ACM	NO SAMPLE	( NS )
-----------	---------	-----------	--------

End Of Report, Total Of 93 Pages

**HOMOGENEOUS MATERIALS IN**  
**BUESD MAINTENANCE AND TRANSPORTATION YARD**

**BUILDING NAME**

**MATERIAL CATEGORY**

**LOCATION**

**MATERIAL TYPE**

**GROUPS STORAGE BUILDING**

MISCELLANEOUS MATERIAL

EXTERIOR  
STORAGE

FIRE DOOR CORE INSULATION  
MISCELLANEOUS

**MAINTENANCE GARAGE BUILDING**

MISCELLANEOUS MATERIAL

OFFICE  
OFFICE  
OFFICE, RESTROOM, SHOWER ROOM, AND STORAGE ROOM

SINK UNDERCOATING  
SUSPENDED CEILING TILE

REPAIR / SERVICES GARAGE  
REPAIR / SERVICES GARAGE  
RESTROOMS (2), AND SHOWER ROOM

SMOOTH WALL  
MISCELLANEOUS  
CHALK BOARD  
WALL MASTIC  
HEAT SHIELD

SURFACING MATERIAL

OFFICE, RESTROOM, SHOWER ROOM, AND STORAGE ROOM

SMOOTH WALL SURFACING

**MAINTENANCE SHOPS OFFICE PORTABLE BUILDING**

MISCELLANEOUS MATERIAL

DOORS - EXTERIOR  
DOORS - INTERIOR  
EXTERIOR WALLS

FIRE DOOR CORE INSULATION  
FIRE DOOR CORE INSULATION  
WEATHER PROOFING  
(OUTSIDE)

HVAC OFFICE AND HALLWAY  
HVAC OFFICE AND HALLWAY

BASEBOARD MASTIC  
SMOOTH WALL  
MISCELLANEOUS

OFFICE PORTABLE  
OFFICE PORTABLE  
OFFICE PORTABLE

BASEBOARD MASTIC  
PRESSED WOOD WALL PANEL  
PRESSED WOOD WALL PANEL  
MASTIC

OFFICE PORTABLE  
OFFICE PORTABLE  
OFFICE PORTABLE  
OFFICES, LOUNGE ROOM AND LOCKSMITH OFFICE

SUSPENDED CEILING TILE  
VINYL WALL COVER  
VINYL WALL COVER MASTIC  
CARPET MASTIC

SURFACING MATERIAL

HVAC OFFICE AND HALLWAY

SMOOTH WALL SURFACING

**MENTOR'S HOUSE**

MISCELLANEOUS MATERIAL

ATTIC  
CHILDREN'S RESTROOM  
CHILDREN'S RESTROOM

LOOSE FILL INSULATION  
VINYL FLOOR TILE  
VINYL FLOOR TILE MASTIC

# HOMOGENEOUS MATERIALS IN BUESD MAINTENANCE AND TRANSPORTATION YARD

## BUILDING NAME

### MATERIAL CATEGORY

#### LOCATION

#### MATERIAL TYPE

DAYCARE KITCHEN	VINYL SHEETING
DAYCARE KITCHEN	VINYL SHEETING
DAYCARE KITCHEN	VINYL SHEETING BACKING PAPER/MASTIC
DAYCARE KITCHEN	VINYL SHEETING BACKING PAPER/MASTIC
DAYCARE ROOM AND ENTRY TO KITCHEN	CEILING MASTIC
DAYCARE ROOM AND ENTRY TO KITCHEN	CEILING TILE
DAYCARE ROOM (IN SE CORNER OF BUILDING)	CARPET MASTIC
ENTIRE BUILDING	SMOOTH WALL MISCELLANEOUS
EXTERIOR WINDOWS	CAULKING
KITCHEN (COUNTER TOP) AND RESTROOM	MORTAR MISCELLANEOUS
OFFICE AND DAYCARE ROOMS	CARPET MASTIC
RESTROOM	BASEBOARD MASTIC
RESTROOM	VINYL FLOOR TILE
RESTROOM	VINYL FLOOR TILE MASTIC
SOUTHEAST ROOM	LAMINATE FLOORING
SOUTHEAST ROOM	LAMINATE FLOORING MASTIC
SURFACING MATERIAL	
ENTIRE BUILDING	SMOOTH WALL SURFACING
EXTERIOR WALLS	ROUGH WALL
EXTERIOR WALLS	ROUGH WALL SURFACING

## METAL STORAGE CONTAINERS (10 EA)

MISCELLANEOUS MATERIAL	
METAL STORAGE CONTAINERS (8 EA)	STORAGE CONTAINER

## METAL STORAGE SHED

MISCELLANEOUS MATERIAL	
METAL STORAGE SHED	STORAGE BUILDING

## PG&E NORTH TOWER BUILDING

MISCELLANEOUS MATERIAL	
PG&E	MISCELLANEOUS

## PG&E SOUTH TOWER ENCLOSURE

MISCELLANEOUS MATERIAL	
TOWER	WOOD WALL

## PORTABLE

# HOMOGENEOUS MATERIALS IN

## BUESD MAINTENANCE AND TRANSPORTATION YARD

### BUILDING NAME

#### MATERIAL CATEGORY

#### LOCATION

#### MATERIAL TYPE

#### MISCELLANEOUS MATERIAL

EXTERIOR DOOR

INTERIOR DOOR

PORTABLES

PORTABLES

PORTABLES

PORTABLES

FIRE DOOR CORE INSULATION

FIRE DOOR CORE INSULATION

BASEBOARD MASTIC

SUSPENDED CEILING TILE

VINYL FLOOR TILE

VINYL FLOOR TILE MASTIC

### STUDENT NUTRITION SERVICE

#### MISCELLANEOUS MATERIAL

STUDENT NUTRITION SERVICES - KITCHEN

PERMANENT BUILDING

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

#### MISCELLANEOUS MATERIAL

ASSISTANT DIRECTOR

ASSISTANT DIRECTOR

CONFERENCE ROOM, STAFF'S LOUNGE ROOM, AND 2 STORAGE ROOM

ENTIRE BUILDING

EXTERIOR BUILDING

LOUNGE ROOM

MAIN OFFICE

MAIN OFFICE

MAIN OFFICE

MAIN OFFICES, HALLWAY, CONFERENCE ROOM, STORAGE ROOM AND LOUNGE ROOM

MAIN OFFICES, RESTROOM, HALLWAY, CONFERENCE ROOM

MAIN OFFICES, RESTROOM, HALLWAY, CONFERENCE ROOM

MAIN OFFICES, RESTROOMS, HALLWAY CONFERENCE ROOM

MAIN OFFICES, RESTROOMS, HALLWAY CONFERENCE ROOM

PLENUM

STAFF RESTROOMS (2)

STAFF RESTROOMS (2)

SUPPLY ROOM, DISPATCH, DRIVER TRAINING OFFICE, DRIVERS LOUNGE, KITCHEN, AND PROGRAMMING ROOM

SUPPLY ROOM, DISPATCH, DRIVER TRAINING OFFICE, DRIVERS LOUNGE, KITCHEN, AND PROGRAMMING ROOM

VINYL FLOOR TILE

VINYL FLOOR TILE MASTIC

SUSPENDED CEILING TILE

FIRE DOOR CORE INSULATION

WEATHER PROOFING  
(OUTSIDE)

SINK UNDERCOATING

BASEBOARD MASTIC

SMOOTH WALL  
MISCELLANEOUS

SUSPENDED CEILING TILE

CARPET MASTIC

VINYL WALL COVER

VINYL WALL COVER MASTIC

PRESSED WOOD WALL PANEL

PRESSED WOOD WALL PANEL  
MASTIC

WALL INSULATION

VINYL SHEETING

VINYL SHEETING BACKING  
PAPER/MASTIC

VINYL FLOOR TILE

VINYL FLOOR TILE MASTIC

#### SURFACING MATERIAL

MAIN OFFICE

SMOOTH WALL SURFACING

### WAREHOUSE BUILDING

# HOMOGENEOUS MATERIALS IN BUESD MAINTENANCE AND TRANSPORTATION YARD

**BUILDING NAME**

**MATERIAL CATEGORY**

**LOCATION**

**MATERIAL TYPE**

MISCELLANEOUS MATERIAL

ALL OFFICES, RESTROOMS, CARPENTERS SHOP, AND LOUNGE ROOM  
 ALL OFFICES, RESTROOMS, SHOPS, LOUNGE ROOM, AND WAREHOUSE STORAGE ROOM  
 ALL OFFICES, RESTROOMS, SHOPS, LOUNGE ROOM, AND WAREHOUSE STORAGE ROOM  
 CARPENTERS SHOP, AND RESTROOM  
 CARPENTERS SHOP, AND RESTROOM  
 ENTIRE BUILDING  
 EXTERIOR WALL OF WAREHOUSE OFFICE  
 EXTERIOR WALL OF WAREHOUSE OFFICE  
 WAREHOUSE OFFICE  
 WAREHOUSE RESTROOMS, LOUNGE ROOM, OFFICES, AND SHOPS  
  
 WOOD SHOP (RESTROOM ONLY)  
 WOOD SHOP (RESTROOM ONLY)

BASEBOARD MASTIC  
 VINYL FLOOR TILE  
 VINYL FLOOR TILE MASTIC  
 CEILING MASTIC  
 CEILING TILE  
 FIRE DOOR CORE INSULATION  
 CHALK BOARD  
 WALL MASTIC  
 CARPET MASTIC  
 SMOOTH WALL  
 MISCELLANEOUS  
 VINYL FLOOR TILE  
 VINYL FLOOR TILE MASTIC

SURFACING MATERIAL

WAREHOUSE RESTROOMS, LOUNGE ROOM, OFFICES, AND SHOPS

SMOOTH WALL SURFACING

**WELDING SHOP BUILDING**

MISCELLANEOUS MATERIAL

EXTERIOR  
 SIGNS / TOOLS / PARTS SHOP

FIRE DOOR CORE INSULATION  
 SMOOTH WALL  
 MISCELLANEOUS

SURFACING MATERIAL

SIGNS / TOOLS / PARTS SHOP

SMOOTH WALL SURFACING

**WOOD SHEDS (2 EA)**

MISCELLANEOUS MATERIAL

WOOD STORAGE SHEDS (2 EA)

WOOD WALL

**WOOD STORAGE SHED**

MISCELLANEOUS MATERIAL

WOOD STORAGE SHED

WOOD WALL

End Of Report, Total Of 4 Pages

**FRIABLE LOCATIONS IN  
BUESD MAINTENANCE AND TRANSPORTATION YARD**

<b>BUILDING NAME</b>	<b>LOCATION</b>	<b>QTY (APPROXIMATE)</b>	<b>ASBESTOS CONTENT</b>
<b>MATERIAL TYPE</b>			
<b>GROUNDS STORAGE BUILDING</b>			
	EXTERIOR		
	FIRE DOOR CORE INSULATION	21 SF	Assumed
<b>MAINTENANCE GARAGE BUILDING</b>			
	OFFICE		
	SUSPENDED CEILING TILE	260 SF	Assumed
	OFFICE, RESTROOM, SHOWER ROOM, AND STORAGE ROOM		
	SMOOTH WALL MISCELLANEOUS	2,650 SF	Assumed
	OFFICE, RESTROOM, SHOWER ROOM, AND STORAGE ROOM		
	SMOOTH WALL SURFACING	2,650 SF	Assumed
	RESTROOMS (2), AND SHOWER ROOM		
	HEAT SHIELD	7.5 SF	Assumed
<b>MAINTENANCE SHOPS OFFICE PORTABLE BUILDING</b>			
	DOORS - EXTERIOR		
	FIRE DOOR CORE INSULATION	42 SF	Assumed
	DOORS - INTERIOR		
	FIRE DOOR CORE INSULATION	168 SF	Assumed
	HVAC OFFICE AND HALLWAY		
	SMOOTH WALL MISCELLANEOUS	1,000 SF	Assumed
	HVAC OFFICE AND HALLWAY		
	SMOOTH WALL SURFACING	1,000 SF	Assumed
	OFFICE PORTABLE		
	BASEBOARD MASTIC	265 LF	Assumed
	OFFICE PORTABLE		
	PRESSED WOOD WALL PANEL	2,660 SF	Assumed
	OFFICE PORTABLE		
	PRESSED WOOD WALL PANEL MASTIC	2,660 SF	Assumed
	OFFICE PORTABLE		
	SUSPENDED CEILING TILE	1,600 SF	Assumed
	OFFICE PORTABLE		
	VINYL WALL COVER	2,660 SF	Assumed
	OFFICE PORTABLE		
	VINYL WALL COVER MASTIC	2,660 SF	Assumed
	OFFICES, LOUNGE ROOM AND LOCKSMITH OFFICE		
	CARPET MASTIC	1,600 SF	Assumed

S= Sq. Ft, l=Inches, L=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*



**FRIABLE LOCATIONS IN  
BUESD MAINTENANCE AND TRANSPORTATION YARD**

BUILDING NAME	LOCATION	MATERIAL TYPE	QTY (APPROXIMATE)	ASBESTOS CONTENT
<b>MENTOR'S HOUSE</b>				
	ATTIC	LOOSE FILL INSULATION	800 SF	Assumed
	CHILDREN'S RESTROOM	VINYL FLOOR TILE	70 SF	New Material
	CHILDREN'S RESTROOM	VINYL FLOOR TILE MASTIC	70 SF	New Material
	DAYCARE KITCHEN	VINYL SHEETING BACKING PAPER/MASTIC	250 SF	Assumed
	DAYCARE KITCHEN	VINYL SHEETING BACKING PAPER/MASTIC	250 SF	Assumed
	DAYCARE ROOM AND ENTRY TO KITCHEN	CEILING MASTIC	500 SF	Assumed
	DAYCARE ROOM AND ENTRY TO KITCHEN	CEILING TILE	500 SF	Assumed
	DAYCARE ROOM (IN SE CORNER OF BUILDING)	CARPET MASTIC	240 SF	Assumed
	ENTIRE BUILDING	SMOOTH WALL MISCELLANEOUS	6,400 SF	Assumed
	ENTIRE BUILDING	SMOOTH WALL SURFACING	6,400 SF	Assumed
	EXTERIOR WINDOWS	CAULKING	400 LF	Assumed
<b>PORTABLE</b>				
	EXTERIOR DOOR	FIRE DOOR CORE INSULATION	42 SF	Assumed
	INTERIOR DOOR	FIRE DOOR CORE INSULATION	21 SF	Assumed
	PORTABLES	BASEBOARD MASTIC	130 LF	Assumed
	PORTABLES	SUSPENDED CEILING TILE	450 SF	Assumed
	PORTABLES	VINYL FLOOR TILE	480 SF	Assumed

**FRIABLE LOCATIONS IN  
BUESD MAINTENANCE AND TRANSPORTATION YARD**

<b>BUILDING NAME</b>	<b>LOCATION</b>	<b>MATERIAL TYPE</b>	<b>QTY (APPROXIMATE)</b>	<b>ASBESTOS CONTENT</b>
	PORTABLES	VINYL FLOOR TILE MASTIC	480 SF	Assumed
<b>TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING</b>				
	ASSISTANT DIRECTOR	VINYL FLOOR TILE	38 SF	Assumed
	ASSISTANT DIRECTOR	VINYL FLOOR TILE MASTIC	38 SF	Assumed
	CONFERENCE ROOM, STAFF'S LOUNGE ROOM, AND 2 STORAGE ROOM	SUSPENDED CEILING TILE	1,500 SF	Assumed
	ENTIRE BUILDING	FIRE DOOR CORE INSULATION	252 SF	Assumed
	EXTERIOR BUILDING	WEATHER PROOFING (OUTSIDE)	1,100 SF	Assumed
	MAIN OFFICE	BASEBOARD MASTIC	1,400 LF	Assumed
	MAIN OFFICE	SMOOTH WALL MISCELLANEOUS	5,100 SF	Assumed
	MAIN OFFICE	SMOOTH WALL SURFACING	5,100 SF	Assumed
	MAIN OFFICE	SUSPENDED CEILING TILE	2,150 SF	Assumed
	MAIN OFFICES, HALLWAY, CONFERENCE ROOM, STORAGE ROOM AND LOUNGE ROOM	CARPET MASTIC	3,300 SF	Assumed
	MAIN OFFICES, RESTROOM, HALLWAY, CONFERENCE ROOM	VINYL WALL COVER	7,800 SF	Assumed
	MAIN OFFICES, RESTROOM, HALLWAY, CONFERENCE ROOM	VINYL WALL COVER MASTIC	7,800 SF	Assumed
	MAIN OFFICES, RESTROOMS, HALLWAY CONFERENCE ROOM	PRESSED WOOD WALL PANEL	7,800 SF	Assumed
	MAIN OFFICES, RESTROOMS, HALLWAY CONFERENCE ROOM	PRESSED WOOD WALL PANEL MASTIC	7,800 SF	Assumed
	PLENUM	WALL INSULATION	2,500 SF	Assumed
	STAFF RESTROOMS (2)	VINYL SHEETING BACKING PAPER/MASTIC	400 SF	Assumed

S= Sq. Ft, I=Inches, L=Linear Ft., N=Number, EA=Each

*HazMat Doc. All Rights Reserved.*

**FRIABLE LOCATIONS IN  
BUESD MAINTENANCE AND TRANSPORTATION YARD**

BUILDING NAME			
LOCATION	MATERIAL TYPE	QTY (APPROXIMATE)	ASBESTOS CONTENT
<b>WAREHOUSE BUILDING</b>			
ALL OFFICES, RESTROOMS, CARPENTERS SHOP, AND LOUNGE ROOM	BASEBOARD MASTIC	470 LF	Assumed
ALL OFFICES, RESTROOMS, SHOPS, LOUNGE ROOM, AND WAREHOUSE STORAGE ROOM	VINYL FLOOR TILE	2,310 SF	Assumed
ALL OFFICES, RESTROOMS, SHOPS, LOUNGE ROOM, AND WAREHOUSE STORAGE ROOM	VINYL FLOOR TILE MASTIC	2,360 SF	Assumed
CARPENTERS SHOP, AND RESTROOM	CEILING MASTIC	1,000 SF	Assumed
CARPENTERS SHOP, AND RESTROOM	CEILING TILE	1,000 SF	Assumed
ENTIRE BUILDING	FIRE DOOR CORE INSULATION	294 SF	Assumed
WAREHOUSE RESTROOMS, LOUNGE ROOM, OFFICES, AND SHOPS	SMOOTH WALL MISCELLANEOUS	6,620 SF	Assumed
WAREHOUSE RESTROOMS, LOUNGE ROOM, OFFICES, AND SHOPS	SMOOTH WALL SURFACING	6,620 SF	Assumed
<b>WELDING SHOP BUILDING</b>			
EXTERIOR	FIRE DOOR CORE INSULATION	21 SF	Assumed
SIGNS / TOOLS / PARTS SHOP	SMOOTH WALL MISCELLANEOUS	650 SF	Assumed
SIGNS / TOOLS / PARTS SHOP	SMOOTH WALL SURFACING	650 SF	Assumed

End Of Report, Total Of 4 Pages

**NON- FRIABLE LOCATIONS IN  
BUESD MAINTENANCE AND TRANSPORTATION YARD**

<b>BUILDING NAME</b>	<b>LOCATION</b>	<b>QTY</b>	<b>ASBESTOS</b>
	<b>MATERIAL TYPE</b>	<b>(APPROXIMATE)</b>	<b>CONTENT</b>
<b>GROUNDS STORAGE BUILDING</b>			
	STORAGE		
	MISCELLANEOUS	240 SF	Assumed
<b>MAINTENANCE GARAGE BUILDING</b>			
	OFFICE		
	SINK UNDERCOATING	5 SF	Assumed
	REPAIR / SERVICES GARAGE		
	CHALK BOARD	8 SF	Assumed
	REPAIR / SERVICES GARAGE		
	WALL MASTIC	8 SF	Assumed
<b>MAINTENANCE SHOPS OFFICE PORTABLE BUILDING</b>			
	EXTERIOR WALLS		
	WEATHER PROOFING (OUTSIDE)	2,800 SF	Assumed
	HVAC OFFICE AND HALLWAY		
	BASEBOARD MASTIC	20 LF	Assumed
<b>MENTOR'S HOUSE</b>			
	DAYCARE KITCHEN		
	VINYL SHEETING	250 SF	Assumed
	DAYCARE KITCHEN		
	VINYL SHEETING	250 SF	Assumed
	EXTERIOR WALLS		
	ROUGH WALL	1,400 SF	Assumed
	EXTERIOR WALLS		
	ROUGH WALL SURFACING	1,400 SF	Assumed
	KITCHEN (COUNTER TOP) AND RESTROOM		
	MORTAR MISCELLANEOUS	750 SF	Assumed
	OFFICE AND DAYCARE ROOMS		
	CARPET MASTIC	1,300 SF	Assumed
	RESTROOM		
	BASEBOARD MASTIC	20 LF	Assumed
	RESTROOM		
	VINYL FLOOR TILE	32 SF	Assumed
	RESTROOM		
	VINYL FLOOR TILE MASTIC	32 SF	Assumed
	SOUTHEAST ROOM		
	LAMINATE FLOORING	421 SF	New Material
	SOUTHEAST ROOM		
	LAMINATE FLOORING MASTIC	421 SF	New Material

**NON- FRIABLE LOCATIONS IN  
BUESD MAINTENANCE AND TRANSPORTATION YARD**

BUILDING NAME	LOCATION	MATERIAL TYPE	QTY (APPROXIMATE)	ASBESTOS CONTENT
<b>METAL STORAGE SHED</b>				
<b>STUDENT NUTRITION SERVICE</b>				
	STUDENT NUTRITION SERVICES - KITCHEN			
	PERMANENT BUILDING		7,480 SF	New Material
<b>TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING</b>				
	LOUNGE ROOM			
	SINK UNDERCOATING		4 SF	Assumed
	STAFF RESTROOMS (2)			
	VINYL SHEETING		400 SF	Assumed
	SUPPLY ROOM, DISPATCH, DRIVER TRAINING OFFICE, DRIVERS LOUNGE, KITCHEN, AND PROGRAMMING ROOM			
	VINYL FLOOR TILE		700 SF	Assumed
	SUPPLY ROOM, DISPATCH, DRIVER TRAINING OFFICE, DRIVERS LOUNGE, KITCHEN, AND PROGRAMMING ROOM			
	VINYL FLOOR TILE MASTIC		700 SF	Assumed
<b>WAREHOUSE BUILDING</b>				
	EXTERIOR WALL OF WAREHOUSE OFFICE			
	CHALK BOARD		20 SF	Assumed
	EXTERIOR WALL OF WAREHOUSE OFFICE			
	WALL MASTIC		20 SF	Assumed
	WAREHOUSE OFFICE			
	CARPET MASTIC		72 SF	Assumed
	WOOD SHOP (RESTROOM ONLY)			
	VINYL FLOOR TILE		50 SF	Assumed
	WOOD SHOP (RESTROOM ONLY)			
	VINYL FLOOR TILE MASTIC		50 SF	Assumed

End Of Report, Total Of 2 Pages

# RECOMMENDATIONS FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

---

### **GROUNDS STORAGE BUILDING**

---

#### **EXTERIOR**

FIRE DOOR CORE INSULATION

21 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.
- 

#### **STORAGE**

MISCELLANEOUS

240 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.
-

# RECOMMENDATIONS FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

### MAINTENANCE GARAGE BUILDING

#### OFFICE

SINK UNDERCOATING 5 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

#### OFFICE

SUSPENDED CEILING TILE 260 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

#### OFFICE, RESTROOM, SHOWER ROOM, AND STORAGE ROOM

SMOOTH WALL MISCELLANEOUS 2,650 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

#### OFFICE, RESTROOM, SHOWER ROOM, AND STORAGE ROOM

SMOOTH WALL SURFACING 2,650 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

# RECOMMENDATIONS FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

---

### REPAIR / SERVICES GARAGE

CHALK BOARD

8 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

### REPAIR / SERVICES GARAGE

WALL MASTIC

8 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

### RESTROOMS (2), AND SHOWER ROOM

HEAT SHIELD

7.5 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.
-



**RECOMMENDATIONS FOR**  
**BUESD MAINTENANCE AND TRANSPORTATION YARD**

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

**MAINTENANCE SHOPS OFFICE PORTABLE BUILDING**

**DOORS - EXTERIOR**

FIRE DOOR CORE INSULATION 42 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

**DOORS - INTERIOR**

FIRE DOOR CORE INSULATION 168 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

**EXTERIOR WALLS**

WEATHER PROOFING (OUTSIDE) 2,800 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

**HVAC OFFICE AND HALLWAY**

BASEBOARD MASTIC 20 LF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.

# RECOMMENDATIONS FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

**BUILDING NAME****LOCATION****MATERIAL TYPE****RECOMMENDATION****QTY****(APPROXIMATE)**

---

**HVAC OFFICE AND HALLWAY**

SMOOTH WALL MISCELLANEOUS 1,000 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

**HVAC OFFICE AND HALLWAY**

SMOOTH WALL SURFACING 1,000 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

**OFFICE PORTABLE**

BASEBOARD MASTIC 265 LF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

**OFFICE PORTABLE**

PRESSED WOOD WALL PANEL 2,660 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

**RECOMMENDATIONS FOR**  
**BUESD MAINTENANCE AND TRANSPORTATION YARD**

---

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

---

OFFICE PORTABLE

PRESSED WOOD WALL PANEL MASTIC 2,660 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

OFFICE PORTABLE

SUSPENDED CEILING TILE 1,600 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

OFFICE PORTABLE

VINYL WALL COVER 2,660 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

OFFICE PORTABLE

VINYL WALL COVER MASTIC 2,660 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.
-

# RECOMMENDATIONS FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

**BUILDING NAME****LOCATION****MATERIAL TYPE****RECOMMENDATION****QTY****(APPROXIMATE)**

---

**OFFICES, LOUNGE ROOM AND LOCKSMITH OFFICE**

CARPET MASTIC

1,600 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

**MENTOR'S HOUSE**

---

**ATTIC**

LOOSE FILL INSULATION

800 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

**CHILDREN'S RESTROOM**

VINYL FLOOR TILE

70 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

**CHILDREN'S RESTROOM**

VINYL FLOOR TILE MASTIC

70 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

# RECOMMENDATIONS FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

---

DAYCARE KITCHEN

VINYL SHEETING

250 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

DAYCARE KITCHEN

VINYL SHEETING

250 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

DAYCARE KITCHEN

VINYL SHEETING BACKING PAPER/MASTIC

250 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

DAYCARE KITCHEN

VINYL SHEETING BACKING PAPER/MASTIC

250 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.
-

**RECOMMENDATIONS FOR**  
**BUESD MAINTENANCE AND TRANSPORTATION YARD**

---

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

---

DAYCARE ROOM AND ENTRY TO KITCHEN

CEILING MASTIC 500 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

DAYCARE ROOM AND ENTRY TO KITCHEN

CEILING TILE 500 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

DAYCARE ROOM (IN SE CORNER OF BUILDING)

CARPET MASTIC 240 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

ENTIRE BUILDING

SMOOTH WALL MISCELLANEOUS 6,400 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.
-

# RECOMMENDATIONS FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

---

### ENTIRE BUILDING

SMOOTH WALL SURFACING 6,400 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

### EXTERIOR WALLS

ROUGH WALL 1,400 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

### EXTERIOR WALLS

ROUGH WALL SURFACING 1,400 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

### EXTERIOR WINDOWS

CAULKING 400 LF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.
-

**RECOMMENDATIONS FOR**  
**BUESD MAINTENANCE AND TRANSPORTATION YARD**

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

**KITCHEN (COUNTER TOP) AND RESTROOM**

MORTAR MISCELLANEOUS 750 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

**OFFICE AND DAYCARE ROOMS**

CARPET MASTIC 1,300 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

**RESTROOM**

BASEBOARD MASTIC 20 LF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

**RESTROOM**

VINYL FLOOR TILE 32 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.



# RECOMMENDATIONS FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

---

### RESTROOM

VINYL FLOOR TILE MASTIC

32 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.
- 

### SOUTHEAST ROOM

LAMINATE FLOORING

421 SF

- (a) This is a replacement/new material.
  - (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
  - (c) This documentation is to be maintained with the District's AHERA records.
- 

### SOUTHEAST ROOM

LAMINATE FLOORING MASTIC

421 SF

- (a) This is a replacement/new material.
  - (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
  - (c) This documentation is to be maintained with the District's AHERA records.
-

# RECOMMENDATIONS FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

---

### **METAL STORAGE CONTAINERS (10 EA)**

---

#### METAL STORAGE CONTAINERS (8 EA)

STORAGE CONTAINER 2,750 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.
- 

### **METAL STORAGE SHED**

---

#### METAL STORAGE SHED

STORAGE BUILDING 725 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.
-

# RECOMMENDATIONS FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

---

### **PG&E NORTH TOWER BUILDING**

This material has been deemed as Non-Asbestos Containing Material (Non-ACM) by the AHERA accredited Inspector. No recommendations are necessary.

---

PG&E

MISCELLANEOUS

154 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.
- 

### **PG&E SOUTH TOWER ENCLOSURE**

TOWER

WOOD WALL

533 SF

This material has been deemed as Non-Asbestos Containing Material (Non-ACM) by the AHERA accredited Inspector. No recommendations are necessary.

---

# RECOMMENDATIONS FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

### PORTABLE

#### EXTERIOR DOOR

FIRE DOOR CORE INSULATION 42 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

#### INTERIOR DOOR

FIRE DOOR CORE INSULATION 21 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

### PORTABLES

BASEBOARD MASTIC 130 LF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

### PORTABLES

SUSPENDED CEILING TILE 450 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

# RECOMMENDATIONS FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

---

### PORTABLES

VINYL FLOOR TILE 480 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.
- 

### PORTABLES

VINYL FLOOR TILE MASTIC 480 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.
- 

## **STUDENT NUTRITION SERVICE**

---

### STUDENT NUTRITION SERVICES - KITCHEN

PERMANENT BUILDING 7,480 SF

- (a) This is a replacement/new material.
  - (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
  - (c) This documentation is to be maintained with the District's AHERA records.
-

# RECOMMENDATIONS FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

---

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

---

#### ASSISTANT DIRECTOR

VINYL FLOOR TILE 38 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.
- 

#### ASSISTANT DIRECTOR

VINYL FLOOR TILE MASTIC 38 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.
- 

#### CONFERENCE ROOM, STAFF'S LOUNGE ROOM, AND 2 STORAGE ROOM

SUSPENDED CEILING TILE 1,500 SF

- (a) Sample the material. If ACM include this material in the Operations and Maintenance (O & M) manual. Maintain the material in an intact and undamaged condition
  - (b) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.
- 

#### ENTIRE BUILDING

FIRE DOOR CORE INSULATION 252 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.
-

# RECOMMENDATIONS FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

**BUILDING NAME****LOCATION****MATERIAL TYPE****RECOMMENDATION****QTY****(APPROXIMATE)**

---

**EXTERIOR BUILDING**

WEATHER PROOFING (OUTSIDE) 1,100 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

**LOUNGE ROOM**

SINK UNDERCOATING 4 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

**MAIN OFFICE**

BASEBOARD MASTIC 1,400 LF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

**MAIN OFFICE**

SMOOTH WALL MISCELLANEOUS 5,100 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.
-

# RECOMMENDATIONS FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

---

### MAIN OFFICE

SMOOTH WALL SURFACING 5,100 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

### MAIN OFFICE

SUSPENDED CEILING TILE 2,150 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

### MAIN OFFICES, HALLWAY, CONFERENCE ROOM, STORAGE ROOM AND LOUNGE ROOM

CARPET MASTIC 3,300 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

### MAIN OFFICES, RESTROOM, HALLWAY, CONFERENCE ROOM

VINYL WALL COVER 7,800 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.
-



# RECOMMENDATIONS FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

**BUILDING NAME****LOCATION****MATERIAL TYPE****RECOMMENDATION****QTY****(APPROXIMATE)**

---

**MAIN OFFICES, RESTROOM, HALLWAY, CONFERENCE ROOM**

VINYL WALL COVER MASTIC 7,800 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

**MAIN OFFICES, RESTROOMS, HALLWAY CONFERENCE ROOM**

PRESSED WOOD WALL PANEL 7,800 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

**MAIN OFFICES, RESTROOMS, HALLWAY CONFERENCE ROOM**

PRESSED WOOD WALL PANEL MASTIC 7,800 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

**PLENUM**

WALL INSULATION 2,500 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

# RECOMMENDATIONS FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

**BUILDING NAME****LOCATION****MATERIAL TYPE****RECOMMENDATION****QTY****(APPROXIMATE)**

---

## STAFF RESTROOMS (2)

VINYL SHEETING

400 SF

- (a) This is a replacement/new material.
- (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
- (c) This documentation is to be maintained with the District's AHERA records.

## STAFF RESTROOMS (2)

VINYL SHEETING BACKING PAPER/MASTIC

400 SF

- (a) This is a replacement/new material.
- (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
- (c) This documentation is to be maintained with the District's AHERA records.

## SUPPLY ROOM, DISPATCH, DRIVER TRAINING OFFICE, DRIVERS LOUNGE, KITCHEN, AND PROGRAMMING ROOM

VINYL FLOOR TILE

700 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

## SUPPLY ROOM, DISPATCH, DRIVER TRAINING OFFICE, DRIVERS LOUNGE, KITCHEN, AND PROGRAMMING ROOM

VINYL FLOOR TILE MASTIC

700 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

# RECOMMENDATIONS FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

**BUILDING NAME****LOCATION****MATERIAL TYPE****RECOMMENDATION****QTY****(APPROXIMATE)**

---

**WAREHOUSE BUILDING**

## ALL OFFICES, RESTROOMS, CARPENTERS SHOP, AND LOUNGE ROOM

BASEBOARD MASTIC

470 LF

- (a) Sample the material. If ACM include this material in the Operations and Maintenance (O & M) manual. Maintain the material in an intact and undamaged condition
- (b) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

## ALL OFFICES, RESTROOMS, SHOPS, LOUNGE ROOM, AND WAREHOUSE STORAGE ROOM

VINYL FLOOR TILE

2,310 SF

- (a) Sample the material. If ACM include this material in the Operations and Maintenance (O & M) manual. Maintain the material in an intact and undamaged condition
- (b) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

## ALL OFFICES, RESTROOMS, SHOPS, LOUNGE ROOM, AND WAREHOUSE STORAGE ROOM

VINYL FLOOR TILE MASTIC

2,360 SF

- (a) Sample the material. If ACM include this material in the Operations and Maintenance (O & M) manual. Maintain the material in an intact and undamaged condition
- (b) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

## CARPENTERS SHOP, AND RESTROOM

CEILING MASTIC

1,000 SF

- (a) Sample the material. If ACM include this material in the Operations and Maintenance (O & M) manual. Maintain the material in an intact and undamaged condition
- (b) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

## CARPENTERS SHOP, AND RESTROOM

CEILING TILE

1,000 SF

- (a) Sample the material. If ACM include this material in the Operations and Maintenance (O & M) manual. Maintain the material in an intact and undamaged condition
- (b) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

# RECOMMENDATIONS FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

**BUILDING NAME****LOCATION****MATERIAL TYPE****RECOMMENDATION****QTY****(APPROXIMATE)**

---

**ENTIRE BUILDING**

FIRE DOOR CORE INSULATION 294 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

**EXTERIOR WALL OF WAREHOUSE OFFICE**

CHALK BOARD 20 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

**EXTERIOR WALL OF WAREHOUSE OFFICE**

WALL MASTIC 20 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

**WAREHOUSE OFFICE**

CARPET MASTIC 72 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.
-

# RECOMMENDATIONS FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

---

### WAREHOUSE RESTROOMS, LOUNGE ROOM, OFFICES, AND SHOPS

SMOOTH WALL MISCELLANEOUS 6,620 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

### WAREHOUSE RESTROOMS, LOUNGE ROOM, OFFICES, AND SHOPS

SMOOTH WALL SURFACING 6,620 SF

- (a) No abatement is necessary.
- (b) Maintain the material in an intact and undamaged condition.
- (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
- (d) Include this material in the long term surveillance and re-inspection program
- (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.

---

### WOOD SHOP (RESTROOM ONLY)

VINYL FLOOR TILE 50 SF

- (a) This is a replacement/new material.
- (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
- (c) This documentation is to be maintained with the District's AHERA records.

---

### WOOD SHOP (RESTROOM ONLY)

VINYL FLOOR TILE MASTIC 50 SF

- (a) This is a replacement/new material.
  - (b) The District should obtain documentation from the manufacturer/installer that no asbestos has been used in the manufacture or installation of this building material.
  - (c) This documentation is to be maintained with the District's AHERA records.
-

# RECOMMENDATIONS FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

---

### **WELDING SHOP BUILDING**

---

#### **EXTERIOR**

FIRE DOOR CORE INSULATION 21 SF

- (a) No abatement is necessary.
  - (b) Maintain the material in an intact and undamaged condition.
  - (c) Include this material in the Operations and Maintenance (O & M) program until it has been replaced with a material that does not contain Asbestos.
  - (d) Include this material in the long term surveillance and re-inspection program
  - (e) Remove the material if it becomes damaged or repairs and maintenance work may impact this material.
- Removal must be designed and performed by accredited personnel only.
- 

#### **SIGNS / TOOLS / PARTS SHOP**

SMOOTH WALL MISCELLANEOUS 650 SF

- (a) Sample the material. If ACM include this material in the Operations and Maintenance (O & M) manual. Maintain the material in an intact and undamaged condition
  - (b) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.
- 

#### **SIGNS / TOOLS / PARTS SHOP**

SMOOTH WALL SURFACING 650 SF

- (a) Sample the material. If ACM include this material in the Operations and Maintenance (O & M) manual. Maintain the material in an intact and undamaged condition
  - (b) Remove the material if it becomes damaged or repairs and maintenance work may impact this material. Removal must be designed and performed by accredited personnel only.
-

**RECOMMENDATIONS FOR**  
**BUESD MAINTENANCE AND TRANSPORTATION YARD**

---

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

**RECOMMENDATION**

**QTY**

**(APPROXIMATE)**

---

**WOOD SHEDS (2 EA)**

---

**WOOD STORAGE SHEDS (2 EA)**

WOOD WALL

200 SF

This material has been deemed as Non-Asbestos Containing Material (Non-ACM) by the AHERA accredited Inspector. No recommendations are necessary.

---

**WOOD STORAGE SHED**

**WOOD STORAGE SHED**

WOOD WALL

330 SF

This material has been deemed as Non-Asbestos Containing Material (Non-ACM) by the AHERA accredited Inspector. No recommendations are necessary.

---

---

**End Of Report, Total Of 26 Pages**

---

# SAMPLES REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME

LOCATION

MATERIAL TYPE

SAMPLE No. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
------------------------	------	--------	---------------------	------------------	------------------

**GROUND STORAGE BUILDING**

**GROUND STORAGE BUILDING**

EXTERIOR

FIRE DOOR CORE INSULATION

**15-174AAA** 9/16/2015 Positive ASSUMED NO SAMPLE NS

**GROUND STORAGE BUILDING**

STORAGE

MISCELLANEOUS

**08-241AAA** 10/13/2008 Positive ASSUMED NO SAMPLE NS

Metal Ceiling, Wood Wall, and Concrete Floor.



# SAMPLES REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	SAMPLE No.	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
<b>MAINTENANCE GARAGE BUILDING</b>								
<b>MAINTENANCE GARAGE BUILDING</b>								
	OFFICE	SINK UNDERCOATING						
<b><u>09-098AAA</u></b>			5/11/2009	Positive	ASSUMED	NO SAMPLE		NS
<b>MAINTENANCE GARAGE BUILDING</b>								
	OFFICE	SUSPENDED CEILING TILE						
<b><u>05-212AAA</u></b>			9/6/2005	Positive	ASSUMED	NO SAMPLE		NS
<b>MAINTENANCE GARAGE BUILDING</b>								
	OFFICE, RESTROOM, SHOWER ROOM, AND STORAGE ROOM	SMOOTH WALL MISCELLANEOUS						
<b><u>05-212AAA</u></b>			9/6/2005	Positive	ASSUMED	NO SAMPLE		NS
<b>MAINTENANCE GARAGE BUILDING</b>								
	OFFICE, RESTROOM, SHOWER ROOM, AND STORAGE ROOM	SMOOTH WALL SURFACING						
<b><u>05-212AAA</u></b>			4/18/2006	Positive	ASSUMED	NO SAMPLE		NS
<b>MAINTENANCE GARAGE BUILDING</b>								
	REPAIR / SERVICES GARAGE	CHALK BOARD						
<b><u>09-098AAA</u></b>			5/11/2009	Positive	ASSUMED	NO SAMPLE		NS
<b>MAINTENANCE GARAGE BUILDING</b>								
	REPAIR / SERVICES GARAGE	WALL MASTIC						
<b><u>09-098AAA</u></b>			5/11/2009	Positive	ASSUMED	NO SAMPLE		NS
<b>MAINTENANCE GARAGE BUILDING</b>								
	RESTROOMS (2), AND SHOWER ROOM	HEAT SHIELD						
<b><u>05-212AAA</u></b>			3/5/2007	Positive	ASSUMED	NO SAMPLE		NS

# SAMPLES REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE				
SAMPLE No. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE	
<b>MAINTENANCE SHOPS OFFICE PORTABLE BUILDING</b>						
<b>MAINTENANCE SHOPS OFFICE PORTABLE BUILDING</b>						
DOORS - EXTERIOR						
FIRE DOOR CORE INSULATION						
<b><u>12-185AAA</u></b>	10/8/2012	Positive	ASSUMED	NO SAMPLE	NS	
<b>MAINTENANCE SHOPS OFFICE PORTABLE BUILDING</b>						
<b>MAINTENANCE SHOPS OFFICE PORTABLE BUILDING</b>						
DOORS - INTERIOR						
FIRE DOOR CORE INSULATION						
<b><u>09-095AAA</u></b>	5/11/2009	Positive	ASSUMED	NO SAMPLE	NS	
<b>MAINTENANCE SHOPS OFFICE PORTABLE BUILDING</b>						
<b>MAINTENANCE SHOPS OFFICE PORTABLE BUILDING</b>						
EXTERIOR WALLS						
WEATHER PROOFING (OUTSIDE)						
<b><u>05-212AAA</u></b>	4/18/2006	Positive	ASSUMED	NO SAMPLE	NS	
<b>MAINTENANCE SHOPS OFFICE PORTABLE BUILDING</b>						
<b>MAINTENANCE SHOPS OFFICE PORTABLE BUILDING</b>						
HVAC OFFICE AND HALLWAY						
BASEBOARD MASTIC						
<b><u>05-212AAA</u></b>	4/18/2006	Positive	ASSUMED	NO SAMPLE	NS	
<b>MAINTENANCE SHOPS OFFICE PORTABLE BUILDING</b>						
<b>MAINTENANCE SHOPS OFFICE PORTABLE BUILDING</b>						
HVAC OFFICE AND HALLWAY						
SMOOTH WALL MISCELLANEOUS						
<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS	
<b>MAINTENANCE SHOPS OFFICE PORTABLE BUILDING</b>						
<b>MAINTENANCE SHOPS OFFICE PORTABLE BUILDING</b>						
HVAC OFFICE AND HALLWAY						
SMOOTH WALL SURFACING						
<b><u>05-212AAA</u></b>	4/18/2006	Positive	ASSUMED	NO SAMPLE	NS	
<b>MAINTENANCE SHOPS OFFICE PORTABLE BUILDING</b>						
<b>MAINTENANCE SHOPS OFFICE PORTABLE BUILDING</b>						
OFFICE PORTABLE						
BASEBOARD MASTIC						
<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS	

# SAMPLES REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	SAMPLE No.	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
COMMENTS								

**MAINTENANCE SHOPS OFFICE PORTABLE BUILDING**

OFFICE PORTABLE  
PRESSED WOOD WALL PANEL

<b><u>08-241AAA</u></b>	10/13/2008	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	------------	----------	---------	-----------	----

**MAINTENANCE SHOPS OFFICE PORTABLE BUILDING**

OFFICE PORTABLE  
SUSPENDED CEILING TILE

<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

**MAINTENANCE SHOPS OFFICE PORTABLE BUILDING**

OFFICE PORTABLE  
VINYL WALL COVER

<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

**MAINTENANCE SHOPS OFFICE PORTABLE BUILDING**

OFFICE PORTABLE  
VINYL WALL COVER MASTIC

<b><u>08-241AAA</u></b>	10/13/2008	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	------------	----------	---------	-----------	----

**MAINTENANCE SHOPS OFFICE PORTABLE BUILDING**

OFFICES, LOUNGE ROOM AND LOCKSMITH OFFICE  
CARPET MASTIC

<b><u>05-212AAA</u></b>	4/18/2006	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

# SAMPLES REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	SAMPLE No.	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
---------------	----------	---------------	------------	------	--------	------------------	---------------	---------------

**MENTOR'S HOUSE**

**MENTOR'S HOUSE**

ATTIC  
LOOSE FILL INSULATION

<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

**MENTOR'S HOUSE**

CHILDREN'S RESTROOM  
VINYL FLOOR TILE

<b><u>18-127AAA</u></b>	8/6/2018	Negative	NEW MATERIAL	NONE DETECTED	ND
-------------------------	----------	----------	--------------	---------------	----

**MENTOR'S HOUSE**

CHILDREN'S RESTROOM  
VINYL FLOOR TILE MASTIC

<b><u>18-127AAA</u></b>	8/6/2018	Negative	NEW MATERIAL	NONE DETECTED	ND
-------------------------	----------	----------	--------------	---------------	----

**MENTOR'S HOUSE**

DAYCARE KITCHEN  
VINYL SHEETING

<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

**MENTOR'S HOUSE**

DAYCARE KITCHEN  
VINYL SHEETING

<b><u>16-074AAA</u></b>	3/17/2016	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

**MENTOR'S HOUSE**

DAYCARE KITCHEN  
VINYL SHEETING BACKING PAPER/MASTIC

<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

**MENTOR'S HOUSE**

DAYCARE KITCHEN  
VINYL SHEETING BACKING PAPER/MASTIC

<b><u>16-074AAA</u></b>	3/17/2016	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

# SAMPLES REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	SAMPLE No.	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
---------------	----------	---------------	------------	------	--------	------------------	---------------	---------------

**MENTOR'S HOUSE**

DAYCARE ROOM AND ENTRY TO KITCHEN  
CEILING MASTIC

<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

**MENTOR'S HOUSE**

DAYCARE ROOM AND ENTRY TO KITCHEN  
CEILING TILE

<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

**MENTOR'S HOUSE**

DAYCARE ROOM (IN SE CORNER OF BUILDING)  
CARPET MASTIC

<b><u>08-075AAA</u></b>	4/14/2008	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

**MENTOR'S HOUSE**

ENTIRE BUILDING  
SMOOTH WALL MISCELLANEOUS

<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

**MENTOR'S HOUSE**

ENTIRE BUILDING  
SMOOTH WALL SURFACING

<b><u>05-212AAA</u></b>	4/18/2006	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

**MENTOR'S HOUSE**

EXTERIOR WALLS  
ROUGH WALL

<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

**MENTOR'S HOUSE**

EXTERIOR WALLS  
ROUGH WALL SURFACING

<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

# SAMPLES REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE				
SAMPLE No. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE	
<b>MENTOR'S HOUSE</b>						
EXTERIOR WINDOWS CAULKING						
<u>05-212AAA</u>	9/6/2005	Positive	ASSUMED	NO SAMPLE		NS
<b>MENTOR'S HOUSE</b>						
KITCHEN (COUNTER TOP) AND RESTROOM MORTAR MISCELLANEOUS						
<u>05-212AAA</u>	4/18/2006	Positive	ASSUMED	NO SAMPLE		NS
<b>MENTOR'S HOUSE</b>						
OFFICE AND DAYCARE ROOMS CARPET MASTIC						
<u>05-212AAA</u>	9/6/2005	Positive	ASSUMED	NO SAMPLE		NS
<b>MENTOR'S HOUSE</b>						
RESTROOM BASEBOARD MASTIC						
<u>08-241AAA</u>	10/13/2008	Positive	ASSUMED	NO SAMPLE		NS
<b>MENTOR'S HOUSE</b>						
RESTROOM VINYL FLOOR TILE						
<u>08-241AAA</u>	10/13/2008	Positive	ASSUMED	NO SAMPLE		NS
<b>MENTOR'S HOUSE</b>						
RESTROOM VINYL FLOOR TILE MASTIC						
<u>08-241AAA</u>	10/13/2008	Positive	ASSUMED	NO SAMPLE		NS
<b>MENTOR'S HOUSE</b>						
SOUTHEAST ROOM LAMINATE FLOORING						
<u>18-127AAA</u>	8/6/2018	Negative	NEW MATERIAL	NONE DETECTED		ND

# SAMPLES REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME

LOCATION

MATERIAL TYPE

SAMPLE No. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
------------------------	------	--------	---------------------	------------------	------------------

### MENTOR'S HOUSE

SOUTHEAST ROOM

LAMINATE FLOORING MASTIC

<b>18-127AAA</b>	8/6/2018	Negative	NEW MATERIAL	NONE DETECTED	ND
------------------	----------	----------	--------------	---------------	----

# SAMPLES REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME

LOCATION

MATERIAL TYPE

SAMPLE No. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
------------------------	------	--------	---------------------	------------------	------------------

**METAL STORAGE CONTAINERS (10 EA)**

**METAL STORAGE CONTAINERS (10 EA)**

METAL STORAGE CONTAINERS (8 EA)

STORAGE CONTAINER

<b>05-212.NS</b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS
------------------	----------	----------	---------	-----------	----

Metal Storage Containers.



# SAMPLES REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME

LOCATION

MATERIAL TYPE

SAMPLE No. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
------------------------	------	--------	---------------------	------------------	------------------

**METAL STORAGE SHED**

**METAL STORAGE SHED**

METAL STORAGE SHED

STORAGE BUILDING

**11-202.NS**

11/28/2011 Positive

ASSUMED

NO SAMPLE

NS

Metal Storage Shed.

# SAMPLES REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME

LOCATION

MATERIAL TYPE

SAMPLE No. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
------------------------	------	--------	---------------------	------------------	------------------

PG&E NORTH TOWER BUILDING

PG&E NORTH TOWER BUILDING

PG&E

MISCELLANEOUS

**16-074.NS**

3/17/2016

Positive

ASSUMED

NO SAMPLE

NS

Metal and Concrete Building.

# SAMPLES REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME

LOCATION

MATERIAL TYPE

SAMPLE No. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
------------------------	------	--------	---------------------	------------------	------------------

PG&E SOUTH TOWER ENCLOSURE

PG&E SOUTH TOWER ENCLOSURE

TOWER

WOOD WALL

**11-202.NS**

11/28/2011 Negative

NON-ACM

NO SAMPLE

NS

Wood Walls.

# SAMPLES REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

**BUILDING NAME**

**LOCATION**

**MATERIAL TYPE**

SAMPLE NO. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
------------------------	------	--------	---------------------	------------------	------------------

**PORTABLE**

**PORTABLE**

EXTERIOR DOOR

FIRE DOOR CORE INSULATION

<b><u>10-174AAA</u></b>	7/30/2010	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

**PORTABLE**

INTERIOR DOOR

FIRE DOOR CORE INSULATION

<b><u>10-174AAA</u></b>	7/30/2010	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

**PORTABLE**

PORTABLES

BASEBOARD MASTIC

<b><u>10-174AAA</u></b>	7/30/2010	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

**PORTABLE**

PORTABLES

SUSPENDED CEILING TILE

<b><u>10-174AAA</u></b>	7/30/2010	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

**PORTABLE**

PORTABLES

VINYL FLOOR TILE

<b><u>10-174AAA</u></b>	7/30/2010	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

**PORTABLE**

PORTABLES

VINYL FLOOR TILE MASTIC

<b><u>10-174AAA</u></b>	7/30/2010	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

# SAMPLES REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME

LOCATION

MATERIAL TYPE

SAMPLE No. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
------------------------	------	--------	---------------------	------------------	------------------

STUDENT NUTRITION SERVICE

STUDENT NUTRITION SERVICE

STUDENT NUTRITION SERVICES - KITCHEN

PERMANENT BUILDING

<u>22-025.NS</u>	2/16/2022	Positive	ASSUMED	NO SAMPLE	NS
------------------	-----------	----------	---------	-----------	----

# SAMPLES REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	SAMPLE No.	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
---------------	----------	---------------	------------	------	--------	------------------	---------------	---------------

**TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING**

**TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING**

ASSISTANT DIRECTOR  
VINYL FLOOR TILE

<b><u>11-202AAA</u></b>	11/28/2011	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	------------	----------	---------	-----------	----

**TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING**

ASSISTANT DIRECTOR  
VINYL FLOOR TILE MASTIC

<b><u>11-202AAA</u></b>	11/28/2011	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	------------	----------	---------	-----------	----

**TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING**

CONFERENCE ROOM, STAFF'S LOUNGE ROOM, AND 2 STORAGE ROOM  
SUSPENDED CEILING TILE

<b><u>09-098AAA</u></b>	5/11/2009	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

**TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING**

ENTIRE BUILDING  
FIRE DOOR CORE INSULATION

<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

**TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING**

EXTERIOR BUILDING  
WEATHER PROOFING (OUTSIDE)

<b><u>07-041AAA</u></b>	3/5/2007	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

**TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING**

LOUNGE ROOM  
SINK UNDERCOATING

<b><u>08-075AAA</u></b>	4/14/2008	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

**TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING**

MAIN OFFICE  
BASEBOARD MASTIC

<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

# SAMPLES REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	SAMPLE No.	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
---------------	----------	---------------	------------	------	--------	------------------	---------------	---------------

**TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING**

MAIN OFFICE

SMOOTH WALL MISCELLANEOUS

<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

**TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING**

MAIN OFFICE

SMOOTH WALL SURFACING

<b><u>05-212AAA</u></b>	4/18/2006	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

**TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING**

MAIN OFFICE

SUSPENDED CEILING TILE

<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

**TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING**

MAIN OFFICES, HALLWAY, CONFERENCE ROOM, STORAGE ROOM AND LOUNGE ROOM

CARPET MASTIC

<b><u>05-212AAA</u></b>	4/18/2006	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

**TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING**

MAIN OFFICES, RESTROOM, HALLWAY, CONFERENCE ROOM

VINYL WALL COVER

<b><u>08-214AAA</u></b>	10/13/2008	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	------------	----------	---------	-----------	----

**TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING**

MAIN OFFICES, RESTROOM, HALLWAY, CONFERENCE ROOM

VINYL WALL COVER MASTIC

<b><u>08-241AAA</u></b>	10/13/2008	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	------------	----------	---------	-----------	----

**TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING**

MAIN OFFICES, RESTROOMS, HALLWAY CONFERENCE ROOM

PRESSED WOOD WALL PANEL

<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

# SAMPLES REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	SAMPLE No.	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
<b>TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING</b>								
	PLENUM							
	WALL INSULATION							
<b><u>05-212AAA</u></b>				9/6/2005	Positive	ASSUMED	NO SAMPLE	NS
<b>TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING</b>								
	STAFF RESTROOMS (2)							
	VINYL SHEETING							
<b><u>05-212AAA</u></b>				4/18/2006	Positive	ASSUMED	NO SAMPLE	NS
Apparent New Material as of this date.								
<b>TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING</b>								
	STAFF RESTROOMS (2)							
	VINYL SHEETING BACKING PAPER/MASTIC							
<b><u>05-212AAA</u></b>				4/18/2006	Positive	ASSUMED	NO SAMPLE	NS
Apparent New Material as of this date.								
<b>TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING</b>								
	SUPPLY ROOM, DISPATCH, DRIVER TRAINING OFFICE, DRIVERS LOUNGE, KITCHEN, AND PROGRAMMING ROOM							
	VINYL FLOOR TILE							
<b><u>05-212AAA</u></b>				9/6/2005	Positive	ASSUMED	NO SAMPLE	NS
<b>TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING</b>								
	SUPPLY ROOM, DISPATCH, DRIVER TRAINING OFFICE, DRIVERS LOUNGE, KITCHEN, AND PROGRAMMING ROOM							
	VINYL FLOOR TILE MASTIC							
<b><u>05-212AAA</u></b>				9/6/2005	Positive	ASSUMED	NO SAMPLE	NS



# SAMPLES REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	SAMPLE No.	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
<b>WAREHOUSE BUILDING</b>								
<b>WAREHOUSE BUILDING</b>								
ALL OFFICES, RESTROOMS, CARPENTERS SHOP, AND LOUNGE ROOM								
BASEBOARD MASTIC								
<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS			
<b>WAREHOUSE BUILDING</b>								
ALL OFFICES, RESTROOMS, SHOPS, LOUNGE ROOM, AND WAREHOUSE STORAGE ROOM								
VINYL FLOOR TILE								
<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS			
<b>WAREHOUSE BUILDING</b>								
ALL OFFICES, RESTROOMS, SHOPS, LOUNGE ROOM, AND WAREHOUSE STORAGE ROOM								
VINYL FLOOR TILE MASTIC								
<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS			
<b>WAREHOUSE BUILDING</b>								
CARPENTERS SHOP, AND RESTROOM								
CEILING MASTIC								
<b><u>07-041AAA</u></b>	3/5/2007	Positive	ASSUMED	NO SAMPLE	NS			
<b>WAREHOUSE BUILDING</b>								
CARPENTERS SHOP, AND RESTROOM								
CEILING TILE								
<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS			
<b>WAREHOUSE BUILDING</b>								
ENTIRE BUILDING								
FIRE DOOR CORE INSULATION								
<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS			
<b>WAREHOUSE BUILDING</b>								
EXTERIOR WALL OF WAREHOUSE OFFICE								
CHALK BOARD								
<b><u>09-098AAA</u></b>	5/11/2009	Positive	ASSUMED	NO SAMPLE	NS			

# SAMPLES REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	SAMPLE No.	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
COMMENTS								

**WAREHOUSE BUILDING**

EXTERIOR WALL OF WAREHOUSE OFFICE  
WALL MASTIC

<b><u>09-098AAA</u></b>	5/11/2009	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

**WAREHOUSE BUILDING**

WAREHOUSE OFFICE  
CARPET MASTIC

<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

**WAREHOUSE BUILDING**

WAREHOUSE RESTROOMS, LOUNGE ROOM, OFFICES, AND SHOPS  
SMOOTH WALL MISCELLANEOUS

<b><u>05-212AAA</u></b>	9/6/2005	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	----------	----------	---------	-----------	----

**WAREHOUSE BUILDING**

WAREHOUSE RESTROOMS, LOUNGE ROOM, OFFICES, AND SHOPS  
SMOOTH WALL SURFACING

<b><u>05-212AAA</u></b>	4/18/2006	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

**WAREHOUSE BUILDING**

WOOD SHOP (RESTROOM ONLY)  
VINYL FLOOR TILE

<b><u>09-098AAA</u></b>	5/11/2009	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

**WAREHOUSE BUILDING**

WOOD SHOP (RESTROOM ONLY)  
VINYL FLOOR TILE MASTIC

<b><u>09-098AAA</u></b>	5/11/2009	Positive	ASSUMED	NO SAMPLE	NS
-------------------------	-----------	----------	---------	-----------	----

# SAMPLES REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME

LOCATION

MATERIAL TYPE

SAMPLE No. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
------------------------	------	--------	---------------------	------------------	------------------

**WELDING SHOP BUILDING**

**WELDING SHOP BUILDING**

EXTERIOR

FIRE DOOR CORE INSULATION

**15-174AAA**

9/16/2015

Positive

ASSUMED

NO SAMPLE

NS

**WELDING SHOP BUILDING**

SIGNS / TOOLS / PARTS SHOP

SMOOTH WALL MISCELLANEOUS

**05-212AAA**

9/6/2005

Positive

ASSUMED

NO SAMPLE

NS

**WELDING SHOP BUILDING**

SIGNS / TOOLS / PARTS SHOP

SMOOTH WALL SURFACING

**05-212AAA**

4/18/2006

Positive

ASSUMED

NO SAMPLE

NS

# SAMPLES REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME

LOCATION

MATERIAL TYPE

SAMPLE No. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
------------------------	------	--------	---------------------	------------------	------------------

WOOD SHEDS (2 EA)

WOOD SHEDS (2 EA)

WOOD STORAGE SHEDS (2 EA)

WOOD WALL

**10-052AAA**

3/8/2010

Negative

NON-ACM

NO SAMPLE

NS

Wood Wall Panels.

# SAMPLES REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME

LOCATION

MATERIAL TYPE

SAMPLE No. COMMENTS	DATE	RESULT	ASBESTOS CONTENT	ASBESTOS NAME	ASBESTOS TYPE
------------------------	------	--------	---------------------	------------------	------------------

WOOD STORAGE SHED

WOOD STORAGE SHED

WOOD STORAGE SHED

WOOD WALL

**11-202.NS**

11/28/2011 Negative

NON-ACM

NO SAMPLE

NS

Wood Walls.

---

End Of Report, Total Of 22 Pages

---

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	--

### MAINTENANCE GARAGE BUILDING

### MAINTENANCE GARAGE BUILDING

OFFICE

SUSPENDED CEILING TILE

260 SF

**P:** Less Than 5%

**W:** <10% Stains or Flaking

### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/06/2005	2'X4' Suspended Ceiling Tile. This Material is in GOOD condition as of this date.
05/11/2009	Damage Observed. <5% Physical Damage in the form of minor cuts and holes. <10% Water Damage due to 3 Tiles with water stains. Material Condition changed from GOOD to FAIR overall as of this date. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	Additional Damage Observed. 11 Tiles have Water Damage. No other changes as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

### MAINTENANCE GARAGE BUILDING

OFFICE, RESTROOM, SHOWER ROOM, AND STORAGE ROOM

SMOOTH WALL MISCELLANEOUS

2,650 SF

**P:** Less Than 5%

**W:** No Evidence

### DAMAGED FRIABLE SURFACING ACM

09/06/2005	Gypsum Wallboard System Walls and Ceilings. This Material is in GOOD condition as of this date.
------------	---

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<u>BUILDING NAME</u>	<u>LOCATION</u>	<u>MATERIAL TYPE</u>	<u>QTY</u> <u>(APPROXIMATE)</u>	<u>PHYSICAL DAMAGE (P:)</u> <u>WATER DAMAGE (W:)</u>
<u>RISK ASSESMENT CATEGORY</u>	<u>COMMENTS</u>			

03/03/2014	This Material is unchanged as of this date.			
08/28/2014	This Material is unchanged as of this date.			
03/18/2015	This Material is unchanged as of this date.			
09/16/2015	This Material is unchanged as of this date.			
03/17/2016	This Material is unchanged as of this date.			
09/09/2016	This Material is unchanged as of this date.			
03/27/2017	This Material is unchanged as of this date.			
08/25/2017	This Material is unchanged as of this date.			
02/12/2018	This Material is unchanged as of this date.			
08/06/2018	This Material is unchanged as of this date.			
02/04/2019	This Material is unchanged as of this date.			
08/12/2019	This Material is unchanged as of this date.			
08/26/2020	Damage Observed. <5% Physical Damage in the form of 4 LF of Cracks at South and West Walls of Storage Room. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.			
02/08/2021	This Material is unchanged as of this date.			
08/09/2021	This Material is unchanged as of this date.			
02/16/2022	This Material is unchanged as of this date.			

### **MAINTENANCE GARAGE BUILDING**

OFFICE, RESTROOM, SHOWER ROOM, AND STORAGE ROOM

SMOOTH WALL SURFACING

2,650 SF

**P:** Less Than 5%

**W:** No Evidence

### DAMAGED FRIABLE SURFACING ACM

04/18/2006	Skim Coat for Gypsum Wallboard System Walls and Ceilings. This Material is in GOOD condition as of this date. This Material is in GOOD condition as of this date.			
03/03/2014	This Material is unchanged as of this date.			
08/28/2014	This Material is unchanged as of this date.			
03/18/2015	This Material is unchanged as of this date.			
09/16/2015	This Material is unchanged as of this date.			
03/17/2016	This Material is unchanged as of this date.			
09/09/2016	This Material is unchanged as of this date.			

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)
				03/27/2017		This Material is unchanged as of this date.
				08/25/2017		This Material is unchanged as of this date.
				02/12/2018		This Material is unchanged as of this date.
				08/06/2018		This Material is unchanged as of this date.
				02/04/2019		This Material is unchanged as of this date.
				08/12/2019		This Material is unchanged as of this date.
				08/26/2020		Damage Observed. <5% Physical Damage in the form of 4 LF of Cracks at South and West Walls of Storage Room. Material condition changed from GOOD to FAIR overall. Friability updated from Non-Friable to Friable. No other changes as of this date.
				02/08/2021		This Material is unchanged as of this date.
				08/09/2021		This Material is unchanged as of this date.
				02/16/2022		This Material is unchanged as of this date.



# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	--

### MAINTENANCE SHOPS OFFICE PORTABLE BUILDING

### MAINTENANCE SHOPS OFFICE PORTABLE BUILDING

OFFICE PORTABLE

BASEBOARD MASTIC

265 LF

**P:** Less Than 10%

**W:** No Evidence

### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/06/2005	Mastic/Adhesive for 3" Cream Baseboard. This Material is in GOOD condition as of this date.
11/05/2007	Material Re-Assessed. Damage Observed <5% Physical Damage - due to 5 LF loose in Front Office. Material condition changed from GOOD to FAIR overall. No other changes as of this date.
11/28/2011	Additional Damage observed - in the form of approximately 20 LF is loose in 1 Office. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	Material Re-Assessed. Additional 40 LF of Damage found. Baseboard is missing and Mastic/Adhesive is exposed. No other changes as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	Additional Damage Observed. 8 LF Loose Mastic Exposed in Office 1. 8 LF Loose and 4 LF Missing in Office 2. No other changes as of this date.
08/25/2017	Additional Damage Observed. Front Office now has 25 LF of Baseboard Missing. Mastic/Adhesive is Exposed. No other changes as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESSMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
---------------	----------	---------------	--------------------------	----------	----------------------	--

### MAINTENANCE SHOPS OFFICE PORTABLE BUILDING

OFFICE PORTABLE

PRESSED WOOD WALL PANEL

2,660 SF

**P:** No Visible Damage

**W:** <10% Stains or Flaking

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

10/13/2008	4'x10' Pressed Wood Wall Panel with Vinyl Wall Cover. This Material is in GOOD condition as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	Damage Observed. <10% Water Damage - in the form of 16 SF of Loose and Peeling Vinyl. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

### MAINTENANCE SHOPS OFFICE PORTABLE BUILDING

OFFICE PORTABLE

PRESSED WOOD WALL PANEL MASTIC

2,660 SF

**P:** No Visible Damage

**W:** <10% Stains or Flaking

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

10/13/2008	Mastic/Adhesive for 4'x10' Pressed Wood Wall Panel with Vinyl Wall Cover. This Material is in GOOD condition as of this date.
03/03/2014	This Material is unchanged as of this date.

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	---

08/28/2014	This Material is unchanged as of this date.					
03/18/2015	This Material is unchanged as of this date.					
09/16/2015	This Material is unchanged as of this date.					
03/17/2016	This Material is unchanged as of this date.					
09/09/2016	This Material is unchanged as of this date.					
03/27/2017	Damage Observed. <10% Water Damage - in the form of 16 SF of Loose and Peeling Vinyl. Material condition changed from GOOD to FAIR overall. Friability changed from Non to Low. No other changes as of this date.					
08/25/2017	This Material is unchanged as of this date.					
02/12/2018	This Material is unchanged as of this date.					
08/06/2018	This Material is unchanged as of this date.					
02/04/2019	This Material is unchanged as of this date.					
08/12/2019	This Material is unchanged as of this date.					
08/26/2020	This Material is unchanged as of this date.					
02/08/2021	This Material is unchanged as of this date.					
02/16/2022	This Material is unchanged as of this date.					

### MAINTENANCE SHOPS OFFICE PORTABLE BUILDING

#### OFFICE PORTABLE

SUSPENDEED CEILING TILE

1,600 SF

**P:** Less Than 5%

**W:** <10% Stains or Flaking

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/06/2005	2'X4' Suspended Ceiling Tile. This Material is in GOOD condition as of this date.					
11/28/2011	Damage Observed. <10% Water Damage - in the form of 2 Tiles are Water Damaged in Office; <5% Physical Damage - in the form of 1 Tile is broken. Material condition changed from GOOD to FAIR overall. No other changes as of this date.					
03/03/2014	This Material is unchanged as of this date.					
08/28/2014	This Material is unchanged as of this date.					
03/18/2015	This Material is unchanged as of this date.					
09/16/2015	This Material is unchanged as of this date.					
03/17/2016	This Material is unchanged as of this date.					
09/09/2016	Additional Damage observed. 1 Tile is missing in Office. No other changes as of this date.					
03/27/2017	This Material is unchanged as of this date.					

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	--

08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

### MAINTENANCE SHOPS OFFICE PORTABLE BUILDING

#### OFFICE PORTABLE

VINYL WALL COVER

2,660 SF

**P:** Less Than 5%

**W:** No Evidence

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/06/2005	4'X10' Vinyl Cover on Pressed Wood Wall Panels. This Material is in GOOD condition as of this date.
11/28/2011	Damage Observed. <5% Physical Damage - in the form of approximately 1 SF is Damaged. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	Damage Observed. <10% Water Damage - in the form of 16 SF of Loose and Peeling Vinyl. Material condition changed from GOOD to FAIR overall. Friability changed from Non to Low. No other changes as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

**BUILDING NAME****LOCATION****MATERIAL TYPE****RISK ASSESMENT CATEGORY****COMMENTS****QTY  
(APPROXIMATE)****PHYSICAL DAMAGE (P:)  
WATER DAMAGE (W:)**

08/12/2019 This Material is unchanged as of this date.  
08/26/2020 This Material is unchanged as of this date.  
02/08/2021 This Material is unchanged as of this date.  
08/09/2021 This Material is unchanged as of this date.  
02/16/2022 This Material is unchanged as of this date.

**MAINTENANCE SHOPS OFFICE PORTABLE BUILDING****OFFICE PORTABLE**

VINYL WALL COVER MASTIC

2,660 SF

**P:** Less Than 5%  
**W:** No EvidenceDAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

10/13/2008 Mastic/Adhesive for Vinyl Wall Cover, (on 4'x10' Pressed Wood Wall Panel). This Material is in GOOD condition as of this date.  
11/28/2011 Damage Observed. <5% Physical Damage - in the form of approximately 1 SF is Damaged. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.  
03/03/2014 This Material is unchanged as of this date.  
08/28/2014 This Material is unchanged as of this date.  
03/18/2015 This Material is unchanged as of this date.  
09/16/2015 This Material is unchanged as of this date.  
03/17/2016 This Material is unchanged as of this date.  
09/09/2016 This Material is unchanged as of this date.  
03/27/2017 This Material is unchanged as of this date.  
08/25/2017 This Material is unchanged as of this date.  
02/12/2018 This Material is unchanged as of this date.  
08/06/2018 This Material is unchanged as of this date.  
02/04/2019 This Material is unchanged as of this date.  
08/12/2019 This Material is unchanged as of this date.  
08/26/2020 This Material is unchanged as of this date.  
02/08/2021 This Material is unchanged as of this date.  
08/09/2021 This Material is unchanged as of this date.  
02/16/2022 This Material is unchanged as of this date.

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	--

### MAINTENANCE SHOPS OFFICE PORTABLE BUILDING

OFFICES, LOUNGE ROOM AND LOCKSMITH OFFICE

CARPET MASTIC

1,600 SF

**P:** Less Than 5%

**W:** <10% Stains or Flaking

### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

04/18/2006	Mastic/Adhesive for Green Carpet. This Material is in GOOD condition as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	Damage Observed. Offices have Approximately 1 SF of Carpet Damaged exposing Mastic/Adhesive. Material Condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	Additional Damage Observed. Water Damages and Stains found in all of the Rooms. No other changes as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	--

### MENTOR'S HOUSE

#### MENTOR'S HOUSE

DAYCARE ROOM AND ENTRY TO KITCHEN

CEILING MASTIC

500 SF

**P:** Less Than 5%

**W:** No Evidence

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/06/2005	Mastic/Adhesive for 1'X1' Ceiling Tile. This Material is in GOOD condition as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	Damage Observed. <5% Physically Damage - in the form of 4 Tiles have small Cracks and Chips in them. Material condition changed from GOOD to FAIR overall. Friability changed from Non to Low. No other changes as of this date.
08/06/2018	Material Re-assessed. Partial Repairs made some Tiles have been Patched with Mud. Remains in FAIR condition as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

### MENTOR'S HOUSE

DAYCARE ROOM AND ENTRY TO KITCHEN

CEILING TILE

500 SF

**P:** Less Than 5%

**W:** No Evidence

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/06/2005	1'X1' Ceiling Tile. This Material is in GOOD condition as of this date.
------------	---

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	--

03/03/2014	This Material is unchanged as of this date.					
08/28/2014	This Material is unchanged as of this date.					
03/18/2015	This Material is unchanged as of this date.					
09/16/2015	This Material is unchanged as of this date.					
03/17/2016	This Material is unchanged as of this date.					
09/09/2016	This Material is unchanged as of this date.					
03/27/2017	This Material is unchanged as of this date.					
08/25/2017	This Material is unchanged as of this date.					
02/12/2018	Damage Observed. <5% Physically Damage - in the form of 4 Tiles have small Cracks and Chips in them. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.					
08/06/2018	Material Re-assessed. Partial Repairs made some Tiles have been Patched with Mud. Remains in FAIR condition as of this date.					
02/04/2019	This Material is unchanged as of this date.					
08/12/2019	This Material is unchanged as of this date.					
08/26/2020	Additional Damage Observed. <5% Physical Damage in the form of 3 Loose Tiles at Enry into Kitchen. Material remains in FAIR condition overall. No other changes as of this date.					
02/08/2021	This Material is unchanged as of this date.					
08/09/2021	This Material is unchanged as of this date.					
02/16/2022	This Material is unchanged as of this date.					

### MENTOR'S HOUSE

DAYCARE ROOM (IN SE CORNER OF BUILDING)

CARPET MASTIC

240 SF

**P:** No Visible Damage

**W:** <10% Stains or Flaking

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

04/14/2008	Mastic/Adhesive for Brown/Grey Carpet. This Material is in GOOD condition as of this date.					
03/03/2014	This Material is unchanged as of this date.					
08/28/2014	This Material is unchanged as of this date.					
03/18/2015	This Material is unchanged as of this date.					
09/16/2015	This Material is unchanged as of this date.					
03/17/2016	This Material is unchanged as of this date.					
09/09/2016	This Material is unchanged as of this date.					



# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	--

03/27/2017	This Material is unchanged as of this date.					
08/25/2017	This Material is unchanged as of this date.					
02/12/2018	Damage Observed. <10% Water Damage - in the form of a 12 SF Water Stain by the Desk. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.					
08/06/2018	This Material is unchanged as of this date.					
02/04/2019	This Material is unchanged as of this date.					
08/12/2019	This Material is unchanged as of this date.					
08/26/2020	Additional Damage Observed. <5% Physical Damage in the form of 3 Loose Tiles at Enry into Kitchen. Material remains in FAIR condition overall. No other changes as of this date.					
02/08/2021	This Material is unchanged as of this date.					
08/09/2021	This Material is unchanged as of this date.					
02/16/2022	This Material is unchanged as of this date.					

### MENTOR'S HOUSE

#### ENTIRE BUILDING

SMOOTH WALL MISCELLANEOUS	6,400 SF	<b>P:</b> Less Than 5% <b>W:</b> No Evidence
---------------------------	----------	---

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/06/2005	Gypsum Wallboard System Walls, (with Vinyl Wall Cover in some areas). This Material is in GOOD condition as of this date.					
04/18/2006	This Material is also on ceilings. No other changes as of this date.					
03/03/2014	This Material is unchanged as of this date.					
08/28/2014	Damage observed. Physical Damage <5% in the of form of a crack in the Hallway. Material condition changed from GOOD to FAIR overall. No other changes as of this date.					
03/18/2015	This Material is unchanged as of this date.					
09/16/2015	This Material is unchanged as of this date.					
03/17/2016	Additional Damage observed. 6 LF is cracked in Kitchen. No other changes as of this date.					
09/09/2016	This Material is unchanged as of this date.					
03/27/2017	Additional Damage Observed. 12 LF is Cracked in Kitchen. No other changes as of this date.					
08/25/2017	This Material is unchanged as of this date.					
02/12/2018	Additional Damage Observed. 12 LF Crack in Kithchen is no 1/4" Split to it. No other changes as of this date.					

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
	MATERIAL TYPE		
	RISK ASSESMENT CATEGORY		
COMMENTS			

08/06/2018	Material Re-assessed. 12 LF Crack in Kithchen has been Patched with Mud. 6 LF Crack now in the same spot. No other changes as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		
02/16/2022	This Material is unchanged as of this date.		

### MENTOR'S HOUSE

#### EXTERIOR WINDOWS

##### CAULKING

**P:** Less Than 5%  
**W:** <10% Stains or Flaking

400 LF

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/06/2005	Window Caulking. Damaged in various areas. This Material is in FAIR condition as of this date.		
05/11/2009	Damage Observed. <10% Water Damage due to moisture and heat degradation on various surfaces. Material remains in FAIR condition overall as of this date.		
03/03/2014	This Material is unchanged as of this date.		
08/28/2014	This Material is unchanged as of this date.		
03/18/2015	This Material is unchanged as of this date.		
09/16/2015	This Material is unchanged as of this date.		
03/17/2016	This Material is unchanged as of this date.		
09/09/2016	This Material is unchanged as of this date.		
03/27/2017	This Material is unchanged as of this date.		
08/25/2017	This Material is unchanged as of this date.		
02/12/2018	This Material is unchanged as of this date.		
08/06/2018	This Material is unchanged as of this date.		
02/04/2019	This Material is unchanged as of this date.		
08/12/2019	This Material is unchanged as of this date.		
08/26/2020	This Material is unchanged as of this date.		
02/08/2021	This Material is unchanged as of this date.		
08/09/2021	This Material is unchanged as of this date.		

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P): WATER DAMAGE (W):
---------------	----------	---------------	-------------------------	----------	----------------------	---

---

02/16/2022      This Material is unchanged as of this date.

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	---

### PORTABLE

### PORTABLE

#### PORTABLES

VINYL FLOOR TILE

480 SF

**P:** Less Than 5%

**W:** No Evidence

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

07/30/2010	12"x12" Beige and Cream Vinyl Floor Tile. This Material is in GOOD condition as of this date.
11/28/2011	Damage Observed. <5% Physical Damage - in the form of a hairline crack observed on Tile. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	Additional Damage Observed. Several Tiles appear to have Cracks on them. No other changes as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	--

### PORTABLE

#### PORTABLES

VINYL FLOOR TILE MASTIC

480 SF

**P:** Less Than 5%

**W:** No Evidence

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

07/30/2010	Mastic/Adhesive for 12"x12" Beige and Cream Vinyl Floor Tile. This Material is in GOOD condition as of this date.
11/28/2011	Damage Observed. <5% Physical Damage - in the form of a hairline crack observed on Tile. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	Additional Damage Observed. Several Tiles appear to have Cracks on them. No other changes as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	--

---

### STUDENT NUTRITION SERVICE

#### STUDENT NUTRITION SERVICE

STUDENT NUTRITION SERVICES - KITCHEN

PERMANENT BUILDING

7,480 SF

**P:** No Visible Damage

**W:** No Evidence

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

02/16/2022      New Permant Building. Material in GOOD condtion as of this date.

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	--

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

ASSISTANT DIRECTOR

VINYL FLOOR TILE

38 SF

**P:** Less Than 5%

**W:** No Evidence

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

11/28/2011	12"x12" Grey Vinyl Floor Tile. This Material is in GOOD condition as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	Damage Observed. <5% Physical Damage - in the form of 2 Tiles are Sliding and Exposing Mastic. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.
08/25/2017	Additional Damage Observed. 3 Tiles are now Cracked. No other changes as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

ASSISTANT DIRECTOR

VINYL FLOOR TILE MASTIC

38 SF

**P:** Less Than 5%

**W:** No Evidence

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

11/28/2011	Mastic/Adhesive for 12"x12" Grey Vinyl Floor Tile. This Material is in GOOD condition as of this date
03/03/2014	This Material is unchanged as of this date.

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESSMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)
---------------	----------	---------------	--------------------------	----------	----------------------	---

08/28/2014	This Material is unchanged as of this date.					
03/18/2015	This Material is unchanged as of this date.					
09/16/2015	This Material is unchanged as of this date.					
03/17/2016	This Material is unchanged as of this date.					
09/09/2016	This Material is unchanged as of this date.					
03/27/2017	Damage Observed. <5% Physical Damage - in the form of 2 Tiles are Sliding and Exposing Mastic. Material condition changed from GOOD to FAIR overall. Friability changed from Non-Friable to Friable. No other changes as of this date.					
08/25/2017	Additional Damage Observed. 3 Tiles are now Cracked. No other changes as of this date.					
02/12/2018	This Material is unchanged as of this date.					
08/06/2018	This Material is unchanged as of this date.					
02/04/2019	This Material is unchanged as of this date.					
08/12/2019	This Material is unchanged as of this date.					
08/26/2020	This Material is unchanged as of this date.					
02/08/2021	This Material is unchanged as of this date.					
08/09/2021	This Material is unchanged as of this date.					
02/16/2022	This Material is unchanged as of this date.					

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

CONFERENCE ROOM, STAFF'S LOUNGE ROOM, AND 2 STORAGE ROOM

SUSPENDED CEILING TILE

1,500 SF

**P:** Less Than 5%

**W:** <10% Stains or Flaking

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

05/12/2009	2'x4' Suspended Ceiling Tile, (with small uneven cuts and holes pattern). Damage Observed. <5% Physical Damage due to 3 missing Tiles. This Material is in FAIR condition as of this date.					
03/08/2010	Location Description changed from STAFF'S LOUNGE ROOM to CONFERENCE ROOM AND STAFF'S LOUNGE ROOM. Quantity changed from 500 SF to 1,500 SF. Additional Damage: <10% Water Damage in the form of 2 Tiles are Water Damaged. No other changes as of this date.					
08/30/2010	Location Description changed from CONFERENCE ROOM AND STAFF'S LOUNGE ROOM to CONFERENCE ROOM, STAFF'S LOUNGE ROOM, AND STORAGE ROOM. Additional Damage observed in Conference Room in the form of 3 Tiles are Water Damaged and 1 has a hole. No other changes as of this date.					
11/28/2011	Additional Damage observed - in the form of 3 more Tiles are Water Damaged, and 1 Tile is missing in Storage Room. No other changes as of this date.					
10/08/2012	Damage Re-Assessed and Conference Room now has a total of 4 Water Damaged Tiles. No other changes as of this date.					



# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)
09/23/2013				Material Re-Assessed. Conference Room now has Debris on Floor due to Water leaks from the Roof. No other changes as of this date.		
03/03/2014				Debris has been cleaned up. No other changes as of this date.		
08/28/2014				Material Re-Assessed. 2 Suspended Ceiling Tiles have Water Damage in the Office.		
03/18/2015				Additional Damage Observed. 3 Suspended Ceiling Tiles Water Damaged. No other change as of this date.		
09/16/2015				This Material is unchanged as of this date.		
03/17/2016				Additional Damage observed. 1 Tile is missing in Director's Office. No other changes as of this date.		
09/09/2016				Partial Repairs observed. Current Damage: 2 Tiles with Water Damage in the Storage Room, and 1 Tile with Water Damage in the Conference Room. No other changes as of this date.		
03/27/2017				Additional Damage Observed. 2 Tiles with Water Stains and Several Tiels Have been repainted in Staff Room. However 11 Tiles have Cracks and Cuts with Broken Edges in Staff Room. 5 Tiles have Water Damage while other have been Painted Over. Several Tiles have Cracks and Borken Edges in the Conferecnce Room. 2 Tiles have have Water Damage in the Storage by Front of the Building. 2 Tiles have Water Damage and 1 Tile Missing in the Storage by Rear of the Building. No other changes as of this date.		
08/25/2017				Additional Damage Observed. Conference Room now has 3 Tiles with Water Damage. No other changes as of this date.		
02/12/2018				This Material is unchanged as of this date.		
08/06/2018				This Material is unchanged as of this date.		
02/04/2019				This Material is unchanged as of this date.		
08/12/2019				This Material is unchanged as of this date.		
08/26/2020				This Material is unchanged as of this date.		
02/08/2021				This Material is unchanged as of this date.		
08/09/2021				This Material is unchanged as of this date.		
02/16/2022				This Material is unchanged as of this date.		

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

#### MAIN OFFICE

BASEBOARD MASTIC

1,400 LF

**P:** Less Than 5%

**W:** No Evidence

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/06/2005	Mastic/Adhesive for Baseboard. Approximately 15 LF exposed in Womens Restroom. This Material is in FAIR condition as of this date.
04/18/2006	Material redefined as 4" Black Baseboard (in Offices and Hallways) and 4" Blue Baseboard (in Conference Room). All Damages have been repaired. Friability changed from Non-Friable to Friable. No other changes as of this date.

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	--

03/08/2010				Material Re-Assessed. 4" Brown Baseboard was also observed in several Offices and Main Entry Office. No other changes as of this date.		
03/03/2014				This Material is unchanged as of this date.		
08/28/2014				This Material is unchanged as of this date.		
03/18/2015				New Material Installed. Men's and Women's Restrooms Floor and Baseboard now Covered with Vinyl Sheeting. Old Material is Possibly Behind. No other changes as of this date.		
09/16/2015				This Material is unchanged as of this date.		
03/17/2016				This Material is unchanged as of this date.		
09/09/2016				This Material is unchanged as of this date.		
03/27/2017				Damage Observed. <5% Physical Damage - in the form of 4" of Baseboard is missing in Main Office. Material condition changed from GOOD to FAIR overall. Friability changed from Non to Low. No other changes as of this date.		
08/25/2017				This Material is unchanged as of this date.		
02/12/2018				This Material is unchanged as of this date.		
08/06/2018				This Material is unchanged as of this date.		
02/04/2019				This Material is unchanged as of this date.		
08/12/2019				This Material is unchanged as of this date.		
08/26/2020				This Material is unchanged as of this date.		
02/08/2021				This Material is unchanged as of this date.		
08/09/2021				This Material is unchanged as of this date.		
02/16/2022				This Material is unchanged as of this date.		

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

#### MAIN OFFICE

SMOOTH WALL MISCELLANEOUS	5,100 SF	<b>P:</b> Less Than 5% <b>W:</b> <10% Stains or Flaking
---------------------------	----------	--

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/06/2005	Gypsum Wallboard System, Walls. Damages noticed. This Material is in FAIR condition as of this date.
05/11/2009	Additional Damages Observed. <5% Physical Damage in the form of small holes, gauging, and scratches on various surfaces. Material remains in FAIR condition overall as of this date.
11/28/2011	Additional Damage observed - in the form of Kitchen Ceiling has a crack, and approximately 1 SF of Material is peeling. Material condition changed from GOOD to FAIR. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	---

03/18/2015	This Material is unchanged as of this date.					
09/16/2015	This Material is unchanged as of this date.					
03/17/2016	This Material is unchanged as of this date.					
09/09/2016	This Material is unchanged as of this date.					
03/27/2017	This Material is unchanged as of this date.					
08/25/2017	This Material is unchanged as of this date.					
02/12/2018	This Material is unchanged as of this date.					
08/06/2018	This Material is unchanged as of this date.					
02/04/2019	This Material is unchanged as of this date.					
08/12/2019	This Material is unchanged as of this date.					
08/26/2020	Additional Damage Observed. <10% Water Damage in the form of 1 SF of Water Damage on Wall under Urinal in Mens Retroom in Dreivers Lounge. Material remains in FAIR condition overall. No other changes as of this date.					
02/08/2021	This Material is unchanged as of this date.					
08/09/2021	This Material is unchanged as of this date.					
02/16/2022	This Material is unchanged as of this date.					

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

#### MAIN OFFICE

SMOOTH WALL SURFACING	5,100 SF	<b>P:</b> Less Than 5% <b>W:</b> <10% Stains or Flaking
-----------------------	----------	--

#### DAMAGED FRIABLE SURFACING ACM

04/18/2006	Skim Coat for Gypsum Wallboard System, Walls. Various Damages noticed. This Material is in FAIR condition as of this date.					
05/11/2009	Additional Damages observed. <5% Physical Damage in the form of small holes, gauging, and scratches on various surfaces. Material remains in FAIR condition overall as of this date.					
11/28/2011	Additional Damage observed - in the form of Kitchen Ceiling has a crack, and approximately 1 SF of Material is peeling. Material condition changed from GOOD to FAIR. No other changes as of this date.					
03/03/2014	This Material is unchanged as of this date.					
08/28/2014	This Material is unchanged as of this date.					
03/18/2015	This Material is unchanged as of this date.					
09/16/2015	This Material is unchanged as of this date.					
03/17/2016	This Material is unchanged as of this date.					

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>	<b>LOCATION</b>	<b>MATERIAL TYPE</b>	<b>QTY (APPROXIMATE)</b>	<b>PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)</b>
<b>RISK ASSESMENT CATEGORY</b>	<b>COMMENTS</b>			

09/09/2016	This Material is unchanged as of this date.			
03/27/2017	This Material is unchanged as of this date.			
08/25/2017	This Material is unchanged as of this date.			
02/12/2018	This Material is unchanged as of this date.			
08/06/2018	This Material is unchanged as of this date.			
02/04/2019	This Material is unchanged as of this date.			
08/12/2019	This Material is unchanged as of this date.			
08/26/2020	Additional Damage Observed. <10% Water Damage in the form of 1 SF of Water Damage on Wall under Urinal in Mens Restroom in Drivers Lounge. Material remains in FAIR condition overall. No other changes as of this date.			
02/08/2021	This Material is unchanged as of this date.			
08/09/2021	This Material is unchanged as of this date.			
02/16/2022	This Material is unchanged as of this date.			

### **TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING**

#### MAIN OFFICE

SUSPENDED CEILING TILE

2,150 SF

**P:** Less Than 5%

**W:** <10% Stains or Flaking

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/06/2005	2'X4' Suspended Ceiling Tile. Several Tiles Damaged and Water stained. This Material is in FAIR condition as of this date.			
11/05/2007	Material Re-Assessed. Damage: <5% Physical Damage - 1 Tile in Telephone Panel Closet and 1 Tile in Mens Restroom; <10% Water Damage - 2 Tiles in Blueprint Office and 4 Tiles in Trainer Office. This Material is in FAIR condition overall as of this date.			
04/14/2008	Additional Damage noted: 1/2 Tile is missing in the Supply Storage Room as of this date.			
10/13/2008	Additional 3 Tiles missing at Lounge area. Also several Tiles Damaged at Hallway. No other changes as of this date.			
05/11/2009	Damages Re-Assessed. 1 Tile is missing above the Main Entry Door, (next to Receptionist Office). Physical damage is in various locations. Tiles damaged in Telephone Panel Closet has increased to 3 Tiles. Quantity changed from 2,650 SF to 3,150 SF. No change to damage in Hallway. Friability changed from Moderate to High to reflect these changes.			
09/03/2009	Repairs have been made in Main Lobby. Missing Tile has been replaced. Also, 3 Tiles Damaged at Hallway have been repaired. Telephone Panel Closet and Storage Closet are Water Damaged. No other changes as of this date.			

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

<b>BUILDING NAME</b>	<b>LOCATION</b>	<b>MATERIAL TYPE</b>	<b>RISK ASSESMENT CATEGORY</b>	<b>COMMENTS</b>	<b>QTY (APPROXIMATE)</b>	<b>PHYSICAL DAMAGE (P): WATER DAMAGE (W:)</b>
03/08/2010				Material Re-Assessed. Approx. 1,000 SF of 2'x4' Suspended Ceiling Tile is the same as Staff's Lounge. Quantity changed from 3,150 SF to 2,150 SF. Additional Damage in the form of 6 Tiles are cracked in Hallway and Main Office. Also, 2 Tiles are Water Damaged in Office, adjacent to Lounge Room. Material remains in FAIR condition. No other changes as of this date.		
11/28/2011				Additional Damage observed - in the form of Hallway has some Tiles broken. No other changes as of this date.		
10/08/2012				Additional Damage - in the form of 1 hole observed on Hallway Ceiling. Also, 2 additional Water Damaged Tiles observed in Telephone Panel Closet. No other changes as of this date.		
03/03/2014				This Material is unchanged as of this date.		
08/28/2014				Material Re-Assessed. Additional Water Damage Observed. No other changes as of this date.		
03/18/2015				This Material is unchanged as of this date.		
09/16/2015				This Material is unchanged as of this date.		
03/17/2016				Additional Damage observed and Partial Repairs made. Director's Office has 1 Tile with Water Damage. Missing Tile above Main Entry Door has been Replaced. No other changes as of this date.		
09/09/2016				Additional Damage observed. 2 Tiles with Water Damage in Trainer's Office. No other changes as of this date.		
03/27/2017				Additional Damage Observed. 4 Tiles with Water Damage and Several other have broken edges and are Cracked in the Director's Office. 4 Water Damage Tiles, 7 other Tiles have Cracks, in the Project Manager's Office. 4 Tiles with Cracked and Chipped Tiles in the Executive Assistant Office. No other changes as of this date.		
08/25/2017				Additional Damage Observed. Trainer's Office now has 3 Tiles. No other changes as of this date.		
02/12/2018				This Material is unchanged as of this date.		
08/06/2018				This Material is unchanged as of this date.		
02/04/2019				This Material is unchanged as of this date.		
08/12/2019				This Material is unchanged as of this date.		
08/26/2020				This Material is unchanged as of this date.		
02/08/2021				This Material is unchanged as of this date.		
08/09/2021				This Material is unchanged as of this date.		
02/16/2022				This Material is unchanged as of this date.		

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
RISK ASSESMENT CATEGORY				
COMMENTS				

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

MAIN OFFICES, HALLWAY, CONFERENCE ROOM, STORAGE ROOM AND LOUNGE ROOM

CARPET MASTIC	3,300 SF	<b>P:</b> Less Than 5% <b>W:</b> <10% Stains or Flaking
---------------	----------	--

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

04/18/2006	Mastic/Adhesive for Carpets (Approximately 80% Blue and 20% Mix of Red, Brown and Grey Colors). This Material is in FAIR condition as of this date.
05/11/2009	Damage Observed. <5% Physical Damage in the form of the Carpet has been Damaged due to several separations observed in locations of seams. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	Additional Damage Observed. Storage Room by Rear of Building there is Water Damage in the form of Stains and Mold, still damp. 20 LF of Blue Carpet in the Staff Lounge is loose. No other changes as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	--

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

MAIN OFFICES, RESTROOM, HALLWAY, CONFERENCE ROOM

VINYL WALL COVER

7,800 SF

**P:** Less Than 5%

**W:** No Evidence

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

10/13/2008	Vinyl Wall Cover, (on Pressed Wood Wall Panel). Damage in the form of cuts and holes. This Material is in FAIR condition as of this date.
09/03/2009	This Material is unchanged as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	Additional Damage Observed. 20 SF of Loose Vinyl and Wall Boards in the Conference Room. No other changes as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	Additional Damage Observed. 1 Panel with Holes in it and 1 Panle has Scrapes and Cuts in Project Manager's Office. No other changes as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

MAIN OFFICES, RESTROOM, HALLWAY, CONFERENCE ROOM

VINYL WALL COVER MASTIC

7,800 SF

**P:** Less Than 5%

**W:** No Evidence

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

10/13/2008	Mastic/Adhesive for Vinyl Wall Cover, (on Pressed Wood Wall Panel). Damage in the form of cuts and holes. This Material is in FAIR condition as of this date.
------------	---

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	--

09/03/2009				Material remains in <5% Physical Damage. This Material is unchanged as of this date.		
03/03/2014				This Material is unchanged as of this date.		
08/28/2014				This Material is unchanged as of this date.		
03/18/2015				This Material is unchanged as of this date.		
09/16/2015				This Material is unchanged as of this date.		
03/17/2016				This Material is unchanged as of this date.		
09/09/2016				This Material is unchanged as of this date.		
03/27/2017				Additional Damage Observed. 20 SF of Loose Vinyl and Wall Boards in the Conference Room. No other changes as of this date.		
08/25/2017				This Material is unchanged as of this date.		
02/12/2018				This Material is unchanged as of this date.		
08/06/2018				This Material is unchanged as of this date.		
02/04/2019				This Material is unchanged as of this date.		
08/12/2019				This Material is unchanged as of this date.		
08/26/2020				This Material is unchanged as of this date.		
02/08/2021				Additional Damage Observed. 1 Panel with Holes in it and 1 Panle has Scrapes and Cuts in Project Manager's Office. No other changes as of this date.		
08/09/2021				This Material is unchanged as of this date.		
02/16/2022				This Material is unchanged as of this date.		

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

MAIN OFFICES, RESTROOMS, HALLWAY CONFERENCE ROOM

PRESSED WOOD WALL PANEL

7,800 SF

**P:** Less Than 5%

**W:** No Evidence

### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/06/2005				Pressed wood wall panels. Damaged in forms of cuts and holes in Receptionist Area. This Material is in FAIR condition as of this date.		
10/13/2008				Material Location changed from MAIN OFFICE to MAIN OFFICES, RESTROOMS, HALLWAY CONFERENCE ROOM. No other changes as of this date.		
09/03/2009				Material remains in <5% Physical Damage. No changes as of this date.		
03/03/2014				This Material is unchanged as of this date.		
08/28/2014				This Material is unchanged as of this date.		
03/18/2015				This Material is unchanged as of this date.		



# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESSMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P:) WATER DAMAGE (W:)
---------------	----------	---------------	--------------------------	----------	----------------------	---

09/16/2015	This Material is unchanged as of this date.					
03/17/2016	This Material is unchanged as of this date.					
09/09/2016	This Material is unchanged as of this date.					
03/27/2017	Additional Damage Observed. 20 SF of Loose Vinyl and Wall Boards in the Conference Room. No other changes as of this date.					
08/25/2017	This Material is unchanged as of this date.					
02/12/2018	This Material is unchanged as of this date.					
08/06/2018	This Material is unchanged as of this date.					
02/04/2019	This Material is unchanged as of this date.					
08/12/2019	This Material is unchanged as of this date.					
08/26/2020	This Material is unchanged as of this date.					
02/08/2021	This Material is unchanged as of this date.					
08/09/2021	This Material is unchanged as of this date.					
02/16/2022	This Material is unchanged as of this date.					

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

MAIN OFFICES, RESTROOMS, HALLWAY CONFERENCE ROOM

PRESSED WOOD WALL PANEL MASTIC	7,800 SF	<b>P:</b> Less Than 5% <b>W:</b> No Evidence
--------------------------------	----------	---

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/06/2005	Mastic/Adhesive for Pressed Wood Wall Panels. Damaged in forms of cuts and holes in Receptionist Area. This Material is in FAIR condition as of this date.					
10/13/2008	Material Location changed from MAIN OFFICE to MAIN OFFICES, RESTROOMS, HALLWAY CONFERENCE ROOM. No other changes as of this date.					
09/03/2009	Material remains in <5% Physical Damage. No changes as of this date.					
03/03/2014	This Material is unchanged as of this date.					
08/28/2014	This Material is unchanged as of this date.					
03/18/2015	This Material is unchanged as of this date.					
09/16/2015	This Material is unchanged as of this date.					
03/17/2016	This Material is unchanged as of this date.					
09/09/2016	This Material is unchanged as of this date.					
03/27/2017	Additional Damage Observed. 20 SF of Loose Vinyl and Wall Boards in the Conference Room. No other changes as of this date.					

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	--

08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

### TRANSPORTATION AND MAINTENANCE DEPARTMENT OFFICE BUILDING

PLENUM

WALL INSULATION

2,500 SF

**P:** Less Than 10%

**W:** <10% Stains or Flaking

### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/06/2005	Spray-On Foam Insulation. Material is loose and Water Damaged in several locations. This Material is in FAIR condition as of this date.
09/03/2009	Material remains in <5% Physical Damage and <10% Water Damage. This Material is unchanged as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P): WATER DAMAGE (W):
---------------	----------	---------------	-------------------------	----------	----------------------	---

---

08/26/2020	This Material is unchanged as of this date.				
02/08/2021	This Material is unchanged as of this date.				
08/09/2021	This Material is unchanged as of this date.				
02/16/2022	This Material is unchanged as of this date.				

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	--

### WAREHOUSE BUILDING

### WAREHOUSE BUILDING

ALL OFFICES, RESTROOMS, CARPENTERS SHOP, AND LOUNGE ROOM

BASEBOARD MASTIC

470 LF

**P:** Less Than 50% No Debris

**W:** No Evidence

### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/06/2005	Mastic/Adhesive for 4" Black and brown Baseboards. Material is exposed in Carpenters Shop and Restroom. This Material is in FAIR condition as of this date.
04/18/2006	Approximately 120 LF is exposed in Shop and Main Office. Condition changed from FAIR to POOR. Recommendation changed to reflect this fact. No other changes as of this date.
05/11/2009	Damages Re-Assessed. Physical Damages remains at <50%. This Material is unchanged as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	Additional Damage Observed. <5% Physical Damage in the form of 2 LF of Missing Baseboard with Brown Mastic exposed in Restroom. Material remains in FAIR condition overall. No other changes as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	--

### WAREHOUSE BUILDING

ALL OFFICES, RESTROOMS, SHOPS, LOUNGE ROOM, AND WAREHOUSE STORAGE ROOM

VINYL FLOOR TILE

2,310 SF

**P:** Less Than 50% No Debris  
**W:** No Evidence

### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/06/2005	12"X12" Multi-Color Vinyl Floor Tile. Broken and missing in various locations. This Material is in FAIR condition as of this date.
04/14/2008	50 SF Removed in the Restroom. Quantity changed from 2,360 SF to 2,310 SF. This Material condition is unchanged as of this date.
05/11/2009	Damages Re-Assessed. Physical Damage has increased to <50% and approx. 100 SF is damaged due to oil spills and degradation in Wood Shop (Warehouse Storage Room) by the South Wall. Material condition changed from FAIR to POOR. Recommendation changed to reflect this change.
04/13/2012	Location Description changed from ALL OFFICES, RESTROOMS, SHOPS, AND LOUNGE ROOM to ALL OFFICES, RESTROOMS, SHOPS, LOUNGE ROOM, AND WAREHOUSE STORAGE ROOM. No other changes as of this date.
10/08/2012	Additional Damage - in the form of 4 Tiles are becoming loose in Wood Shop. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	Material Re-Assessed. Warehouse Storage Room has Several Tiles Broken and Missing. Friability changed from Moderate to Low. No other changes as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	--

### WAREHOUSE BUILDING

ALL OFFICES, RESTROOMS, SHOPS, LOUNGE ROOM, AND WAREHOUSE STORAGE ROOM

VINYL FLOOR TILE MASTIC

2,360 SF

**P:** Less Than 50% No Debris

**W:** No Evidence

### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/06/2005	Mastic/Adhesive for 12"X12" Multi-Color Vinyl Floor Tile. Material is exposed in broken and missing Tile locations. This Material is in FAIR condition as of this date.
04/14/2008	50 SF is exposed in the Restroom. This Material condition is unchanged as of this date.
05/11/2009	Damages Re-Assessed. Physical Damage has increased to <50% and approx. 100 SF is Damaged due to oil spills and degradation in Wood Shop (Warehouse Storage Room) by the South Wall. Material condition changed from FAIR to POOR. Friability changed from Low to Moderate. Recommendation changed to reflect this change. 50 SF that was exposed in Restroom has been repaired. Material has been replaced with Off-White 12"x12".
04/13/2012	Location Description changed from ALL OFFICES, RESTROOMS, SHOPS, AND LOUNGE ROOM to ALL OFFICES, RESTROOMS, SHOPS, LOUNGE ROOM, AND WAREHOUSE STORAGE ROOM. No other changes as of this date.
10/08/2012	Additional Damage - in the form of 4 Tiles are becoming loose in Wood Shop. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	Material Re-Assessed. Warehouse Storage Room has Several Tiles Broken and Missing. Friability changed from Moderate to Low. No other changes as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	--

02/16/2022 This Material is unchanged as of this date.

### WAREHOUSE BUILDING

CARPENTERS SHOP, AND RESTROOM

CEILING MASTIC

1,000 SF

**P:** Less Than 50% No Debris  
**W:** <10% Stains or Flaking

### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

03/05/2007	Mastic/Adhesive for 1'x1' Ceiling Tile. Damage: <5% Physical Damage - in the form of approximately 10 SF missing in Entry Area; <10% Water Damage - in the form of loose and falling Ceiling Tiles. No other changes as of this date.
05/11/2009	Material condition is FAIR overall. This Material is unchanged as of this date.
09/03/2009	Material Re-Assessed. Physical Damage is <50% and remains in FAIR condition overall as of this date.
10/08/2012	Material condition Re-Assessed and Wood Shop has 4 Tiles becoming loose. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	Carpenter's Shop has 300 Ceiling Tiles Missing and Mastic/Adhesive is exposed. It is now Covered with Plywood. No other changes as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	Additional Damage Observed. Storage Room has 100 SF of Water Damage and 6 Tiles are Missing. 40 Sf of Water Damage and 25 loose Tiles in the Shop. No other changes as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P): WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	---

### WAREHOUSE BUILDING

CARPENTERS SHOP, AND RESTROOM

CEILING TILE

1,000 SF

**P:** Less Than 5%

**W:** >10% Evident

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/06/2005	1'X1' Nailed-On Ceiling Tile. Material is damaged in the form of holes and cuts. This Material is in FAIR condition as of this date.
04/18/2006	Damage Observed. >10% Water Damaged. Friability changed from Moderate to High. Condition changed from FAIR to POOR. Recommendation changed to reflect this fact. No other changes as of this date.
03/05/2007	Material Description changed from ' 1'x1' Nailed-on Ceiling Tile. ' to '1'x1' Ceiling Tile, (Glued-on). Mastic/Adhesive entry added for this Material. Damage reassessed. Damage: <5% Physical Damage - in the form of approximately 10 SF missing in Entry Area; <10% Water Damage - in the form of loose and falling Ceiling Tiles. Friability changed to High. No other changes as of this date.
09/03/2009	Damage Re-Assessed. Physical Damage has changed to <50% due to scratches and gouging observed. Water Damage remains <10% and in POOR condition as of this date.
10/08/2012	Material condition Re-Assessed and Wood Shop has 4 Tiles becoming loose. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	Carpenter's Shop has 300 Ceiling Tiles Missing and Mastic/Adhesive is exposed. It is now Covered with Plywood. Friability changed from Low to Moderate. No other changes as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.



# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	--

### WAREHOUSE BUILDING

WAREHOUSE RESTROOMS, LOUNGE ROOM, OFFICES, AND SHOPS

SMOOTH WALL MISCELLANEOUS

6,620 SF

**P:** Less Than 5%

**W:** <10% Stains or Flaking

#### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/06/2005	Gypsum Wallboard System Walls and Ceilings. This Material is in GOOD condition as of this date.
03/05/2007	Damage Re-Assessed. Damage Observed. <5% Physical Damage - in the form of small cuts and holes in Restrooms and Entry Hall. Material Condition changed from GOOD to FAIR. No other changes as of this date.
04/14/2008	Water Damage (<10% overall) under the 1'x1' Ceiling Tiles and 5 SF Damaged or missing on the Wall next to the Entry Door. This Material is in FAIR condition as of this date.
09/03/2009	Material remains in <5% Physical Damage and <10% Water Damage. This Material is unchanged as of this date.
09/23/2013	Friability changed from Moderate to Low. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	No Access to Lounge Room as of this date. Other locations were Accessable. No other changes as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	Additional Damage Observed. <5% Physical Damage in the form of 10 SF of Cracks and Peeling on Ceiling in Woodshop Restroom. Material remains in FAIR condition overall. No other changes as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	--

### WAREHOUSE BUILDING

WAREHOUSE RESTROOMS, LOUNGE ROOM, OFFICES, AND SHOPS

SMOOTH WALL SURFACING

6,620 SF

**P:** Less Than 5%

**W:** <10% Stains or Flaking

#### DAMAGED FRIABLE SURFACING ACM

04/18/2006	Skim Coat for Gypsum Wallboard System Walls and Ceilings. This Material is in GOOD condition as of this date.
03/05/2007	Damage Re-Assessed. Damage: <5% Physical Damage - in the form of small cuts and holes in Restrooms and Entry Hall. Material Condition changed from GOOD to FAIR. No other changes as of this date.
04/14/2008	Water Damage (<10% overall) under the 1'x1' Ceiling Tiles and 5 SF damaged or missing on the Wall next to the Entry Door. This Material is in FAIR condition as of this date.
09/03/2009	Material remains in <5% Physical Damage and <10% Water Damage. This Material is unchanged as of this date.
09/23/2013	Friability changed from Moderate to Low. No other changes as of this date.
03/03/2014	Friability changed from Low to Moderate. No other changes as of this date.
08/28/2014	This Material is unchanged as of this date.
03/18/2015	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	No Access to Lounge Room as of this date. Other locations were Accessable. No other changes as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	Additional Damage Observed. <5% Physical Damage in the form of 10 SF of Cracks and Peeling on Ceiling in Woodshop Restroom. Material remains in FAIR condition overall. No other changes as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

BUILDING NAME	LOCATION	MATERIAL TYPE	RISK ASSESMENT CATEGORY	COMMENTS	QTY (APPROXIMATE)	PHYSICAL DAMAGE (P: WATER DAMAGE (W:)
---------------	----------	---------------	-------------------------	----------	----------------------	--

### WELDING SHOP BUILDING

### WELDING SHOP BUILDING

SIGNS / TOOLS / PARTS SHOP

SMOOTH WALL MISCELLANEOUS

650 SF

**P:** Less Than 50% No Debris  
**W:** <10% Stains or Flaking

### DAMAGED OR SIGNIFICANTLY DAMAGED FRIABLE MISCELLANEOUS ACM

09/06/2005	Gypsum Wallboard System Walls and Ceilings. This Material is in GOOD condition as of this date.
04/18/2006	Material Re-Assessed. Damage: <10% Physical Damage - noted in forms of holes and cuts. This Material is in FAIR condition overall as of this date.
05/11/2009	Damages Re-Assessed. Physical Damages changed to <50% due to deterioration of Material in the form of cuts, holes, and gauging. <10% Water Damage in the form of degradation. Material condition changed from FAIR to POOR overall. Recommendation changed to reflect this change. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is unchanged as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

# DAMAGE REPORT FOR

## BUESD MAINTENANCE AND TRANSPORTATION YARD

---

<b>BUILDING NAME</b>	<b>LOCATION</b>	<b>QTY (APPROXIMATE)</b>	<b>PHYSICAL DAMAGE (P: WATER DAMAGE (W:)</b>
<b>MATERIAL TYPE</b>	<b>RISK ASSESMENT CATEGORY</b>		
<b>COMMENTS</b>			

---

### WELDING SHOP BUILDING

SIGNS / TOOLS / PARTS SHOP

SMOOTH WALL SURFACING

650 SF

**P:** Less Than 50% No Debris

**W:** <10% Stains or Flaking

#### DAMAGED FRIABLE SURFACING ACM


04/18/2006	Skim Coat for Gypsum Wallboard System Walls and Ceilings. <10% Physical Damages noted in forms of holes and cuts. This Material is in FAIR condition as of this date.
05/11/2009	Damages Re-Assessed. Physical Damages changed to <50% due to deterioration of Material in the form of cuts, holes, and gauging. <10% Water Damage in the form of degradation. Material condition changed from FAIR to POOR overall. Recommendation changed to reflect this change.
09/23/2013	This Material changed from POOR condition to FAIR condition as of this date. No other changes as of this date.
03/03/2014	This Material is unchanged as of this date.
08/28/2014	This Material is in POOR condition as of this date.
09/16/2015	This Material is unchanged as of this date.
03/17/2016	This Material is unchanged as of this date.
09/09/2016	This Material is unchanged as of this date.
03/27/2017	This Material is unchanged as of this date.
08/25/2017	This Material is unchanged as of this date.
02/12/2018	This Material is unchanged as of this date.
08/06/2018	This Material is unchanged as of this date.
02/04/2019	This Material is unchanged as of this date.
08/12/2019	This Material is unchanged as of this date.
08/26/2020	This Material is unchanged as of this date.
02/08/2021	This Material is unchanged as of this date.
08/09/2021	This Material is unchanged as of this date.
02/16/2022	This Material is unchanged as of this date.

---

End Of Report, Total Of 39 Pages

---

BUESD MAINTENANCE AND TRANSPORTATION YARD  
 INSPECTED ON: 02-16-2022



EXPLANATION	
	STORM DRAIN
SW-1	MONITORING POINT
	SURFACE WATER FLOW
	STORM WATER CONVEYANCE SYSTEM

NOT TO SCALE




DATE JUN 1997  
 DWN KAJ  
 APP \_\_\_\_\_  
 REV \_\_\_\_\_  
 PROJECT NO.  
 2136-001.001

**FIGURE 2**  
 BERRYESSA UNION SCHOOL DISTRICT  
 945 PIEDMONT ROAD  
 SAN JOSE, CALIFORNIA  
 CORPORATION YARD  
 SITE PLAN

EA-SANJOSE-040 DRAWINGS: 2136011 SITE PLAN (revised) DATE: 5/25/97 Operator: AU  
 Scale: 1" = 100'

BUESD MAINTENANCE AND TRANSPORTATION YARD  
INSPECTED ON:

8/9/21



EXPLANATION	
	STORM DRAIN
SW-1	MONITORING POINT
	SURFACE WATER FLOW
	STORM WATER CONVEYANCE SYSTEM

NOT TO SCALE




DATE JUN. 1997  
 DWN KAJ  
 APP \_\_\_\_\_  
 REV \_\_\_\_\_  
 PROJECT NO.  
 2136-001.001

**FIGURE 2**  
 BERRYESSA UNION SCHOOL DISTRICT  
 945 PIEDMONT ROAD  
 SAN JOSE, CALIFORNIA  
 CORPORATION YARD  
 SITE PLAN

EA-SANJOSE-CAD DRAWINGS, P. 2136011, SITE PLAN (revised) (NONE)  
 Date: 8/26/97 Time: 0:12 AM Operator: AU  
 Scale: 1" = 100'

BUESD MAINTENANCE AND TRANSPORTATION YARD  
 INSPECTED ON: 2/8/21



EXPLANATION	
	STORM DRAIN
SW-1	MONITORING POINT
	SURFACE WATER FLOW
	STORM WATER CONVEYANCE SYSTEM

NOT TO SCALE


EA-SANJOSE-CAD DRAWINGS: 2136011-SUBSITE.dwg Xrefs: <NONE>  
 Date: 8/25/97 Time: 8:12 AM Operator: AU  
 Scale: 1" = 100'



DATE JUN. 1997  
 DWN KAJ  
 APP \_\_\_\_\_  
 REV \_\_\_\_\_  
 PROJECT NO.  
 2136-001.001

**FIGURE 2**  
 BERRYESSA UNION SCHOOL DISTRICT  
 945 PIEDMONT ROAD  
 SAN JOSE, CALIFORNIA  
 CORPORATION YARD  
 SITE PLAN

BUESD MAINTENANCE AND TRANSPORTATION YARD  
 INSPECTED ON: 8/26/20



EXPLANATION	
	STORM DRAIN
SW-1	MONITORING POINT
	SURFACE WATER FLOW
	STORM WATER CONVEYANCE SYSTEM

NOT TO SCALE




DATE JUN. 1997  
 DWN KAJ  
 APP \_\_\_\_\_  
 REV \_\_\_\_\_  
 PROJECT NO. 2136-001.001

**FIGURE 2**  
 BERRYESSA UNION SCHOOL DISTRICT  
 945 PIEDMONT ROAD  
 SAN JOSE, CALIFORNIA  
 CORPORATION YARD  
 SITE PLAN

EA-SANJOSE-CAD. DRAWINGS. 213601. SUBSITE. VEG. YRHS. 4/20/97. DATE 8/25/97. TIME 01:2 AM. OPERATOR: AU  
 Scale: 1" = 100' Contour: 4' 0.00' Contour: 4' 0.00'



BUESD MAINTENANCE AND TRANSPORTATION YARD  
 INSPECTED ON: 1-30-2020



EXPLANATION	
	STORM DRAIN
SW-1	MONITORING POINT
	SURFACE WATER FLOW
	STORM WATER CONVEYANCE SYSTEM

NOT TO SCALE




**EMCON**

DATE JUN. 1997  
 DWN KAJ  
 APP \_\_\_\_\_  
 REV \_\_\_\_\_  
 PROJECT NO.  
 2136-001.001

**FIGURE 2**  
 BERRYESSA UNION SCHOOL DISTRICT  
 945 PIEDMONT ROAD  
 SAN JOSE, CALIFORNIA  
 CORPORATION YARD  
 SITE PLAN


EA-SANJOSE-CAD DRAWINGS: 213601 SITE SWD (cels: CINCNE)  
 Date: 2/25/97 "me: C:12 AV Operator: AU  
 Scale: 1" = 100' Contour: 1"

BUESD MAINTENANCE AND TRANSPORTATION YARD  
 INSPECTED ON: 8/12/19



EXPLANATION	
	STORM DRAIN
SW-1	MONITORING POINT
	SURFACE WATER FLOW
	STORM WATER CONVEYANCE SYSTEM

NOT TO SCALE




DATE	JUN. 1997
OWN	KAJ
APP	
REV	
PROJECT NO.	2136-001.001

**FIGURE 2**  
 BERRYESSA UNION SCHOOL DISTRICT  
 945 PIEDMONT ROAD  
 SAN JOSE, CALIFORNIA  
 CORPORATION YARD  
 SITE PLAN


EA-SANJOSE-CAD. DRAWINGS. 2136011.SITE.dwg (ref: <NONE>  
 Scale: 1" = 100' Date: 8/25/97 "met: 0:12 AM Creator: "AJ

BUESD MAINTENANCE AND TRANSPORTATION YARD  
INSPECTED ON: 02-04-2019



EXPLANATION	
	STORM DRAIN
SW-1	MONITORING POINT
	SURFACE WATER FLOW
	STORM WATER CONVEYANCE SYSTEM

NOT TO SCALE




DATE JUN. 1997  
DWN KAJ  
APP \_\_\_\_\_  
REV \_\_\_\_\_  
PROJECT NO. 2136-001.001

**FIGURE 2**  
BERRYESSA UNION SCHOOL DISTRICT  
945 PIEDMONT ROAD  
SAN JOSE, CALIFORNIA  
CORPORATION YARD  
SITE PLAN


EA-SANJOSE-CAD. DRAWINGS. : 213601.SJ SITE.dwg Xrefs: <NONE>  
Scale: 1" = 100' Date: 5/25/97 Time: 01:12 AM Operator: AU

BUESD MAINTENANCE AND TRANSPORTATION YARD  
 INSPECTED ON: 8/6/18



EXPLANATION	
	STORM DRAIN
	MONITORING POINT
	SURFACE WATER FLOW
	STORM WATER CONVEYANCE SYSTEM

NOT TO SCALE




DATE JUN. 1997  
 DWN KAJ  
 APP \_\_\_\_\_  
 REV \_\_\_\_\_  
 PROJECT NO. 2136-001.001

**FIGURE 2**  
 BERRYESSA UNION SCHOOL DISTRICT  
 945 PIEDMONT ROAD  
 SAN JOSE, CALIFORNIA  
 CORPORATION YARD  
 SITE PLAN


EA-SANJOSE-CAD DRAWINGS: 2136011 SITE.dwg Xrefs: KNGNE Date: 6/26/97 Plot: 0:12 AM Operator: wju

BUESD MAINTENANCE AND TRANSPORTATION YARD  
 INSPECTED ON: 2/12/18



EXPLANATION	
	STORM DRAIN
SW-1	MONITORING POINT
	SURFACE WATER FLOW
	STORM WATER CONVEYANCE SYSTEM

NOT TO SCALE




DATE JUN. 1997  
 DWN KAJ  
 APP \_\_\_\_\_  
 REV \_\_\_\_\_  
 PROJECT NO.  
 2136-001.001

**FIGURE 2**  
 BERRYESSA UNION SCHOOL DISTRICT  
 945 PIEDMONT ROAD  
 SAN JOSE, CALIFORNIA  
 CORPORATION YARD  
 SITE PLAN

EA-SANJOSE-CAD. DRAWINGS. 2:156011 SITE PLAN. Xrefs: 4:NOVE2  
 Scale: 1" = 100' Date: 5/25/97 "met" C:1:2 AV Operator: AU

BUESD MAINTENANCE AND TRANSPORTATION YARD  
INSPECTED ON:


8/25/17



EXPLANATION	
	STORM DRAIN
SW-1	MONITORING POINT
	SURFACE WATER FLOW
	STORM WATER CONVEYANCE SYSTEM

NOT TO SCALE


EA-SANJOSE-CAD. DRAWINGS: 213601.SJ SITE.dwg \refs: <NGNE>  
 Date: 5/25/97 Time: 1:00 User: kja  
 Date: 5/25/97 Time: 1:00 User: kja



DATE JUN. 1997  
 DWN KAJ  
 APP \_\_\_\_\_  
 REV \_\_\_\_\_  
 PROJECT NO.  
 2136-001.001

**FIGURE 2**  
**BERRYESSA UNION SCHOOL DISTRICT**  
**945 PIEDMONT ROAD**  
**SAN JOSE, CALIFORNIA**  
**CORPORATION YARD**  
**SITE PLAN**

BUESD MAINTENANCE AND TRANSPORTATION YARD  
 INSPECTED ON: 3/27/17



EXPLANATION	
	STORM DRAIN
SW-1	MONITORING POINT
	SURFACE WATER FLOW
	STORM WATER CONVEYANCE SYSTEM

NOT TO SCALE




DATE JUN. 1997  
 DWN KAJ  
 APP \_\_\_\_\_  
 REV \_\_\_\_\_  
 PROJECT NO.  
 2136-001.001

**FIGURE 2**  
 BERRYESSA UNION SCHOOL DISTRICT  
 945 PIEDMONT ROAD  
 SAN JOSE, CALIFORNIA  
 CORPORATION YARD  
 SITE PLAN

EA-SANJOSE-CAD. DRAWINGS. 213601 SITE DWG. Xrefs: CNDNEZ  
 Date: 5/26/97 File: 1:00 1:00 1:00 Operator: AU


BUESD MAINTENANCE AND TRANSPORTATION YARD  
 INSPECTED ON: 7-9-16



EXPLANATION	
	STORM DRAIN
SW-1	MONITORING POINT
	SURFACE WATER FLOW
	STORM WATER CONVEYANCE SYSTEM

NOT TO SCALE

EA-SANJOSE-CAD. DRAWINGS. 2:1601:SUBSITE.dwg Xrefs: <NONE>  
 Scale: 1" = 100' Date: 5/25/97 Operator: AU




DATE JUN. 1997  
 DWN KAJ  
 APP \_\_\_\_\_  
 REV \_\_\_\_\_  
 PROJECT NO.  
 2136-001.001

**FIGURE 2**  
 BERRYESSA UNION SCHOOL DISTRICT  
 945 PIEDMONT ROAD  
 SAN JOSE, CALIFORNIA  
**CORPORATION YARD  
 SITE PLAN**




BUESD MAINTENANCE AND TRANSPORTATION YARD  
INSPECTED ON:

3-17-16 *1990*



EXPLANATION	
	STORM DRAIN
	MONITORING POINT
	SURFACE WATER FLOW
	STORM WATER CONVEYANCE SYSTEM

NOT TO SCALE



DATE JUN. 1997  
DWN KAJ  
APP \_\_\_\_\_  
REV \_\_\_\_\_  
PROJECT NO. 2136-001.001

**FIGURE 2**  
BERRYESSA UNION SCHOOL DISTRICT  
945 PIEDMONT ROAD  
SAN JOSE, CALIFORNIA  
CORPORATION YARD  
SITE PLAN

EA-SANJOSE-CAD DRAWINGS: 2136011 SITE PLAN (revised) DATE: 6/12/97 Operator: AJ  
Scale: 1" = 100' Date: 6/25/97

Plumbing  
Locksmith

Garage

PORTABLE

GT  
porta

Carpenter shop, Warehouse,  
Grounds Supply

Towers

Main Office

BUESD MAINTENANCE AND TRANSPORATION YARD  
INSPECTED ON:

2/15/16

Grounds  
Tools  
Mower

Welding Shop

BERRYESSA UNION SCHOOL DISTRICT  
Maintenance Yard  
945 Piedmont Road  
San Jose, CA 95132

Plumbing  
Locksmith

Garage

PORTABLE

GT  
porta

Carpenter shop, Warehouse,  
Grounds Supply

Towers

Main Office

BUESD MAINTENANCE AND TRANSPORATION YARD  
INSPECTED ON: 3/18/15

Grounds  
Tools  
Mower

Welding Shop

BERRYESSA UNION SCHOOL DISTRICT  
Maintenance Yard  
945 Piedmont Road  
San Jose, CA 95132

Plumbing  
Locksmith

Garage

PORTABLE

GT  
porta

Carpenter shop, Warehouse,  
Grounds Supply

Towers

Main Office

BUESD MAINTENANCE AND TRANSPORATION YARD  
INSPECTED ON:

8-28-14

Grounds  
Tools  
Mower

Welding Shop

BERRYESSA UNION SCHOOL DISTRICT  
Maintenance Yard  
945 Piedmont Road  
San Jose, CA 95132

Plumbing  
Locksmith

Garage

PORTABLE

GT  
porta

Carpenter shop, Warehouse,  
Grounds Supply

Towers

Main Office

BUESD MAINTENANCE AND TRANSPORATION YARD  
INSPECTED ON: 3-3-14

Grounds  
Tools  
Mower

Welding Shop

BERRYESSA UNION SCHOOL DISTRICT  
Maintenance Yard  
945 Piedmont Road  
San Jose, CA 95132

Plumbing  
Locksmith

Garage

PORTABLE

GT  
porta

Carpenter shop, Warehouse,  
Grounds Supply

Towers

Main Office

BUESD MAINTENANCE AND TRANSPORATION YARD  
INSPECTED ON: 09-23-2013

Grounds  
Tools  
Mower

Welding Shop

BERRYESSA UNION SCHOOL DISTRICT  
Maintenance Yard  
945 Piedmont Road  
San Jose, CA 95132

Plumbing  
Locksmith

Garage

PORTABLE

GT  
porta

Carpenter shop, Warehouse,  
Grounds Supply

Towers

Main Office

BUESD MAINTENANCE AND TRANSPORATION YARD  
INSPECTED ON:

04-01-13

Grounds  
Tools  
Mower

Welding Shop

BERRYESSA UNION SCHOOL DISTRICT  
Maintenance Yard  
945 Piedmont Road  
San Jose, CA 95132

Plumbing  
Locksmith

Garage

PORTABLE

GT  
porta

Carpenter shop, Warehouse,  
Grounds Supply

Towers

Main Office

BUESD MAINTENANCE AND TRANSPORATION YARD  
INSPECTED ON: 10-8-12

Grounds  
Tools  
Mower

Welding Shop

BERRYESSA UNION SCHOOL DISTRICT  
Maintenance Yard  
945 Piedmont Road  
San Jose, CA 95132



Plumbing  
Locksmith

Garage

PORTABLE

GT  
porta

Carpenter shop, Warehouse,  
Grounds Supply

Towers

Main Office

BUESD MAINTENANCE AND TRANSPORATION YARD  
INSPECTED ON: *04-13-12*

Grounds  
Tools  
Mower

Welding Shop

BERRYESSA UNION SCHOOL DISTRICT  
Maintenance Yard  
945 Piedmont Road  
San Jose, CA 95132

Main Office

Plumbing  
Locksmith

Garage

BUESD MAINTENANCE AND TRANSPORATION YARD  
INSPECTED ON: 11-29-11

Use Desk

GT

GT

GT  
porta

4 M&S  
Storage

Carpenter shop, Warehouse,  
Grounds Supply

M&S

Towers

Grounds  
Tools  
Mower

Welding Shop  
Sine Tool /  
port

BERRYESSA UNION SCHOOL DISTRICT  
Maintenance Yard  
945 Piedmont Road  
San Jose, CA 95132

Plumbing  
Locksmith

Garage

Main Office

BUESD MAINTENANCE AND TRANSPORATION YARD  
INSPECTED ON:

7/30/10

GT  
porta

Carpenter shop, Warehouse,  
Grounds Supply

Towers

Grounds  
Tools  
Mower

Welding Shop

BERRYESA UNION SCHOOL DISTRICT  
Maintenance Yard  
945 Piedmont Road  
San Jose, CA 95132

Plumbing  
Locksmith

Garage

GT  
porta

Carpenter shop, Warehouse,  
Grounds Supply

Towers

Main Office

BUESD MAINTENANCE AND TRANSPORATION YARD  
INSPECTED ON: 03-08-10

Grounds  
Tools  
Mower

Welding Shop

BERRYESSA UNION SCHOOL DISTRICT  
Maintenance Yard  
945 Piedmont Road  
San Jose, CA 95132

Plumbing  
Locksmith

Garage

*metal's storage*

*metal garage*



GT  
porta

Carpenter shop, Warehouse,  
Grounds Supply

*metal storage*

Towers

*metal garage*

Main Office

BUESD MAINTENANCE AND TRANSPORATION YARD  
INSPECTED ON: *09-03-09*

Grounds  
Tools  
Mower

Welding Shop

BERRYESSA UNION SCHOOL DISTRICT  
Maintenance Yard  
945 Piedmont Road  
San Jose, CA 95132

Plumbing  
Locksmith

Garage

GT  
porta

Carpenter shop, Warehouse,  
Grounds Supply

Towers

Main Office

BUESD MAINTENANCE AND TRANSPORATION YARD

INSPECTED ON: 05-11-09  
09-09-8 RBZ

Grounds  
Tools  
Mower

Welding Shop

BERRYESSA UNION SCHOOL DISTRICT  
Maintenance Yard  
945 Piedmont Road  
San Jose, CA 95132

5-12-82  
15/18/81  
1669

Plumbing  
Locksmith

Garage

GT  
porta

Carpenter shop, Warehouse,  
Grounds Supply

Towers

Main Office

BUESD MAINTENANCE AND TRANSPORATION YARD  
INSPECTED ON: 10/13/08

Grounds  
Tools  
Mower

Welding Shop

BERRYESSA UNION SCHOOL DISTRICT  
Maintenance Yard  
945 Piedmont Road  
San Jose, CA 95132

Plumbing  
Locksmith

Garage

GT  
porta

Carpenter shop, Warehouse,  
Grounds Supply

Towers

Main Office

BUESD MAINTENANCE AND TRANSPORATION YARD  
INSPECTED ON: 04-14-08

Grounds  
Tools  
Mower

Welding Shop

BERRYESSA UNION SCHOOL DISTRICT  
Maintenance Yard  
945 Piedmont Road  
San Jose, CA 95132



Plumbing  
Locksmith

Garage

GT  
porta

Carpenter shop, Warehouse,  
Grounds Supply

Towers

Main Office

BUESD MAINTENANCE AND TRANSPORATION YARD  
INSPECTED ON: *NOV. 5, 07*

Grounds  
Tools  
Mower

Welding Shop

BERRYESSA UNION SCHOOL DISTRICT  
Maintenance Yard  
945 Piedmont Road  
San Jose, CA 95132